

Date : 01/06/2020

INSPECTION CANCELLED OR DECLINE				(blue font - new entry since last weekly update)
No	Port	OM	Date	Remark
1	Adelaide, Australia	Koch, Shell	March	Inspection not allowed by Terminal due to COVID – 19
2	A Corunna, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
3	A.D.Reis, Brazil	EQUINOR	05-Jan	Declined due to travel restrictions
4	A.D.Reis, Brazil	TOTAL	05-Apr	Declined due to unavailability of inspectors
5	Abidjan, Ivory Coast	CDI	15-Mar	Local inspector unavailable. (Covid-19 related)
6	Adabiyah, Egypt	Statoil	22-Apr	No flights into Egypt, Statoil cancelled request
7	Adabiyah, Egypt	CDI	25-May	Rejected for business based on SIRE more than 6 months old / no physical SIRE could be completed prior to last SIRE expiring 6mths/12mths.
8	Adelaide, Australia	Shell, BP, Idemitsu, Viva	April	Inspection not allowed as interstate travel is restricted due to Covid 19
9	Ain Sukhna Sonkar Terminal, Egypt	Shell	20-May	Others – Unable to carry out the inspection at this time, do not cover this Country.
10	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
11	Ain Sukhna, Egypt	Lukoil, Adnoc, Maxcom	03-May	Covid 19 - travel restrictions
12	Ain Sukhna, Egypt	ENOC	02-May	Covid 19 - travel restrictions
13	Ain Sukhna, Egypt	P66	04-May	Covid 19 - travel restrictions
14	Ain Sukhna, Egypt	MOH	04-May	Covid 19 - travel restrictions
15	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
16	Alcudia, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
17	Alexandria, Egypt	Enoc	18-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

18	Alexandria, Egypt	Koch	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
19	Alexandria, Egypt	Maxcom	23-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
20	Aliaga, Turkey			Imposed restrictions
21	Aliaga, turkey	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
22	Aliaga, Turkey	All Majors/CDI	15-May	Inspections not permitted to be carried out due to COVID-19. Local inspector was appointed, however he was denied entry to the terminal for the purpose of inspection.
23	All ports in India	All Majors	03-Apr	Locked down till 14-Apr, no inspections can be scheduled
24	Altamira, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
25	Altamira, Mexico			Do not allow inspectors onboard.
26	Altamira, Mexico	Maxcom	27-Mar	All arranged, port closed over night for non-locals, even as inspector was Mexican
27	Altamira, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
28	Altamira, Mexico	Maxcom	08-May	Covid 19 - travel restrictions
29	Altamira, Mexico	ALMA	07-May	Covid 19 - travel restrictions
30	Altamira, Mexico	ENOC	07-May	Covid 19 - travel restrictions
31	Amsterdam, Netherland	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
32	Amsterdam, Netherland	P66	Apr	No inspector available
33	Amsterdam, Netherlands	Neste	18-May	At this moment Neste does not carry out any sire inspections.
34	Antifer, France	BP	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
35	Antwerp, Belgium	Gazprom	06-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. From agent: We received terminal ATPC instructions from that due COVID nobody is allowed on the terminal anymore till further notice
36	Arzew, Algeria		07-Apr	Not allowed due to COVID-19 restrictions
37	Ashklelon, Isreal	Gazprom	04-Mar	Last minute cancellation as inspector's were not allowed to enter Israel if previously travelled to high risk COVID19 countries in Europe
38	Aughinish, Ireland	P66	25-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
39	Aughinish, Ireland	Koch, VIVO	25-Apr	Local inspector unavailable. (Covid-19 related)

40	Augusta, Sicily	BHP	29-May	The Sicily region have still travel limitation until at least the 7th June. Not residents in Sicily cannot travel to Augusta. In view of restriction, we will decline the inspection invitation.
41	Aviero, Portugal	CDI	28-Mar	Terminal requirements not to allow any inspections due to COVID-19
42	Bahia Blanca, Argentina	KOCH, Idemitsu	31-Mar	Local inspector unavailable. KOCH and Idemitsu were not able to find available inspectors due to COVID
43	Banática, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
44	Bangkok & Maptaphut, Thailand	PTT	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
45	Banjul, SK	Maxcom	16-Apr	Covid 19 - travel restrictions
46	Banjul, SK	Maxcom	15-Apr	Covid 19 - travel restrictions
47	Banjul, SK	Total, ENOC, Maxcom	14-Apr	Covid 19 - travel restrictions
48	Banjul, SK	BHP	14-Apr	Covid 19 - travel restrictions
49	Banjul, SK	Aethon/Koch	14-Apr	Covid 19 - travel restrictions
50	Barcelona, Spain	Cepsa	01-Jun	Declined on 20 May 2020 due to COVID-19 travel restrictions
51	Barranquilla, Colombia	BEICO	10-Apr	Port does not allow till further notice.
52	Basamuk, PNG			
53	Bataan, Philiphine	PETRON	18-May	Regret to inform you that visiting inspector is not allowed as of the moment due to COVID-19 and we are still on community quarantine until May 30.
54	Beaumont, USA	Exxon/IMT	05-Apr	
55	Beira, Mozambique	ENOC	20-May	Covid 19 - travel restrictions
56	Beira, Mozambique	P66	27-Apr	Local inspector unavailable. (Covid-19 related)
57	Beira, Mozambique	Lukoil	27-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
58	Belem, Barzil	Petrobras	10-Apr	Petrobras are not carrying out inspections worldwide due to COVID-19
59	Belize	EQUINOR	19-May	Covid 19 - travel restrictions
60	Benicia, CA, USA	Phillips66	07-Apr	Terminal not allowed
61	Bilbao, Brazil			Imposed restrictions

62	Bilbao, Spain	PETRONOR	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
63	Bintulu OPL, Malaysia	Petronas	20-Apr	During Movement Control Order period, all personal enter Sarawak have to be complete compulsory quarantine for 14 days at hotel / hospital arrange by local government. After complete compulsory quarantine 14 days, auditor to need pass Port health screening before permitted to board vessel at anchorage. As per the above and also travel restrictions and safety of the inspector; we regret to inform cannot cover the inspection.
64	Bintulu, Malaysia	MMS	27-May	Due to COVID-19 and movement restriction, inspector need to be quarantine at Sarawak for 14 days before the inspection.
65	Bonny, Nigeria	Petron	16-May	Terminal change policy – visitor/inspector need 14 days quarantine due to Covid-19.
66	Bontang , Indonesia	Idemitsu	17-Apr	No available local inspectors; travelling restrictions
67	Bordeaux, France	EQUINOR	17-May	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available for the given port/date to cover this request at the moment.
68	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
69	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
70	Botany Bay,	VIVA	15-Apr	Local inspector unavailable.
71	Botany Bay, Australia	Ampol	02-Apr	Due to situation of Coronavirus outbreak, OM are unable to process the inspection request.
72	Botany Bay, Australia	BP, Total, IMT, Lukoil, Ampol and Shell	10-Apr	Shell eventually took the inspection but finally terminal did not allow.
73	Botany Bay, Australia	BP	02-Apr	Travel restriction imposed in th country due to COVID 19
74	Bourgas, Bulgaria	SHELL	09-Apr	Local inspector unavailable.
75	Bourgas, Bulgaria	BP	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

76	Burgas, Bulgaria	Chevron	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
77	Brisbane, Australia		03-Apr	Allowed- boarding of inspectors only 3hours after berthing. Check with agents.
78	Brunei	Gazprom, idemitsu, Equinor, Maxcom	04-Apr	other - complete lockdown due to COVID19
79	Brunei	All Majors/CDI	29-May	Information: Inspections not permitted in Brunei due to COVID-19 pandemic. All foreigners arriving Brunei need to serve 14 days quarantine period.
80	Burgas, Bulgaria	All Majors/CDI	01-May	Bulgaria is locked down due to COVID-19
81	Busan, SK		05-May	Not possible due to COVID 19 restrictions
82	Busan, SK		05-May	Not possible due to COVID 19 restrictions
83	Cabo Negro, Chile	CDI	16-May	Other - Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
84	Cabo Negro, Chile	CDI	16-May	Local inspector unavailable. (Covid-19 related)
85	Cabo Negro, Morocco	CDI	16-May	Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
86	Cabo Negro, Morocco	CDI	16-May	Local inspector unavailable. (Covid-19 related)
87	Caldera, Chile	Marathon	22-Apr	Terminal restriction
88	Callao, Peru	ConocoPhillips	23-Apr	ConocoPhillips declined request due to Covid
89	Callao, Peru	CDI	08-May	Local inspector unavailable. (Covid-19 related)
90	Canaport, Canada	Chevron	17-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
91	Canaport, Canada	Equinor	15-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
92	Canaport, Canada			Terminal quarantines vessel if inspector boards prior berthing. Not permitted during discharge. Vessel must be at sea for >14 days prior berthing. Post discharge you are allowed everything at the anchorage.
93	Caoeger Bay, South Africa	ENOC, Equinor	05-May	Local inspector unavailable. (Covid-19 related)
94	Caofeidian, PRC	Enoc, Total, Shell, P66, Bioco, Koch, BHP, IMT, Chevron	Feb	Inspection not allowed by Terminal due to COVID – 19
95	Cartagena, Colombia	Chevron	19-May	Inspector unavailability
96	Cartagena, Spain			Terminal not allowed or non-availability of any local inspector due COVID – 19
97	Cartagena, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be

				evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
98	Cartagena, Spain	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
99	Castellon, Spain	Enoc	March	Inspection not allowed by Terminal due to COVID – 19
100	Castellon, Spain	Equinor	21-Mar	Terminal change policy - no visitor/inspector allowed due to Covid-19
101	Ceuta, Spain	Lukoil,Cepsa, OMV, Total. Maxcom, POT, Repsol, P66, Enoc	16-Apr	No local Inspectors and Covid-19 travel restrictions
102	Ceyhan, Turkey	ENOC	08-May	ENOC are unable to attend the vessel.
103	Ceyhan, Turkey		22-Apr	Checked with Agents - Complete lockdown No Vetting inspections allowed
104	Chang Xing, PRC	All OM	06-May	Terminal restriction
105	Changzhou Huarun, PRC		13-May	As per agents - not allowed
106	Chennai, India	Chevron	04-Apr	other - complete lockdown due to COVID19
107	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
108	Chiba, Japan		22-Apr	Not allowed due to COVID-19 restrictions
109	Chiriqui Grande, Panama		16-Apr	Not possible due to COVID-19 restrictions
110	Chiriqui Grande, Panama	P66. Equinor	30-Apr	Not possible due to COVID 19 travel restrictions. No local inspector.
111	Chittagong	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
112	Chittagong, Bangladesh	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
113	Chittagong, Bangladesh	BP	Apr	Terminal not allowing to board BP vetting inspector due to restriction.
114	Ciudad Madero, Mexico	Equinor	20-Apr	Due to the COVID-19 travel restrictions (Lock Down)
115	Coassa, Panama	All	10-May	Terminal under security level 2 – no visitor/inspector allowed due to Covid-19.
116	Coatzacoalcos, Mexico	EQUINOR	06-Apr	Covid 19 - travel restrictions
117	Coazacoalcos, Mexico			All ports east of Mexico. Do not allow inspectors onboard.

118	Coazacoalcos, Mexico			Do not allow inspectors onboard.
119	Coega Bay, South Africa	Equinor	15-May	Local inspector unavailable. (Covid-19 related)
120	Conarky, Guinea	Lukoil, Alma	29-Mar	
121	Concepcion Bay, Chile	CHEVRON	10-Apr	Not able to attend due the new restriction during easter holidays, travel problems due to COVID19. At this time the inspection is now cancelled.
122	Concepcion Bay, Chile	CHEVRON	11-Apr	Regret we will not be able to attend this one due the new restriction during easter holidays, travel problems due to COVID19. Thank you very much for your help, at this time the inspection is now cancelled.
123	Conchan, Peru	CHEVRON	17-Mar	Peruvian Government has restricted citizens' movement within their homes and closed international travel with effect from 16 March to 1 April.
124	Conchan, Peru	REPSOL	18-Mar	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
125	Corpus Christi, USA	Koch	15-May	Covid 19 - travel restrictions
126	Corpus Christi, USA	Equinor	25-May	Personal issues with the inspector
127	Coruna, Spain	Cepsa	29-Apr	Only at their terminals at Huelva, Tenerife and Algeciras
128	Cotonou, Benin	CDI	17-Mar	Local inspector unavailable. (Covid-19 related)
129	Cotonou, Benin	CDI	21-Mar	Local inspector unavailable. (Covid-19 related)
130	Cotonou, Republic of Benin	Agent	07-May	Covid 19 - travel restrictions
131	Covenas, Columbia		16-Apr	Not possible due to COVID-19 restrictions
132	Covenas, Columbia	ENOC	18-Apr	Permission not granted by terminal due to COVID-19 restrictions
133	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice
134	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
135	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
136	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice. Exception is if the inspector is a local, however permission is required.

137	Cristobal, Panama		27-Mar	Travel restriction
138	Daesan, SK	TOTAL	05-Apr	Declined due to unavailability of inspectors
139	Daesan, SK	Total	31-May	Terminal prohibited any job other than cargo operation at berth. The same was explained you earlier and we have arranged his on / off schedule at the anchorage. However, the vessel's ETB delayed several hours again today as the terminal changed our vessel's jetty. And the inspector suddenly informed that he should cancel the inspection.
140	Daesan, SK			Not permitted by terminal
141	Daesan, SK	ENOC	12-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
142	Daesan, SK	IMT & BP	14-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
143	Dahej, India		01-May	Agents information due to terminal restrictions and lock-down
144	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
145	Dakar, Senegal	Maxcom	14-Apr	Covid 19 - travel restrictions
146	Dakar, Senegal	ENOC, BHP, agents	13-Apr	Covid 19 - travel restrictions
147	Dakar, Senegal	Koch, Aethon, Total	13-Apr	Covid 19 - travel restrictions
148	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
149	Dalian, PRC			
150	Dalian, PRC		13-May	As per agents - not allowed
151	Dalian, PRC	Shell, Chevron	27-May	Terminal restrictions; local inspectors only
152	Dapeng, PRC	MMS	07-May	Visitor enter terminal must stay in this city "Shenzhen" longer than 14 days; Visitor should need Nucleic acid test of COVID-19 3 days before ship arrival, then we can make the application; Terminal will consider to approve or not base on Customs' quarantine pre examination on the vessel about 2-3 days before ship arrival(base on vessel's port calls records, crews conditions etc.
153	Dominican Republic	P66	13-Apr	Due to the COVID-19 travel restrictions
154	Dominican Republic	Lukoil	13-Apr	Due to Dominican Republic is locked down
155	Donges, France	Enoc	23-May	OM - Regret due to COVID 19 we cannot attend this vessel.
156	Donges, France	P66	23-May	Unfortunately due to COVID 19, there are travel or terminal restrictions in the location you requested this inspection to be conducted in
157	Dongguan, PRC	any OM	03-Apr	Covid 19 - country lock down

158	Dongguan, PRC	BHP	18-Apr	Dongguan Immigration is not allowed the SIRE inspector to visit ship for this calling due to Dongguan got two confirmed COVID-19 cases in last week which from foreign ships.
159	Dongguan, PRC	BHP	22-Apr	We do not have available inspectors at the moment due to various virus restrictions and will decline inspections.
160	Dongguan, PRC	Shell	19-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
161	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Insepction at the moment yet.
162	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Insepction at the moment yet.
163	Dongguan, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
164	Dongjiakou, {PRC	BHP	25-May	Covid 19 - travel restrictions
165	Dongjiakou, PRC			
166	Dongjiakou, PRC	Maxcom	07-Apr	Terminal is closed as per covid 19 restrictions
167	Dongjiakou, PRC	MAXCOM	07-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
168	Dongjiakou, PRC	Chevron	10-Apr	Plan 17/04/2020 - Chevron do not schedule SIRE inspection at China port at the moment.
169	Dongjiakou, PRC	Shell	10-Apr	Plan 17/04/2020 - Rejected due to COVID-19
170	Dongying, PRC	EQUINOR	20-May	Covid 19 - travel restrictions
171	Dongying, PRC	BHP	21-May	Covid 19 - travel restrictions
172	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
173	Dongying, PRC	ENOC	23-May	Covid 19 - travel restrictions
174	Dongying, PRC	Maxcom	21-May	Covid 19 - travel restrictions
175	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
176	Douala, Cameroon			Terminal not allowed or non-availability of any local inspector due COVID – 19
177	Durban, South Africa	Shell	26-Mar	
178	Durban, South Africa	Shell	24-Mar	Covid 19 - country lock down
179	Durban, South Africa	Shell	26-Mar	Covid 19 - country lock down
180	El Segundo, California, USA		22-Apr	no visitor/inspector allowed due to Covid-19
181	El Segundo, USWC	Chevron, P66	21-May	Terminal change policy – visitor/inspector allowed due to Covid-19.
182	El Segundo, USWC	Chevron		Terminal does not permit
183	El Segundo, USWC	P66	09-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19. (Terminal belong to Chevron and operator requested them to inspect - tbc)
184	Ennore, India	Shell	04-Jun	Planned: Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections in India until further notice.
185	Ennore, India	ENOC	05-May	Terminal rejection of the inspector

186	Fawley, UK	EXXON	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
187	Fawley, UK			
188	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March:Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
189	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March:Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
190	Fawley, UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
191	Fawley,UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
192	Fos, France			Member reported info from agent, now possible to do inspection
193	Fos, France	TOTAL & OMV	23-May	Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling. We have just received the answer from the last Inspector, unfortunately, he is not available. In view of the above, we are force to postpone the inspection.
194	Freeport , USA	P66	25-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
195	Freeport ,USA	P66	25-Apr	Planned - Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
196	Freeport, Bahamas		10-Apr	Due to Lockdown
197	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
198	Fujairah, UAE	SHELL	22-Apr	Due to launch required for boarding
199	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

200	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
201	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
202	Galveston Offshore lightering area	Chevron	24-Apr	Unavailability of inspector for this inspection
203	Ganyu, PRC	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
204	Gdansk, Poland	ENOC, KOCH	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
205	Geismar, USA	Conocophillips	27-Mar	OM advised they have cancelled due to COVID 19
206	Geismar, USA	Equinor	27-Mar	Equinor did not have inspector due to COVID 19
207	Gemlik, Turkey	CDI	09-Apr	Local inspector unavailable.
208	Geoje, SK		01-Jun	Not allowed by terminal
209	Ghent, Belgium	Neste	14-Apr	Due to corona restrictions within the Company
210	Gijón, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
211	Goeje Yard, SK	PETROBRAS	21-May	Planned: Due to the outbreak of the COVID-19, currently we are not performing SIRE inspections in any port of the world
212	Guam, USA	BP,CHEVRON,P66,GA ZPROM	10-Apr	Travel restrictions 14 days quarantine resulted to no inspectors available
213	Guam/Saipan, USA			Terminal not allowed or non-availability of any local inspector due COVID – 19
214	Guayanilla, Puerto Rico		16-Apr	Not possible due to COVID-19 restrictions
215	Guaynilla, Puerto Rico		20-May	Not possible as no local inspector and no flights operating to the island
216	Gulei, PRC		22-Mar	Due to COVID-19 not permitted by terminal
217	Gulei, PRC	Maxcom	09-May	Terminal restricions
218	Gulei, PRC	ENOC	16-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
219	Hadera, Israel	Repsol	22-May	"Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception"
220	Hadera, Israel	Rightship, Total	22-May	Local inspector unavailable. (Covid-19 related)

221	Haldia, India		Apr	Terminal informed they wil not allow vetting inspector to board due to restriction. India under lockdown.
222	Haldia, India	Idemitsu	04-May	India Lock down.
223	Haldia, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
224	Hamriyah, UAE	P66	Apr	Terminal did not allow BP vetting inspector to board due to COVID 19 restriction
225	Hazira, India	Rightship	01-Apr	country under lockdown - travelling prohibited within country
226	Hong Kong, PRC			
227	Honninggsvag, Norway	BP	03-Apr	Due the COVID-19 there is borders restriction to any non-residents (except for transit passengers).
228	Honninggsvag, Norway			
229	Honolulu, USA	SHELL	25-May	Travel restriction imposed in th country due to COVID 19.
230	Houston, USA	Equinor	Mar	Master has raised concerns about safety & health of the crew and has requested for deferring the inspection so as to avoiding/limit contact with visitors to the bare minimum. Tech. Manager agreed and postponed inspection.
231	Houston, USA	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
232	Houston, USA	Repsol	13-Apr	
233	Houston, USA	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
234	Houston, USA	Repsol	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

235	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-22
236	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-24
237	Huelva, Spain			Imposed restrictions
238	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
239	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected, Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
240	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
241	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected. Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
242	Huelva, Spain		18-May	Not possible due to COVID-19 restrictions in port.
243	Huizhou, PRC	Shell	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
244	Huizhou, PRC	P66	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
245	Huizhou, PRC	Petron	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
246	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April. Equinor do not have any available Inspector at Iceland due to COVID-19
247	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April: Equinor do not have any available Inspector at Iceland due to COVID-19
248	Immingham, UK	Ineos, Borealis, Shell	12-Apr	Local inspector unavailable. (Covid-19 related)
249	Incheon, SK			Not permitted by terminal

250	Iskendrun, Turkey		29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
251	Itaqui, Brazil	BHP	17-Apr	We regret will not be able to cover vessel's inspection.
252	Itaqui, Brazil	ENOC	17-Apr	Regret due to COVID 19 travel restrictions we are unable to attend the vessel.
253	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.
254	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.
255	Itaqui, Brazil	BP	24-May	OM - our inspectors are unable to cover Itaqui as the city it falls in Sao Luis is in lockdown
256	Itaqui, Brazil	Maxcom	24-May	OM- Much to our regret we can't cover as per Covid restrictions
257	Jebel-Ali, UAE	Equinor	14-Apr	Inspection rejected - due to Hamriyah Terminal Restriction Not Allowed (COVID-19 pandemic).
258	Jebel-Ali, UAE	BP	11-Apr	Vessel had berth at SOET terminal, where SIRE Inspection are not permitted at COVID 19.
259	Jeddah, Saudi Arabia	BIECO	22-Apr	Terminal restriction
260	Jeddah, Saudi Arabia	Lukoil	26-Apr	Terminal restriction
261	Jiangsu, PRC		27-Apr	Terminal restrictions
262	Jiangyin, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
263	Jiangyin, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
264	Jisan, Saudi Arabia	Total, ENOC, AMPOL	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
265	Jorf Lasfar, Morocco			Terminal not allowed or non-availability of any local inspector due COVID – 19
266	Jorf Lasfar, Morocco	CDI	Early March	CDI was postponed on the beginning of March intentionally. Planning was to perform CDI under new management after takeover in discharging port. Takeover plans were postponed due to COVID and therefore CDI inspection too.
267	Jorf Lasfar, Morocco	CDI	26-Mar	Local inspector unavailable. No inspector available due to COVID.
268	Jorf Lasfar, Morocco	SIRE	03-Apr	Other (National Lockdown - Travel restriction)
269	Jorf Lasfar, Morocco	Total, Shell, Borealis, Rightship, Equinor, Adnoc	04-May	Local inspector unavailable. (Covid-19 related)

270	Jorf Lasfar, Morocco	Lukoil	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. (local inspector available and appointed)
271	Jorf Lasfar, Morocco	CDI	06-May	Local inspector unavailable. (Covid-19 related)
272	Jorf Lasfar, Morocco	SIRE	05-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
273	Jorf Lasfar, Morocco	CDI	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
274	Kakinada, India	CDI	24-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
275	Kakinada, India	EQUINOR	06-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
276	Kakinada, India	BP	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
277	Kakinada, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
278	Kalundborg, Denmark	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
279	Kandla, India	Rightship, Adnoc, Total, Shell, Bieco	25-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
280	Kandla, India	Adnoc, Total, Shell, Bieco	28-Apr	Local inspector unavailable. (Covid-19 related)
281	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
282	Kaohsiung, Taiwan	Valero	17-Apr	Covid 19 - travel restrictions
283	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
284	Kaohsiung, Taiwan	Gazprom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
285	Kaohsiung, Taiwan	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
286	Kaohsiung, Taiwan	Petron	18-Apr	Local inspector unavailable. (Covid-19 related)
287	Kaohsiung, Taiwan	ENOC	Apr-20	Inspector can not enter Taiwan due to restriction of entry policy for control of Covid 19
288	Kaohsiung, Taiwan	Idemitsu, Shell, BHP	March	Inspection not allowed by Terminal due to COVID – 19
289	Kaoshiung, Taiwan	SHELL, BP, CHEVRON, ENOC	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19 unavailable. (Covid-19 related)
290	Kaoshiung, Taiwan	ENOC	20-Apr	Local inspector unavailable. (Covid-19 related)
291	Kaoshiung, Taiwan	BHP	17-May	Travel restriction imposed in th country due to COVID 19.

292	Kaoshiung, Taiwan	Idemitsu	17-May	Travel restriction imposed in th country due to COVID 19.
293	Karachi, Pakistan	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
294	Karachi, Pakistan.	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
295	Karratha, Australia	BP	01-May	Terminal restrictions
296	Karratha, Australia	BP	01-May	Terminal restrictions
297	Karsto, Norway	CDI	15-Apr	Local inspector unavailable. (Covid-19 related)
298	Karsto, Norway	CDI	15-May	Local inspector unavailable. (Covid-19 related)
299	Kawasaki, Japan	SHELL	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
300	Kawasaki, Japan	P66	30-Apr	Travel/border restrictions being imposed due to COVID-19
301	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
302	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
303	Kingston,Jamaica		25-May	Not possible due to COVID-19 restrictions and country is under lockdown.
304	Koper , Slovenia	Q8	Feb-20	Restriction due to Covid 19
305	Kotka, Finland	Preem, Lukoil, Koch	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19; Local inspector unavailable. (Covid-19 related)
306	Kozmino, Russia	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
307	Kuantan, Malaysia	Gazprom	02-Apr	All hotels closed therefore inspector who was driving 6 hours refused to attend - only local inspectors allowed as there are travel restrictions
308	Kwinana, Australia	BP	01-Apr	Terminal restrictions
309	Kwinana, Australia	Chevron	15-Apr	Covid 19 - travel restrictions
310	Kwinana, Australia	BHP	26-May	Panned: Until further notice all non-essential and non- cargo operation visits such as SIRE inspections and routine technician visits will not be permitted during STS operations or when vessels are alongside the refinery jetties.
311	Kwinana, Australia	IMT	24-May	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
312	La Libertad, Ecuador	Lukoil, Equinor, Rightship, BP, Koch	03-Apr	Local inspector unavailable. (Covid-19 related)

313	La Pampilla, Peru	IMT, Repsol, YPF, Sonangol, Maxcom, Gazprom, Phillips66, Shell	31-Mar	
314	La Pampilla, Peru	IMT	31-Mar	Covid 19 - travel restrictions
315	La Pampilla, Peru	Repsol	31-Mar	Covid 19 - travel restrictions
316	La Pampilla, Peru	YPF	31-Mar	Covid 19 - travel restrictions
317	La Pampilla, Peru	Sonangol	31-Mar	Covid 19 - travel restrictions
318	La Pampilla, Peru	Maxcom	31-Mar	Covid 19 - travel restrictions
319	La Pampilla, Peru	PMI	01-Apr	Covid 19 - travel restrictions
320	La Skhira, Tunisia			Terminal not allowed or non-availability of any local inspector due COVID – 19
321	Lagos, Nigeria	ENOC	10-Apr	Local inspector unavailable. (Covid-19 related)
322	Lagos, Nigeria	Total	28-Apr	Not inspecting in Africa currently
323	Lagos, Nigeria	Nobody invited as informed by Agents	04-Apr	other - complete lockdown due to COVID19
324	Las Minas, Panama	BHP	27-May	Local inspector unavailable. (Covid-19 related)
325	Las Palmas, Spain	ENOC	24-Apr	Covid 19 - travel restrictions
326	Las Palmas, Spain	CEPSA	24-Apr	Covid 19 - travel restrictions
327	Las Palmas, Spain	Repsol	27-Apr	Covid 19 - travel restrictions
328	Lavera, France	KOCH	06-Apr	Not be able to plan the attendance due to COVID 19 travel restrictions
329	Lavera, France	BHP	06-Apr	Do not have available inspectors due to present virus situation. Flight and transport restriction beyond our control
330	Lavera, France	CDI	24-Apr	Travel restriction.
331	Lavera, Portugal	POT	10-Apr	Others - Due to COVID-19, POT do not inspect vessels temporarily.
332	Lavera, Portugal	GAZPROM	10-Apr	Local inspector unavailable.
333	Lavera, Portugal	P66	09-Apr	Local inspector unavailable.
334	Lavera, Portugal	ENOC	09-Apr	Local inspector unavailable.
335	Lavera, Portugal	BHP	06-Apr	Local inspector unavailable.
336	Lavera, Portugal	KOCH	06-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period.
337	Le Havre, France	CDI	25-Mar	Tech. manager decided to do not proceed with inspection in France to do not put crew in unnecessary risk – requested for CDI validity extension (successfully).
338	Le port, Reunion			Terminal not allowed or non-availability of any local inspector due COVID – 19
339	Leixioes, Portugal	Maxcom	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
340	Lianyungang , PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19

341	Lianyungang , PRC	P66	03-May	No inspector available due to COVID-19 travel/border restrictions
342	Lianyungang, China	CDI, Xinrongtai	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
343	Lianyungang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
344	Lianyungang, PRC	Maxcom, ALMA	14-Apr	Covid 19 - travel restrictions
345	Lianyungang, PRC	BHP, Lukoil	14-Apr	Covid 19 - travel restrictions
346	Lianyungang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
347	Lianyungang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
348	Lianyungang, PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
349	Lianyungang, PRC	SHELL	03-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
350	Lianyungangn, PRC	All Majors/CDI	24-Apr	Terminal does not permit inspections due to COVID-19
351	Libreville, Gabon	CDI	March	Inspection not allowed by Terminal due to COVID – 19
352	Limay, Phillipines	IMT	01-Apr	Due to COVID-19 not permitted by terminal
353	Limbe, Cameroon	Shell, Enoc	05-Feb	Local inspector unavailable.
354	Limbe, Cameroon	BP, Maxcom	25-Mar	Inspection cancelled , due to Lockdown and restricted movement by air, road, etc
355	Limetree Bay, US Virgin Islands	P66	17-Apr	Due to the COVID-19 travel restrictions (Lock Down)
356	Lisbon, Portugal	BP	09-May	Understand from our inspectors in the region that Portugal borders are closed till at least 15th May and likely to be extended to June.
357	Lome OPL, Togo	Agent	14-May	Covid 19 - travel restrictions
358	Lome OPL, Togo	Agent	15-May	Covid 19 - travel restrictions
359	Lome OPL, Togo	Alma	15-May	Covid 19 - travel restrictions
360	Lome, Togo	Shell	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
361	Lome, Togo	Lukoil	22-Apr	Lome is locked down
362	Lome, Togo	CDI	16-Mar	Local inspector unavailable. (Covid-19 related)
363	Lome, Togo	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)
364	Lome, Togo	ENOC	27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
365	Long Beach, CA, USA	Shell	30-Mar	Cancelled
366	Loop, USA	Lukoil, ENOC,Maxom	24-Mar	
367	Loop, USA	Lukoil	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
368	Loop, USA	ENOC	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule

369	Loop, USA	Maxcom	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
370	Loop, USA	PHILLIPS 66	12-Apr-20	There are travel restrictions in the region. To submit a new inspection request once next berthing orders are known and OM will try to accommodate inspection request.
371	Loop, USA	PHILLIPS 66	12-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
372	Loop, USA	Exxon	14-May	Unable to attend
373	Louisiana, USG	Marathon		Cancelled
374	Luanda, Angola	BHP , Maxcom, P66	13-Mar	Complete lockdown due to COVID19
375	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
376	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
377	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
378	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
379	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
380	Mailiao, Taiwan			
381	Mailiao, Taiwan	CDI	29-Mar	Local inspector unavailable. (Covid-19 related)
382	Malta	Lukoil	16-Apr	Due to Malta is locked down
383	Malta	ENOC,Koch, BIECO	27-Apr	Malta is Locked down, local inspector unavailable
384	Malta	IMT/SHELL/TOTAL	15-May	Malta in lockdown due to COVID
385	Mamonal, Colombia	CHEVRON	15-Apr	Regret to inform that we do not have an inspector available for this inspection
386	Mamonal, Colombia	LUKOIL	15-Apr	Please be informed that due to terminal restrictions inspection cannot be arranged at Mamonal.
387	Mamonal, Colombia	PHILLIPS 66	15-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
388	Mangalore, India	Idemitsu	17-May	Others
389	Manzanillo, Mexico	P66, Shell	April	Inspection not allowed as interstate travel is restricted due to Covid 19
390	Manzanillo, Mexico	P66	14-Apr	Inspection declined due to COVID -19
391	Manzanillo, Mexico	ENOC	14-Apr	Inspection declined due to COVID -19
392	Manzanillo, Mexico	P66	14-Apr	due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.

393	Manzanillo, Mexico	Equinor	14-Apr	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available to cover this request at the moment.
394	Manzatlan, Mexico	Shell, Chevron, Marathon, P66	10-Apr	Due Covid-19 sanction.
395	Map Ta Phut, Thailand	IMT	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
396	Map Ta Phut, Thailand	SHELL	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
397	Map ta Phut, Thailand	Lukoil	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
398	Map Ta Phut, Thailand	Agent	04-May	Covid 19 - travel restrictions
399	Map Ta Phut, Thailand	MMS	28-May	The current situation due to COVID-19 outbreak, PTTLNG terminal not allow to do sire inspection ,Please find attached PTTLNG's guideline for COVID-19 restriction for reference. Noted : The Civil Aviation Authority of Thailand (CAAT) has announced an extension of temporary ban on all international passenger flights to Thailand until 30 June 2020.
400	Map Ta Phut, Thailand		1-8 Apr	
401	Maptaphut, Thailand	PTT	07-May	According to the "State of Emergency" declaration in Thailand and limitations of Terminal access granted in related to COVID-19 pandemic. PTT Inspection will not be able to assign during this period. Expected the situation will be released by end of this month.
402	Map-Ta-Phut, Thailand			Terminal not allowed or non-availability of any local inspector due COVID – 19
403	Maputo, Mozambique	Lukoil	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
404	Maputo, Mozambique	P66	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
405	Maputo, Mozambique	MAXCOM	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
406	Maputo, Mozambique	ENOC	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
407	Maputo, Mozambique	ENOC	14-Apr	COVID-19 – traveling restrictions.No local inspector available.
408	Maputo, Mozambique	Agenta	23-May	Covid 19 - travel restrictions
409	Marcus Hook, USA	CDI	13-Mar	Nominated inspector declined to attend due to COVID

410	Marcus Hook, USA	CDI	31-Mar	No inspector available due to travel restrictions caused by COVID spread. Local inspector unavailable.
411	Marmara, Turkey			Terminal not allowed or non-availability of any local inspector due COVID – 19
412	Marmara, Turkey	IMT, BP,TOTAL,CHEVRON, SHELL.	10-Apr	Terminal lock down
413	Matosinhos, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
414	Mazatlan, Mexico		10-Apr	No local inspectors available
415	Mazatlan, Mexico	Chevron	15-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
416	Mazatlan, Mexico	PMI	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
417	Mazatlan, Mexico	Enoc	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
418	Mazatlan, Mexico	IMT	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
419	Mazatlan, Mexico	Shell	08-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
420	Mazatlan, Mexico	BHP	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
421	Mazatlan, Mexico	Total	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
422	Mejillones, Mexico	CDI	12-May	Local inspector unavailable. (Covid-19 related)
423	Melbourne, Australia	BHP	March	Inspection not allowed by Terminal due to COVID – 19
424	MERAK	PHILLIPS66	13-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
425	Merak, Indonesia	ENOC	02-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
426	Mesaieed, Qatar	Shell	19-May	OM - We regret we are unable to carry out the inspection at this time. We do not have any local inspectors available

427	Mesaieed, Qatar	BP	19-May	OM - our inspectors in the region are unable to make it due to travel restrictions in place for COVID-19 pandemic.
428	Mesaieed, Qatar	IMT	22-May	OM - Due to COVID-19 pandemic worldwide , with travel/border restrictions being imposed in many countries, we regret to inform that we are currently unable to arrange as your request.
429	Mesaieed, Qatar	TOTAL	22-May	OM - Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling.
430	Midia, Romania	All Majors/CDI	01-May	Inspections are not possible in Romania due to travel restrictions due to COVID-19 pandemic
431	Milazzo , Italy	ENI	1-8 Apr	
432	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
433	Mina Al Ahmadi, Kuwait	IMT	12-Apr	country under lockdown - travelling prohibited within country
434	Mina Al Ahmadi, Kuwait	CDI	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
435	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
436	Mina Al-Ahmadi, Kuwait	KOCH	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
437	Mina Al-Ahmadi, Kuwait	ENOC	10-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
438	Mina Al-Mahadi, Kuwait	BHP	06-May	Unfortunately the UAE /Gulf countries have not yet provided a clear indications as to when flights will resume. In that regards, visas too will not be issued.
439	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
440	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
441	Mobile, Alabama	Koch	02-Apr	Declined inspection as no inspector available. Likely due to COVID19
442	Mobile, Alabama	Lukoil	10-Apr	Inspector could not make in time due to delay at travel checkpoints enroute
443	Mohammedia, Morocco	CDI	26-Apr	Local inspector unavailable. (Covid-19 related)
444	Mombasa, Kenya	BHP	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
445	Monroe Terminal, Philadelphia, USEC			Not permitted as vetting considered non essential

446	Monteverde, Portugal	P66, ConocoPhillips	01-Apr	Local inspector unavailable. (Covid-19 related)
447	Montoir, France			
448	Morocco	All Majors/CDI	10-Apr	Morocco is locked down due to COVID-19 and no inspections can be arranged
449	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
450	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
451	Mumbai - JNPT, India	ENOC	03-Apr	Not possible due to COVID-19 Restrictions lockdown
452	Mumbai, India	Chevron	07-Apr	Travelling restrictions
453	Mumbai, India	Phillips 66	12-Apr	Complete lockdown in India due to COVID 19. No public or private transportation's are available.
454	Mumbai, India	ENOC	25-Apr	Covid 19 - travel restrictions
455	Mumbai, India	Lukoil	24-Apr	Covid 19 - travel restrictions
456	Mumbai, India	EQUINOR	15-May	Inspector while trying to attempt to go onboard the subject vessel for conducting SIRE inspection, he was unable to embark the vessel due to excessive swell (embarking on Eagle Victoria was aborted after making several attempts to board the vessel).
457	Mundra, India	Chevron	06-Apr	Travelling restrictions
458	Murmansk, Russia	SHELL	29-Apr	Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections Russia until further notice.
459	Murmansk, Russia	GAZPROM	28-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
460	Murmansk, Russia	LUKOIL	24-Apr	As per agents quarantine isolation for two weeks is imposed at airport for the passengers arriving from Moscow.
461	Murmansk, Russia	LUKOIL	22-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
462	Murmansk, Russia	TOTAL	18-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
463	Naantali, Finland	LUKOIL	25-Mar	E-mail from LUKOIL 23 March:We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.
464	Naantali, Finland	LUKOIL	25/03/2020	E-mail from LUKOIL 23 March:We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.

465	Nanjing, PRC	Shell, Preem	15-Apr	Local inspector unavailable. (Covid-19 related)
466	Nanjing, PRC	ConocoPhillips	15-Apr	All inspections paused due to Covid-19
467	Nansha, PRC	Shell	30-Mar	
468	Nansha, PRC	Shell	30-Mar	Covid 19 - terminal restrictions
469	Nantong, PRC	P66	27-Apr	Port authorities imposed 14 days quarantine for inspectors after inspection
470	Napier, France	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
471	Napier, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
472	Napier, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
473	New plymouth, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
474	New plymouth, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
475	New Plymouth, New Zeland	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
476	New York, USA			
477	New York, USA	Lukoil	25-Apr	Lukoil cancelled the inspection due to COVID-19.
478	Newcastle, Australia	IMT	Apr	Due to current rapidly increasing severity of COVID-19 pandemic worldwide and with travel/border restrictions being imposed in many countries, we regret to inform you that we are unable to arrange as your request for the subject vessel.
479	Newcastle, Australia			Terminal not allowed or non-availability of any local inspector due COVID – 19
480	Newyork / US	Total	14-Apr	Due to the unavailability of an inspector in the port
481	Ningbo, PRC	Koch	02-Apr	Terminal not allowed any visitors due to Covid-19
482	NingBo, PRC	Petron	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
483	NingBo, PRC	EQUINOR	03-Apr	Due to COVID-19 not permitted by terminal
484	Ningbo, PRC	BP	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
485	Ningbo, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
486	Ningbo, PRC	Lukoil	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.

487	Ningbo, PRC		25-May	COVID-19 restrictions
488	Nipah, Indonesia	IMT, Lukoil, Shell, BP, Maxcom	10-Apr	No inspectors available.
489	Nipah, Indonesia	Idemitsu	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
490	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-23
491	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-25
492	Ocoa Bay, Dominican Republic	All Majors	03-Apr	No local inspectors available in Dominican Republic
493	Omoa, Honduras	Equinor, KOCH	07-May	No available local inspectors; travelling restrictions
494	Onsan, SK		20-Mar	Due to COVID-19 not permitted by terminal
495	Onsan, SK	Shell	March	Inspection not allowed by Terminal due to COVID – 19
496	Ornskoldsvik, Sweden	Lukoil	29-Apr	Declined due to COVID-19 travel restrictions
497	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
498	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
499	Pajaritos, Mexico	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
500	Pajaritos, Mexico	Lukoil	05-May	Not Inspected. Terminal don't allow the permission for Vetting inspector.
501	Panama			Local restriction
502	Panama	BHP		Not permitted as didn't have local presence.
503	Panama	GAZPROM	09-Mar	Not permitted
504	Paradip, India		1-8 Apr	
505	Paradip, India	N/A	09-Apr	Other (National Lockdown - Travel restriction)
506	Paradip, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
507	Paranagua, Brazil			Imposed restrictions
508	Paranagua, Brazil	Equinor, P66, Koch, Shell	01-Apr	Local inspector unavailable.
509	Paranagua, Brazil	Equinor	03-Apr	Local inspector unavailable. (Covid-19 related)
510	Pasir Gudang, Malaysia	Petron	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic
511	Pembroke, UK	EQUINOR	22-May	Planned: According to information received from agent, terminal does not allow inspections to be carried out due to restrictions in force.
512	Pengerang, Malaysia		08-Apr	Due to COVID-19 not permitted by terminal
513	Pengerang, Malaysia	Petronas	14-Apr	MMS does not allow insepector to stay overnight on vessel, As per terminal, inspector to board prior berthing and disembark upon departure from terminal

514	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-19
515	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-20
516	Peru	Repsol	24-Apr	Covid 19 - travel restrictions
517	Philippines	All Majors/CDI	29-May	Information: Inspections not permitted in Phillipines due to COVID-19 pandemic. All foreigners arriving Phillipines need to serve 14 days quarantine period.
518	Pinkenba, Australia			
519	PISCO	KOCH	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
520	Pisco, Peru	EXXON	11-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
521	Point Comfort, USA	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)
522	Point Lisas, Trinidad & Tobago	Lukoil, Savonetta, SP#2 South & SP#4	30-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
523	Point Lisas, Trinidad & Tobago	CDI	21-Apr	Local inspector unavailable. (Covid-19 related)
524	Point Lisas, Trinidad & Tobago	Lukoil, Shell, Rightship, Equinor	10-Apr	Local inspector unavailable. (Covid-19 related)
525	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
526	Point Lisas, Trinidad & Tobago	CDI	05-Apr	Local inspector unavailable. (Covid-19 related)
527	Point Lisas, Trinidad & Tobago	CDI	25-Apr	Local inspector unavailable. (Covid-19 related)
528	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
529	Point Lisas, Trinidad and Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
530	Point Lisas, Trnindad and Tobago	All Majors	03-Apr	No local inspectors available in Point Lisas and airport closed down till furthe notice.
531	Port Allan, USA	EQUINOR	24-Apr	Covid 19 - travel restrictions
532	Port Allan, USA	ENOC	27-Apr	Covid 19 - travel restrictions
533	Port Dickson, Malaysia	Idemitsu	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic .
534	Port Dickson, Malaysia	CDI	16-Apr	lockdown due to COVID19 - Foreign inspectors not allowed to travel to Malaysia
535	Port Elizabeth, South Africa		16-Apr	no visitor/inspector allowed due to Covid-19
536	Port Elizabeth, South Africa	CDI	04-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.

537	Port Esquivel, Jamaica	BHP	30-Mar	
538	Port Esquivel, Jamaica	BHP	30-Mar	Covid 19 - travel restrictions
539	Port Esquivel, Jamaica	Maxcom	01-Apr	Covid 19 - travel restrictions
540	Port Everglades, USA	ENOC	24-Apr	Local inspector unavailable. (Covid-19 related)
541	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
542	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
543	Port Klang, Malaysia	CDI	01-May	Malaysia lock down till 12th May as per message from agents. Only local inspectors allowed to carry out the inspection subject to terminal permission. CDI does not have any local inspector in Malaysia.
544	Port Moresby, Papua New Guinea	Chevron, BHP	27-May	Due to the COVID-19 travel restrictions
545	Port Reunion	CDI	03-Apr	No local inspectors available.
546	Port Said, Egypt	Gazprom	28-Apr	Complete lockdown No Vetting inspections allowed
547	Pozos Colorados, Colombia			
548	Pt. Lisas, USA	CDI	08-Apr	Due to the current travel restrictions CDI unable to assign inspector at T & T
549	Puerto Bahia, Colombia		10-Apr	No inspectors available
550	Puerto Cortes, Honduras	CDI	14-Apr	Covid 19 - travel restrictions
551	Puerto Cortes, Honduras	Agents	14-Apr	Covid 19 - travel restrictions
552	Puerto Moin, Costa Rica	Lukoil	04-May	Not Inspected. Vetting inspections are not allowed to be performed alongside (only at anchorage)
553	Puerto Santo Tomas, Guatemala			Terminal not allowed or non-availability of any local inspector due COVID – 19
554	Pyeongtaek, South Korea	CDI, SPTT	17-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
555	Qidong, PRC	ENOC	06-Apr	Terminal restrictions
556	Qingdao, China	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
557	Qingdao, China	ENOC	01-May	Terminal restrictions
558	Qingdao, China	Petron	05-May	Terminal rejection of the inspector
559	Qingdao, PRC			
560	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
561	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
562	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'

563	Qingdao, PRC	BHP	13-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
564	Qingdao, PRC	PHILLIPS66	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
565	Quanzhou, China	Lukoil, Powershell Terminal	11-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
566	Quanzhou, PRC	P66	Mar-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
567	Quanzhou, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
568	Quintero, Chile	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
569	Quintero, Chile	Marathon	16-Apr	Due to COVID-19, the terminal is no allowing inspections
570	Quintero, Mexico			
571	Ras Al Khair, Saudi Arabia	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
572	Ras Al Khair, Saudi Arabia	ENOC	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
573	Ras Al Khair, Saudi Arabia	Adnoc, Rightship, Koch, Shell	10-Apr	Local inspector unavailable. (Covid-19 related)
574	Ras Al Khair, Saudi Arabia	CDI	14-Mar	Local inspector unavailable. (Covid-19 related)
575	Ras Al Khair, Saudi Arabia	CDI	10-Apr	Local inspector unavailable. (Covid-19 related)
576	Ras Laffan, Qatar		23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
577	Ras Tanura, Saudi Arabia	ENOC	31-Mar	Covid 19 - travel restrictions
578	Ras Tanura, Saudi Arabia	Maxcom	31-Mar	Covid 19 - travel restrictions
579	Ras Tanura, Saudi Arabia	BHP	01-Apr	Covid 19 - travel restrictions
580	Ras Tanura, Saudi Arabia	ENI	01-Apr	Covid 19 - travel restrictions
581	Ras Tanura. Saudi Arabia	ENOC, Maxcom, BHP, ENI	01-Apr	
582	Ras Tanurah, Saudi Arabia	Adnoc, Saudi Aramco, Total, Lukoil, P66	26-Apr	Local inspector unavailable. (Covid-19 related)
583	Rayong, Thailand		27-Apr	Agents - Covid 19 - travel restrictions
584	Reunion	CDI	03-Apr	No local inspectors available.

585	Richard's Bay, South Africa	Rightship, Total, Shell, Neste, Respol, YPF, Conocophilips, Preem	23-Apr	Local inspector unavailable. (Covid-19 related)
586	Richmond, USA	Lukoil	03-Apr	Not possible due to COVID-19 Restrictions. Only critical personnel allowed.
587	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.
588	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.
589	Rio Grande, Brazil			Imposed restrictions
590	Rio Haina, Dominican Republic	CDI	09-May	Local inspector unavailable. (Covid-19 related)
591	Rizhao, PRC	Shell and Maxcom	25-Jan	Inspector's not willing to go due to COVID19
592	Rizhao, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
593	Rizhao, PRC	Chevron	08-May	No available local inspectors; travelling restrictions
594	Rizhao, PRC		1-8 Apr	
595	Rotterdam, Netherland	CDI	20-Mar	Inspector refused travelling to Rotterdam due to airport closure at ISLE OF MAN
596	Rotterdam, Netherlands	SHELL	25-May	We regret we are unable to carry out the inspection at this time, as we do not have any local inspectors available. Please request again at a later date.
597	Rovigo, Itali	Shell	05-May	Inspector required to embark by launch
598	Rovigo, Itali	Repsol	05-May	Inspection deemed 'not exceptional' due to Covid-19
599	Rovigo, Itali	BP	05-May	Inspection declined as inspector would have had to remain onboard overnight
600	Rudong, PRC	Phillips66	03-Apr	Terminal restrictions
601	Ruwais, Qatar	Shell	22-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
602	Ruwais, Qatar	Adnoc, Total, Preem, P66	22-Apr	Local inspector unavailable. (Covid-19 related)
603	Ruwais, Qatar	Bieco	22-Apr	No response from OM
604	Ruwais, UAE	ADNOC	12-Apr	Travel restrictions due to COVID - Terminal restrictions due to security sensitivity of the area
605	Sabine Pass, USA	Rightship, Shell	25-May	Cancelled due to unsafe access - adjusted boarding measures (Covid-19 related)
606	Saint Nicolas, France	CDI	20-May	Local inspector unavailable. (Covid-19 related)
607	Saldana Bay, South Africa	BHP, P66	04-Apr	other - complete lockdown due to COVID19

608	Salina Cruz, Mexico	Lukoil	16-Apr	Foreign Inspector travel ban
609	Salina Cruz, Mexico	P66	16-Apr	Foreign Inspector travel ban
610	Salvador, Brazil	ENOC	23-Apr	Planned - Due to COVID-19 I will not be able to attend you in Salvador as I am requiring flight from Rio De Janeiro. I can attend you in Rio De Janeiro or in São Sebastião therefore keep me posted when you have program to attend one of these two ports.
611	Salvador, Brazil	ENOC	01-May	Inspector is unable to attend at this call due to prior commitments.
612	Salvador, Brazil	ENOC	01-May	The inspector is unable to attend at this call due to prior commitments. Please advise us her next convenient port.
613	Santos, Brazil			Imposed restrictions
614	Santos, Brazil	Koch, Petrobras	02-Apr	Local inspector unavailable.
615	Santos, Brazil	Phillips66	13-Apr	
616	Santos, Brazil	Shell, BHP	14-Apr	Shell - Not covering; BHP Not performing inspection.
617	Santos, Brazil	Petrobras	15-Apr	Petrobras - Not performing inspections until further, KOCH - No available local inspectors; travelling restrictions
618	Santos, Brazil	Shell	01-May	Not covering
619	Santos, Brazil	ENOC	02-May	
620	Sao Luis, Brazil	Idemitsu	18-Mar	
621	Sariaya, Philippines	BHP-Rightship, Equinor	24-Apr	Inspection cancelled.
622	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
623	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
624	Shanghai, China	Shell	March	Inspection not allowed by Terminal due to COVID – 19
625	Shiudong, PRC	Lukoil	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
626	Shiudong, PRC		08-May	Inspector who is from abroad is not permitted to come for inspection. Chinese is permitted. If inspector is Chinese , he need to arrive Maoming for quarantine 3 days before on board, and go to hospital for Nucleic acid detection.Launch cost to the terminal will be around 18,000/-USD
627	Shuidong, PRC	BHP	28-May	Covid 19 - travel restrictions
628	Shuidong, PRC	Alma	29-May	Covid 19 - travel restrictions
629	Sierra Leone	Lukoil, Alma	29-Mar	
630	Sierra Leone & Conakry	Lukoil & Alma	29-Mar	Covid 19 - travel restrictions

631	Sikka India	IDEMITSU	12-May	Lockdown in India due to Covid 19 pandemic.
632	Sikka, India	CDI	30-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
633	Sikka, India		1-8 Apr	
634	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
635	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
636	Sines, Portugal			Imposed restrictions
637	Sines, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
638	Sines, Portugal	Lukoil, POT, Saras, Maxcom, Erg, Neste	20-Apr	No local Inspectors and Covid-19 travel restrictions
639	Sines, Portugal	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC	20-Apr	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC - Local inspector unavailable. (Covid-19 related)
640	Sines, Portugal	Cepsa	01-May	Declined due to COVID-19 travel restrictions
641	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
642	Singapore	Enoc	21-Apr	Due to terminal restriction (Singapore Petrochemical Complex Olefin I)
643	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
644	Singapore	Idemitsu	19-May	Singapore Terminal Restricted for inspection due to COVID 19 pandemic
645	Singapore, Shell Bukom	Gazprom	17-Apr	Terminal declined inspector's boarding at their terminal due to COVID 19
646	Singapore, Vopak Penjuru	Gazprom	15-Apr	Rejected due to terminal disapproved of any visitors or auditor during current Covid -19 situation
647	Sohar, Oman	CDI, Oiltanking Odfjell	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.

648	Sohar, Oman	BHP, Equinor, Gazprom, Repsol, KOCH, ENI, P66, Lukoil, BP, Total, ENOC	30-Apr	Local inspector unavailable. (Covid-19 related)
649	Sohar, Oman	Shell, BP	10-May	Local inspector unavailable. (Covid-19 related)
650	Sohar, Oman	All Majors/CDI	15-May	All routes closed in Oman, foreigners cannot arrive to carry out inspection due to COVID-19
651	Sohar, Oman	Equinor	21-May	Due to travel restrictions imposed by the covid19 outbreak, there are no inspectors available to cover.
652	Sohar, Oman	ENOC, ADNOC, KOCH	21-May	Local inspectors not available; travelling restrictions
653	Sohar, Oman	Idemitsu	22-May	No available local inspectors; travelling restrictions
654	South Africa ports		02-Apr	Heightened level of Security level protocols within the South African Port System during the lockdown period.
655	Southwold, UK	Chevron/Total/Equinor/Shell	25-May	Declined due to unavailability of inspectors
656	Sri Racha, Thailand			Not permitted
657	Sri Racha, Thailand	Lukoil	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
658	St' Charles, Barbados	BHP	02-Apr	Last muete cancellation as terminal change policy - no visitor/inspector allowed due to COVID19
659	St Croix, US Virgin Islands		02-Apr	Not possible due to COVID-19 restrictions
660	St Croix, USA (Virgin Island)	TOTAL	20-Apr	Local inspector unavailable. (Covid-19 related)
661	St. Eustatius		14-Apr	Not possible due to COVID-19
662	St. James, LA USA	Maxcom	01-May	No local inspector available in Louisiana (covid-19 related) normal Texas based inspector to attend but not ready to serve quarantine period when return to Texas
663	Stenungsund, Sweden	CDI	17-Mar	Nominated Inspector declined due to COVID
664	Stignaes, Denmark			Imposed restrictions
665	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April. We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.

666	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April. Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
667	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April. Thank you for your email. Please note we not have any local inspectors in Sweden.
668	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April: We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
669	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April: Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
670	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April: Please note we not have any local inspectors in Sweden.
671	Suape, Barzil	IMT/SHELL/CHEVRO N	15-May	Due to COVID-19 travel restrictions
672	Suape, Brazil			Imposed restrictions
673	Suape, Brazil	ENOC	17-Apr	Due to COVID 19 travel restrictions we are unable to attend the vessel.
674	Suape, Brazil	IMT/SHELL/CHEVRO N	15-May	Due to COVID-19 travel restrictions
675	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
676	Suez, Egypt	Agents	22-May	Covid 19 - travel restrictions
677	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
678	Suez, Egypt	IMT	29-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
679	Sumed, Egypt	Lukoil	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
680	Sumed, Egypt	Shell	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
681	Taicang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
682	Taicang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
683	Taicang, PRC	Maxcom, ALMA, BHP,Lukoil	14-Apr	Covid 19 - travel restrictions
684	Taicang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
685	Taicang, PRC	BP	09-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
686	Taicang, PRC	Idemitsu	29-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
687	Taicang, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19

688	Taichung, Taiwan	Koch, Shell, Total, Rightship, Adnoc	20-Apr	Local inspector unavailable. (Covid-19 related)
689	Taichung, Taiwan	BHP, Gazprom	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
690	Tainjin, PRC			
691	Taipei, Taiwan	CDI	27-Apr	Travel/border restrictions being imposed due to COVID-21
692	Taixing, PRC		10-Apr	Terminal didn't allowed
693	Taixing, PRC	CDI	11-Apr	Terminal rejected additional personnel to enter.
694	Taixing, PRC	Lukoil	01-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
695	Taizhuo, PRC	Lukoil	08-May	Covid 19 - travel restrictions
696	Taizhuo, PRC	Agent	07-May	Covid 19 - travel restrictions
697	Tallinn, Estonia	Lukoil	16-Apr	
698	Tallinn, Portugal	LUKOIL	16-Apr	
699	Tamatave, Madagascar (Toamasina)	Maxcom	16-Apr	Covid 19 - travel restrictions
700	Tamatave, Madagascar (Toamasina)	Lukoil, Total, BHP, ENOC, P66, Aethon, Koch, agents	14-Apr	Covid 19 - travel restrictions
701	Tangier MED, Morocco	ENOC	02-Apr	Travelling restrictions
702	Tangier, Morocco		07-Apr	Not allowed due to COVID-19 restrictions
703	Tanjung Pelepas, Malaysia	KOCH	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
704	Tanjung Pelepas, Malaysia	P66	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
705	Tanjung Bin, Malaysia	Koch	26-Mar	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
706	Tanjung Priok, FSRU Nusentara, Indonesia	BP	10-May	Travel restriction imposed in the country due to COVID 19.
707	Tarragona, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
708	Tarragona, Spain	Equinor	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
709	Tauranga, New Zealand	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down

710	Tauranga, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
711	Teesport, UK	Exxon	02-Apr	No available local inspectors; travelling restrictions
712	Tema, Ghana	CDI	19-Mar	Local inspector unavailable. (Covid-19 related)
713	Tema, Ghana	ENOC, KOCH	30-Apr	Local inspector unavailable. (Covid-19 related)
714	Tetney, UK	BP	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
715	Tetney, UK	EQUINOR	13-Apr	Local inspector unavailable.
716	Tetney, UK	BP	20-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
717	Thessaloniki, Greece	P66	07-May	Local inspector unavailable. (Covid-19 related)
718	Thessaloniki, Greece	Repsol	07-May	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
719	Tianjin, PRC	CDI	10-Apr	No inspection was not allowed by port authority
720	Tianjin, PRC	IMT, Chevron, Shell, Total	Feb	Inspection not allowed by Terminal due to COVID – 19
721	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
722	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
723	Tianjin, PRC	Lukoil	28-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
724	Tianjin, PRC	Equinor, BHP, Gazprom, Lukoil, KOCH, Idemitsu	09-Feb	Inspector's not willing to go due to safety/health reasons + terminal change policy - no visitor/inspector allowed due to Covid-19.
725	Tianjin, PRC	CDI	11-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
726	Townsville, Australia	Chevron	March	Inspection not allowed by Terminal due to COVID – 19
727	Tramandai, Brazil	Lukoil	18-Apr	Due to the COVID-19 travel restrictions (Unavailability of Flights)

728	Tramandai, Brazil		24-Apr	Not allowed due to COVID-19 restrictions
729	Tramandai, Brazil	Lukoil	07-May	Covid 19 - travel restrictions
730	Tramandai, Brazil	PMI	04-May	Covid 19 - travel restrictions
731	Tramandai, Brazil	Koch	03-May	Covid 19 - travel restrictions
732	Tramandai, Brazil	Maxcom	02-May	Covid 19 - travel restrictions
733	Tranmere, UK	ENOC	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
734	Tuban, Indonesia	ENOC	05-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
735	Tuban, Indonesia	Rightship	07-Apr	Not possible due to border closures and quarantine requirements due to COVID-19
736	Tuban, Indonesia	Cocophillips	16-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
737	Tuban, Indonesia	Exxon, P66	16-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
738	Tuticorin, India	CDI	19-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
739	Tuxpan, Mexico	VIVO	31-Mar	
740	Tuxpan, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
741	Tuxpan, Mexico			Do not allow inspectors onboard.
742	Ulsan, SK	NESTEOIL	22-May	(Planned) - Neste not performing any inspections due to the COVID 19 situation.
743	Ulsan, SK	IMT, SHELL	10-Apr	Travel restriction
744	Ulsan, SK	All Majors/CDI	15-May	SK Energy terminal in Ulsan do not permit any inspections to be carried out during cargo operations. Option provided is to carry out the inspection at anchorage which will be an idle inspection and not serve the purpose.
745	Ust Lega, Russia	EXXON	07-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels. We will maintain our pragmatic approach in evaluating TC vessels and SIRE inspections reports will be reviewed on a case by case basis accordingly
746	Ust Lega, Russia	EXXON	07-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
747	Vadinar, India			
748	Vadinar, India	Maxcom	09-Apr	Covid 19 - travel restrictions
749	Vadinar, India	BHP	06-Apr	Covid 19 - travel restrictions
750	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
751	Vadinar, India	ENOC	01-May	Covid 19 - travel restrictions
752	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions

753	Valencia, Spain	BHP	29-May	OM - Unfortunately do not have available inspectors and will decline inspection due to current health/virus/quarantine /travel problems , no flights etc..
754	Valencia, Spain	P66	29-May	OM - Unable to schedule the inspection due to the conflict that the Suggested date is within 30 days of an already planned SIRE/OVID inspection with another member.
755	Vatso, Italy	CDI	March	Inspection not allowed by Terminal due to COVID – 19
756	VeraCruz, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
757	VeraCruz, Mexico			Do not allow inspectors onboard.
758	Veracruz, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
759	Veracruz/Altamira, Mexici	CDI	14-Apr	Covid 19 - travel restrictions
760	Virgin Islands, USA	All Majors/CDI	10-Apr	All ports in USVI is locked down due to COVID-19 and no inspections can be arranged
761	Vizag, India	Koch	08-Apr	Other (National Lockdown - Travel restriction)
762	Vizag, India	CDI	15-Apr	India lockdown due to COVID
763	Vizag, India	Koch	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
764	Vizag, India	Equinor	20-May	Due to several restrictions imposed by the covid-19 outbreak on this given location, the inspector will not be able to attend.
765	Vizag, India	Koch	06-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
766	Vizag, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
767	Vungtau, Vietnam	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
768	Vungtau, Vietnam	NESTEOIL	02-May	At this moment Neste does not carry out sire inspection
769	Vungtau, Vietnam	P66	02-May	Travel/border restrictions being imposed due to COVID-20
770	Walvis Bay, Namibia		April	Namibian authorities suspended Visa issue for 1 month thus NO inspector available
771	Walvis Bay, Namibia	BHP	06-Apr	Lockdown in that area and restricted movement by air, road or rail Not be possible to inspect the subject vessel.
772	Walvis Bay, Namibia	BHP	06-Apr	Local inspector unavailable.
773	Wenzhou, PRC		10-Apr	Terminal didn't allowed
774	Whiffenhead, Canada	BP	16-Apr	Foreign Inspector travel ban
775	Wilhelmshaven, Germany			Imposed restrictions
776	Wilhelmshaven, Germany	BP	29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.

777	Yabucan, Puerto Rico	ENOC/BHP/Lukoil/Equinor	03-Apr	Not possible due to COVID-19 Restrictions
778	Yanbu, Saudi Arabia	ADNOC	28-Apr	Travel restrictions - Lockdown
779	Yanbu, Saudi	Enoc	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
780	Yanbu, Saudi	Shell	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
781	Yanbu, Saudi Arabia	CDI, Koch, Shell	12-Apr	Other (National Lockdown - Travel restriction)
782	Yanbu, Saudi Arabia	CDI	11-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
783	Yanbu, Saudi Arabia	CDI / Gas	26-May	No available local inspectors; travelling restrictions
784	Yanbu, Saudi Arabia	Koch	29-Apr	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
785	Yangpu, PRC	Idemitsu	12-Apr	No inspection was not allowed at the terminal
786	Yangpu, PRC	Idemitsu	12-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
787	Yangpu, PRC	CDI	17-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
788	Yangshan, PRC	MMS	16-May	Present stage, visitor is not allowed in Yangshan LNG terminal.
789	Yantai, PRC	Chevron, Shell, Koch,	Feb	Inspection not allowed by Terminal due to COVID – 19
790	Yantai, PRC	Lukoil, P66	21-Feb	Local inspector unavailable. (Covid-19 related)
791	Yantai, PRC	CDI	21-Feb	Local inspector unavailable. (Covid-19 related)
792	Yeosu, SK		05-Jan	Terminal policy- no visitor/inspector allowed due to Covid-19
793	Yeosu, SK		25-Mar	Due to COVID-19 not permitted by terminal
794	Yeosu, SK	EXXON	08-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.

795	Yingkou, PRC	NA	17-May	<p>The following restrictions applies:</p> <ol style="list-style-type: none"> 1. Inspector should hold Two times (24 interval) nucleic acid testing before onboard date. (Send agent the test reports and other required documents in advance) <ol style="list-style-type: none"> a. Test can be done at local hospital, 1st test to be done 7 days prior to attendance. 2. 14 days isolation in Yingkou hotel arranged by local port authorities after departure from vessel 3. Other documents will inform him directly if confirmed. 4. Inspectors will most preferably not from the high risk area. (HUBEI, JILIN, HEILONGJIANG province)
796	Yingkou, PRC	GAZPROM	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
797	Yizheng, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
798	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
799	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
800	Yumurtalik, Turkey	CDI	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
801	Yung An, Taiwan			
802	Yung An, Taiwan	Chevron	02-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
803	Yung An, Taiwan	KOCH	01-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
804	Yung An, Taiwan	GAZPROM	15-Apr	Local inspector unavailable.
805	Yung An, Taiwan	BP	14-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
806	Zeebrugge, Belgium	REPSOL	14-Apr	<p>Other - Due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.</p>

807	Zeebrugge, Belgium	PREEM	05-May	Inspector refused to follow precautions stipulated by the Company SMS.
808	Zhangjiagang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
809	Zhangjiagang, PRC	Maxcom ALMA, BHP, LukOil,	14-Apr	Covid 19 - travel restrictions
810	Zhangjiagang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
811	Zhangjiagang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
812	Zhangjiagang, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
813	Zhangjiang, PRC	BP	18-Feb	As per BP's message they stated due to terminal restrictions but found out inspector did not want to use launch boat as we managed to book inspection with another oil major
814	Zhapu, PRC	BP	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
815	Zhapu, PRC	Lukoil, BHP Rightship	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
816	Zhoushan, PRC	Shell	02-Apr	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
817	Zhoushan, PRC	ENOC	13-Apr	Terminal restrictions
818	Zhoushan, PRC		21-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
819	Zhoushan, PRC	SHELL	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
820	Zhoushan, PRC	SHELL	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
821	Zhoushan, PRC		08-May	Terminal restriction for sire inspection is in place.
822	Zhoushan, PRC	EQUINOR	14-May	Terminal policy- no visitor/inspector allowed due to Covid-19
823		BASF	Apr	Rejected for business based on CDI more than 12 months old / no physical CDI could be completed prior to last CDI expiring 12mths.