

Date : 28/06/2020

INSPECTION CANCELLED OR DECLINE				
No	Port	OM	Date	(blue font - new entry since last weekly update) Remark
1	Adelaide, Australia	Koch, Shell	March	Inspection not allowed by Terminal due to COVID – 19
2	A Corunna, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
3	A.D.Reis, Brazil	EQUINOR	05-Jan	Declined due to travel restrictions
4	A.D.Reis, Brazil	TOTAL	05-Apr	Declined due to unavailability of inspectors
5	Abidjan, Ivory Coast	CDI	15-Mar	Local inspector unavailable. (Covid-19 related)
6	Adabiyah, Egypt	Statoil	22-Apr	No flights into Egypt, Statoil cancelled request
7	Adabiyah, Egypt	CDI	25-May	Rejected for business based on SIRE more than 6 months old / no physical SIRE could be completed prior to last SIRE expiring 6mths/12mths.
8	Adelaide, Australia	Shell, BP, Idemitsu, Viva	April	Inspection not allowed as interstate travel is restricted due to Covid 19
9	Ain Sukhna Sonkar Terminal, Egypt	Shell	20-May	Others – Unable to carry out the inspection at this time, do not cover this Country.
10	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
11	Ain Sukhna, Egypt	Lukoil, Adnoc, Maxcom	03-May	Covid 19 - travel restrictions
12	Ain Sukhna, Egypt	ENOC	02-May	Covid 19 - travel restrictions
13	Ain Sukhna, Egypt	P66	04-May	Covid 19 - travel restrictions
14	Ain Sukhna, Egypt	MOH	04-May	Covid 19 - travel restrictions
15	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
16	Al Jubail, Saudi Arabia	IMT	25-Jun	OM - Due to current COVID-19 pandemic situation worldwide , we regret to inform that we are currently unable to arrange as your request.
17	Alcudia, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
18	Alexandria, Egypt	Enoc	18-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
19	Alexandria, Egypt	Koch	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
20	Alexandria, Egypt	Maxcom	23-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
21	Aliaga, Turkey			Imposed restrictions

22	Aliaga, turkey	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
23	Aliaga, Turkey	All Majors/CDI	15-May	Inspections not permitted to be carried out due to COVID-19. Local inspector was appointed; however he was denied entry to the terminal for the purpose of inspection.
24	Aliaga, Turkey	GAZPROM	09-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
25	Aliaga, Turkey	GAZPROM	09-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
26	AL-Jubail, Saudi Arabia	Idemitsu	15-Jun	All air-flights to or from Saudi Arabia has been suspended due to COVID-19 until further instructions.
27	All ports in India	All Majors	03-Apr	Locked down till 14-Apr, no inspections can be scheduled
28	Altamira, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
29	Altamira, Mexico			Do not allow inspectors onboard.
30	Altamira, Mexico	Maxcom	27-Mar	All arranged, port closed over night for non-locals, even as inspector was Mexican
31	Altamira, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
32	Altamira, Mexico	Maxcom	08-May	Covid 19 - travel restrictions
33	Altamira, Mexico	ALMA	07-May	Covid 19 - travel restrictions
34	Altamira, Mexico	ENOC	07-May	Covid 19 - travel restrictions
35	Amsterdam, Netherland	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
36	Amsterdam, Netherland	P66	Apr	No inspector available
37	Amsterdam, Netherlands	Neste	18-May	At this moment Neste does not carry out any sire inspections.
38	Angra Dos Reis, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
39	Antifer, France	BP	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
40	Antwerp, Belgium	Gazprom	06-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. From agent: We received terminal ATPC instructions from that due COVID nobody is allowed on the terminal anymore till further notice
41	Apia, Samoa	P66	19-Jun	Due to the COVID-19 travel or terminal restrictions
42	Arzew, Algeria		07-Apr	Not allowed due to COVID-19 restrictions
43	Arzew, Algeria	CDI	27-May	Local inspector unavailable. (Covid-19 related)
44	Ashklelon, Isreal	Gazprom	04-Mar	Last minute cancellation as inspector's were not allowed to enter Israel if previously travelled to high risk COVID19 countries in Europe
45	Aughinish, Ireland	P66	25-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
46	Aughinish, Ireland	Koch, VIVO	25-Apr	Local inspector unavailable. (Covid-19 related)
47	Augusta, Sicily	BHP	29-May	The Sicily region have still travel limitation until at least the 7th June. Not residents in Sicily cannot travel to Augusta. In view of restriction, we will decline the inspection invitation.

48	Aviero, Portugal	CDI	28-Mar	Terminal requirements not to allow any inspections due to COVID-19
49	Bahia Blanca, Argentina	KOCH, Idemitsu	31-Mar	Local inspector unavailable. KOCH and Idemitsu were not able to find available inspectors due to COVID
50	Banática, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
51	Bangkok & Maptaphut, Thailand	PTT	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
52	Banjul, SK	Maxcom	16-Apr	Covid 19 - travel restrictions
53	Banjul, SK	Maxcom	15-Apr	Covid 19 - travel restrictions
54	Banjul, SK	Total, ENOC, Maxcom	14-Apr	Covid 19 - travel restrictions
55	Banjul, SK	BHP	14-Apr	Covid 19 - travel restrictions
56	Banjul, SK	Aethon/Koch	14-Apr	Covid 19 - travel restrictions
57	Barcelona, Spain	Cepsa	01-Jun	Declined on 20 May 2020 due to COVID-19 travel restrictions
58	Barranquilla, Colombia	BEICO	10-Apr	Port does not allow till further notice.
59	Basamuk, PNG			
60	Bataan, Philipine	PETRON	18-May	Regret to inform you that visiting inspector is not allowed as of the moment due to COVID-19 and we are still on community quarantine until May 30.
61	Beaumont, USA	Exxon/IMT	05-Apr	
62	Beira, Mozambique	ENOC	20-May	Covid 19 - travel restrictions
63	Beira, Mozambique	P66	27-Apr	Local inspector unavailable. (Covid-19 related)
64	Beira, Mozambique	Lukoil	27-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
65	Belem, Barzil	Petrobras	10-Apr	Petrobras are not carrying out inspections worldwide due to COVID-19
66	Belize	EQUINOR	19-May	Covid 19 - travel restrictions
67	Belize,	Equinor	01-Jun	Covid 19 - travel restrictions
68	Benicia, CA, USA	Phillips66	07-Apr	Terminal not allowed
69	Bethioua, Algeria	Shell	25-Jun	We regret we are unable to carry out the inspection at this time. We do not cover this Country.
70	Bilbao, Brazil			Imposed restrictions
71	Bilbao, Spain	PETRONOR	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
72	Bintulu OPL, Malaysia	Petronas	20-Apr	During Movement Control Order period, all personal enter Sarawak have to be complete compulsory quarantine for 14 days at hotel / hospital arrange by local government. After complete compulsory quarantine 14 days, auditor to need pass Port health screening before permitted to board vessel at anchorage.

				As per the above and also travel restrictions and safety of the inspector; we regret to inform cannot cover the inspection.
73	Bintulu, Malaysia	MMS	27-May	Due to COVID-19 and movement restriction, inspector need to be quarantine at Sarawak for 14 days before the inspection.
74	Bizerte, Tunisia	BP	09-Jun	short notice
75	Bizerte, Tunisia	Shell	08-Jun	unable to conduct inspection in Tunisia
76	Bonny, Nigeria	Petron	16-May	Terminal change policy – visitor/inspector need 14 days quarantine due to Covid-19.
77	Bontang , Indonesia	Idemitsu	17-Apr	No available local inspectors; travelling restrictions
78	Bordeaux, France	EQUINOR	17-May	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available for the given port/date to cover this request at the moment.
79	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
80	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
81	Botany Bay,	VIVA	15-Apr	Local inspector unavailable.
82	Botany Bay, Australia	Ampol	02-Apr	Due to situation of Coronavirus outbreak, OM are unable to process the inspection request.
83	Botany Bay, Australia	BP, Total, IMT, Lukoil, Ampol and Shell	10-Apr	Shell eventually took the inspection but finally terminal did not allow.
84	Botany Bay, Australia	BP	02-Apr	Travel restriction imposed in th country due to COVID 19
85	Bourgas, Bulgaria	SHELL	09-Apr	Local inspector unavailable.
86	Bourgas, Bulgaria	BP	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
87	Bourgas, Bulgaria	Chevrom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
88	Brisbane, Australia		03-Apr	Allowed- boarding of inspectors only 3hours after berthing. Check with agents.
89	Brisbane, Australia	ENOC	14-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
90	Brisbane, Australia	P66	17-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
91	Brisbane, Australia	CHEVRON	28-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
92	Brisbane, Australia	Chevron	28-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
93	Brunei	Gazprom, idemitsu, Equinor, Maxcom	04-Apr	other - complete lockdown due to COVID19
94	Brunei	All Majors/CDI	29-May	Information: Inspections not permitted in Brunei due to COVID-19 pandemic. All foreigners arriving Brunei need to serve 14 days quarantine period.
95	Burgas, Bulgaria	All Majors/CDI	01-May	Bulgaria is locked down due to COVID-19
96	Busan, SK		05-May	Not possible due to COVID 19 restrictions
97	Busan, SK		05-May	Not possible due to COVID 19 restrictions
98	Cabo Negro, Chile	CDI	16-May	Other - Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
99	Cabo Negro, Chile	CDI	16-May	Local inspector unavailable. (Covid-19 related)
100	Cabo Negro, Morocco	CDI	16-May	Inspection not permitted due to Terminal Internal Policy, not COVID-19 related

101	Cabo Negro, Morocco	CDI	16-May	Local inspector unavailable. (Covid-19 related)
102	Caldera, Chile	Marathon	22-Apr	Terminal restriction
103	Callao, Peru	ConocoPhillips	23-Apr	ConocoPhillips declined request due to Covid
104	Callao, Peru	CDI	08-May	Local inspector unavailable. (Covid-19 related)
105	Callao, Peru	Any OM	15-Jun	Foreign Inspector travel ban. Airports closed due Emergency declared till June 30th.
106	Canaport, Canada	Chevron	17-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
107	Canaport, Canada	Equinor	15-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
108	Canaport, Canada	EQUINOR	21-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
109	Canaport, Canada			Terminal quarantines vessel if inspector boards prior berthing. Not permitted during discharge. Vessel must be at sea for >14 days prior berthing. Post discharge you are allowed everything at the anchorage.
110	Caoeger Bay, South Africa	ENOC, Equinor	05-May	Local inspector unavailable. (Covid-19 related)
111	Caofeidian, PRC	Enoc, Total, Shell, P66, Bieco, Koch, BHP, IMT, Chevron	Feb	Inspection not allowed by Terminal due to COVID – 19
112	Cartagena, Colombia	Chevron	19-May	Inspector unavailability
113	Cartagena, Spain			Terminal not allowed or non-availability of any local inspector due COVID – 19
114	Cartagena, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
115	Cartagena, Spain	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
116	Castellon, Spain	Enoc	March	Inspection not allowed by Terminal due to COVID – 19
117	Castellon, Spain	Equinor	21-Mar	Terminal change policy - no visitor/inspector allowed due to Covid-19
118	Ceuta, Spain	Lukoil, Cepsa, OMV, Total. Maxcom, POT, Repsol, P66, Enoc	16-Apr	No local Inspectors and Covid-19 travel restrictions
119	Ceyhan, Turkey	ENOC	08-May	ENOC are unable to attend the vessel.
120	Ceyhan, Turkey		22-Apr	Checked with Agents - Complete lockdown No Vetting inspections allowed

121	Chang Xing, PRC	All OM	06-May	Terminal restriction
122	Changzhou Huarun, PRC		13-May	As per agents - not allowed
123	Changzhou, PRC	CDI	09-Jun	Pls kindly note subject vessel fixed calling Jiangyin/Changzhou/Taizhou. After checked with each port, Changzhou and Taizhou tml don't permit inspection nowadays due to COVID-19 even Chinese. For Jiangyin, as our agent reported, jgn port authorities need 14 days quarantine after inspection to government appointed hotel waiting 14 days.
124	Chennai, India	Chevron	04-Apr	other - complete lockdown due to COVID19
125	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
126	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
127	Chiba, Japan		22-Apr	Not allowed due to COVID-19 restrictions
128	Chirique Grande, Panama	-	21-Jun	According to local agent, SIRE inspections are not allowed due to COVID 19.
129	Chiriqui Grande, Panama		16-Apr	Not possible due to COVID-19 restrictions
130	Chiriqui Grande, Panama	P66. Equinor	30-Apr	Not possible due to COVID 19 travel restrictions. No local inspector.
131	Chittagong	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
132	Chittagong, Bangladesh	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
133	Chittagong, Bangladesh	BP	Apr	Terminal not allowing to board BP vetting inspector due to restriction.
134	Chittagong, Bangladesh	EQUINOR	12-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
135	Chittagong, Bangladesh	MAXCOM	11-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
136	Ciudad Madero, Mexico	Equinor	20-Apr	Due to the COVID-19 travel restrictions (Lock Down)
137	Coassa, Panama	All	10-May-20	Terminal under security level 2 – no visitor/inspector allowed due to Covid-19.
138	Coatzacoalcos, Mexico	EQUINOR	06-Apr	Covid 19 - travel restrictions
139	Coazacoalcos, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
140	Coazacoalcos, Mexico			Do not allow inspectors onboard.
141	Coega Bay, South Africa	Equinor	15-May	Local inspector unavailable. (Covid-19 related)
142	Conarky, Guinea	Lukoil, Alma	29-Mar	
143	Concepcion Bay, Chile	CHEVRON	10-Apr	Not able to attend due the new restriction during easter holidays, travel problems due to COVID19. At this time the inspection is now cancelled.
144	Concepcion Bay, Chile	CHEVRON	11-Apr	Regret we will not be able to attend this one due the new restriction during easter holidays, travel problems due to COVID19. Thank you very much for your help, at this time the inspection is now cancelled.
145	Conchan, Peru	CHEVRON	17-Mar	Peruvian Government has restricted citizens' movement within their homes and closed international travel with effect from 16 March to 1 April.

146	Conchan, Peru	REPSOL	18-Mar	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
147	Conchan, Peru	Any OM	15-Jun	Foreign Inspector travel ban. Airports closed due Emergency declared till June 30th.
148	Corpus Christi, USA	Koch	15-May	Covid 19 - travel restrictions
149	Corpus Christi, USA	Equinor	25-May	Personal issues with the inspector
150	Coruna, Spain	Cepsa	29-Apr	Only at their terminals at Huelva, Tenerife and Algeciras
151	Cotonou, Benin	CDI	17-Mar	Local inspector unavailable. (Covid-19 related)
152	Cotonou, Benin	CDI	21-Mar	Local inspector unavailable. (Covid-19 related)
153	Cotonou, Benin	Lukoil	16-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
154	Cotonou, Republic of Benin	Agent	07-May	Covid 19 - travel restrictions
155	Covenas, Colombia	NA	15-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19. (ADVISED THROUGH AGENT)
156	Covenas, Columbia		16-Apr	Not possible due to COVID-19 restrictions
157	Covenas, Columbia	ENOC	18-Apr	Permission not granted by terminal due to COVID-19 restrictions
158	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice
159	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
160	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
161	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice. Exception is if the inspector is a local, however permission is required.
162	Cristobal, Panama		27-Mar	Travel restriction
163	Daesan, SK	TOTAL	05-Apr	Declined due to unavailability of inspectors
164	Daesan, SK	Total	31-May	Terminal prohibited any job other than cargo operation at berth. The same was explained you earlier and we have arranged his on / off schedule at the anchorage. However, the vessel's ETB delayed several hours again today as the terminal changed our vessel's jetty. And the inspector suddenly informed that he should cancel the inspection.
165	Daesan, SK			Not permitted by terminal
166	Daesan, SK	ENOC	12-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
167	Daesan, SK	IMT & BP	14-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
168	Dahej, India		01-May	Agents information due to terminal restrictions and lock-down
169	Dakar, Primorsk Oil Terminal, Senegal		10-Jun	Due to COVID restrictions, our inspectors are unable to reach Dakar and carry out the inspection onboard the vessel

170	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
171	Dakar, Senegal	Maxcom	14-Apr	Covid 19 - travel restrictions
172	Dakar, Senegal	ENOC, BHP, agents	13-Apr	Covid 19 - travel restrictions
173	Dakar, Senegal	Koch, Aethon, Total	13-Apr	Covid 19 - travel restrictions
174	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
175	Dalian, PRC			
176	Dalian, PRC		13-May	As per agents - not allowed
177	Dalian, PRC	Shell, Chevron	27-May	Terminal restrictions; local inspectors only
178	Dalian, PRC	KOCH	24-26-Jun	Covid-19 restrictions
179	Dapeng, PRC	MMS	07-May	Visitor enter terminal must stay in this city "Shenzhen" longer than 14 days; Visitor should need Nucleic acid test of COVID-19 3 days before ship arrival, then we can make the application; Terminal will consider to approve or not base on Customs' quarantine pre examination on the vessel about 2-3 days before ship arrival(base on vessel's port calls records, crews conditions etc.
180	Dominican Republic	P66	13-Apr	Due to the COVID-19 travel restrictions
181	Dominican Republic	Lukoil	13-Apr	Due to Dominican Republic is locked down
182	Donges, France	Enoc	23-May	OM - Regret due to COVID 19 we cannot attend this vessel.
183	Donges, France	P66	23-May	Unfortunately due to COVID 19, there are travel or terminal restrictions in the location you requested this inspection to be conducted in
184	Dongguan, PRC	any OM	03-Apr	Covid 19 - country lock down
185	Dongguan, PRC	BHP	18-Apr	Dongguan Immigration is not allowed the SIRE inspector to visit ship for this calling due to Dongguan got two confirmed COVID-19 cases in last week which from foreign ships.
186	Dongguan, PRC	BHP	22-Apr	We do not have available inspectors at the moment due to various virus restrictions and will decline inspections.
187	Dongguan, PRC	Shell	19-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
188	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Inspection at the moment yet.
189	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Inspection at the moment yet.
190	Dongguan, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
191	Dongguan, PRC	Agent	25-Jun	
192	Dongjiakou, {PRC	BHP	25-May	Covid 19 - travel restrictions
193	Dongjiakou, PRC			
194	Dongjiakou, PRC	Maxcom	07-Apr	Terminal is closed as per covid 19 restrictions
195	Dongjiakou, PRC	MAXCOM	07-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
196	Dongjiakou, PRC	Chevron	10-Apr	Plan 17/04/2020 - Chevron do not schedule SIRE inspection at China port at the moment.
197	Dongjiakou, PRC	Shell	10-Apr	Plan 17/04/2020 - Rejected due to COVID-19
198	Dongjiakou, PRC	KOCH	24-26-Jun	Covid-19 restrictions
199	Dongying, PRC	EQUINOR	20-May	Covid 19 - travel restrictions
200	Dongying, PRC	BHP	21-May	Covid 19 - travel restrictions

201	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
202	Dongying, PRC	ENOC	23-May	Covid 19 - travel restrictions
203	Dongying, PRC	Maxcom	21-May	Covid 19 - travel restrictions
204	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
205	Douala, Cameroon			Terminal not allowed or non-availability of any local inspector due COVID – 19
206	Douala, Cameroon	Gazprom,Total	01-Jun	Lockdown due to COVID19 - no local inspectors available
207	Dumai, Indonesia	BHP, Neste oil	05-Jun	Due to COVID-19 travel restrictions
208	Durban, South Africa	Shell	26-Mar	
209	Durban, South Africa	Shell	24-Mar	Covid 19 - country lock down
210	Durban, South Africa	Shell	26-Mar	Covid 19 - country lock down
211	El Segundo, California, USA		22-Apr	no visitor/inspector allowed due to Covid-19
212	El Segundo, USWC	Chevron, P66	21-May	Terminal change policy – visitor/inspector allowed due to Covid-19.
213	El Segundo, USWC	Chevron		Terminal does not permit
214	El Segundo, USWC	P66	09-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19. (Terminal belong to Chevron and operator requested them to inspect - tbc)
215	Ennore, India	Shell	04-Jun	Planned: Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections in India until further notice.
216	Ennore, India	ENOC	05-May	Terminal rejection of the inspector
217	Fawley, UK	EXXON	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
218	Fawley, UK			
219	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March: Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
220	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March: Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
221	Fawley, UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
222	Fawley,UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
223	Fortaleza, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
224	Fos, France			Member reported info from agent, now possible to do inspection
225	Fos, France	TOTAL & OMV	23-May	Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling. We have just received the answer from the last Inspector, unfortunately, he is not available. In view of the above, we are force to postpone the inspection.

226	Freeport , USA	P66	25-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
227	Freeport ,USA	P66	25-Apr	Planned - Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
228	Freeport, Bahamas		10-Apr	Due to Lockdown
229	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
230	Fujairah, UAE	SHELL	22-Apr	Due to launch required for boarding
231	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
232	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
233	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
234	Gabes, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions
235	Galveston Offshore lightering area	Chevron	24-Apr	Unavailability of inspector for this inspection
236	Ganyu, PRC	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
237	Gdansk, Poland	ENOC, KOCH	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
238	Geismar, USA	Conocophillips	27-Mar	OM advised they have cancelled due to COVID 19
239	Geismar, USA	Equinor	27-Mar	Equinor did not have inspector due to COVID 19
240	Gemlik, Turkey	CDI	09-Apr	Local inspector unavailable.
241	Geoje, SK		01-Jun	Not allowed by terminal
242	Ghent, Belgium	Neste	14-Apr	Due to corona restrictions within the Company
243	Gijón, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
244	Gizan, Saudi Arabia	Aramco	15-Jun	No third party attendance possible due to the security reasons. Aramco declined due to travel restrictions.
245	Goeje Yard, SK	PETROBRAS	21-May	Planned: Due to the outbreak of the COVID-19, currently we are not performing SIRE inspections in any port of the world
246	Guam, USA	BP,CHEVRON,P66,GAZPROM	10-Apr	Travel restrictions 14 days quarantine resulted to no inspectors available
247	Guam/Saipan, USA			Terminal not allowed or non-availability of any local inspector due COVID – 19
248	Guayanilla, Puerto Rico		16-Apr	Not possible due to COVID-19 restrictions
249	Guaynilla, Puerto Rico		20-May	Not possible as no local inspector and no flights operating to the island

250	Gulei, PRC		22-Mar	Due to COVID-19 not permitted by terminal
251	Gulei, PRC	Maxcom	09-May	Terminal restrictions
252	Gulei, PRC	ENOC	May-20	Terminal change policy – no visitor/inspector allowed due to Covid-19.
253	Hadera, Israel	Repsol	22-May	"Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception"
254	Hadera, Israel	Rightship, Total	22-May	Local inspector unavailable. (Covid-19 related)
255	Haldia, India		Apr	Terminal informed they will not allow vetting inspector to board due to restriction. India under lockdown.
256	Haldia, India	Idemitsu	04-May	India Lock down.
257	Haldia, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
258	Hamriyah, UAE	P66	Apr	Terminal did not allow BP vetting inspector to board due to COVID 19 restriction
259	Hazira, India	Rightship	01-Apr	country under lockdown - travelling prohibited within country
260	Hong Kong, PRC			
261	Honninggsvag, Norway	BP	03-Apr	Due the COVID-19 there is borders restriction to any non-residents (except for transit passengers).
262	Honninggsvag, Norway			
263	Honolulu, USA	SHELL	25-May	Travel restriction imposed in the country due to COVID 19.
264	Houston, USA	Equinor	Mar	Master has raised concerns about safety & health of the crew and has requested for deferring the inspection so as to avoiding/limit contact with visitors to the bare minimum. Tech. Manager agreed and postponed inspection.
265	Houston, USA	REPSOL	05-Apr-20	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
266	Houston, USA	Repsol	13-Apr	
267	Houston, USA	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
268	Houston, USA	Repsol	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
269	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-22
270	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-24
271	Huangdao, PRC	KOCH	24-26-Jun	Covid-19 restrictions

272	Huelva, Spain			Imposed restrictions
273	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
274	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected, Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
275	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
276	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected. Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
277	Huelva, Spain		18-May	Not possible due to COVID-19 restrictions in port.
278	HuiZhou, PRC	Shell	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
279	Huizhou, PRC	P66	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
280	Huizhou, PRC	Petron	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
281	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April. Equinor do not have any available Inspector at Iceland due to COVID-19
282	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April: Equinor do not have any available Inspector at Iceland due to COVID-19
283	Ilo, Peru	Total	09-Jun	Due to the unavailability of an inspector in the port
284	Ilo, Peru	P66	08-Jun	Due to the COVID-19 travel or terminal restrictions
285	Immingham, UK	Ineos, Borealis, Shell	12-Apr	Local inspector unavailable. (Covid-19 related)
286	Incheon, SK			Not permitted by terminal
287	Iskendrun, Turkey		29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
288	Itaqui, Brazil	BHP	17-Apr	We regret will not be able to cover vessel's inspection.
289	Itaqui, Brazil	ENOC	17-Apr	Regret due to COVID 19 travel restrictions we are unable to attend the vessel.
290	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.

291	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.
292	Itaqui, Brazil	BP	24-May	OM - our inspectors are unable to cover Itaqui as the city it falls in Sao Luis is in lockdown
293	Itaqui, Brazil	Maxcom	24-May	OM- Much to our regret we can't cover as per Covid restrictions
294	Jasaan, Philippines	P66/BHP/Petron	28-May	No domestic flights available.
295	Jebel-Ali, UAE	Equinor	14-Apr	Inspection rejected - due to Hamriyah Terminal Restriction Not Allowed (COVID-19 pandemic).
296	Jebel-Ali, UAE	BP	11-Apr	Vessel had berth at SOET terminal, where SIRE Inspection are not permitted at COVID 19.
297	Jeddah, Saudi Arabia	BIECO	22-Apr	Terminal restriction
298	Jeddah, Saudi Arabia	Lukoil	26-Apr	Terminal restriction
299	Jeddah, Saudi Arabia	Any OM	09-Jun	Aramco Jeddah restricts to conduct any kind of inspection on their Terminals.
300	Jiangsu, PRC		27-Apr	Terminal restrictions
301	Jiangyin, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
302	Jiangyin, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
303	Jiangyin, PRC	P66	03-Jun	COVID 19 travel or terminal restrictions in the location you requested this inspection to be conducted in.
304	Jisan, Saudi Arabia	Total, ENOC, AMPOL	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
305	JNPT India	Idemitsu	05-Jun	Dy. Conservator JNPT not allowing any inspection at JNPT.
306	Jorf Lasfar, Morocco			Terminal not allowed or non-availability of any local inspector due COVID – 19
307	Jorf Lasfar, Morocco	CDI	Early March	CDI was postponed on the beginning of March intentionally. Planning was to perform CDI under new management after takeover in discharging port. Takeover plans were postponed due to COVID and therefore CDI inspection too.
308	Jorf Lasfar, Morocco	CDI	26-Mar	Local inspector unavailable. No inspector available due to COVID.
309	Jorf Lasfar, Morocco	SIRE	03-Apr	Other (National Lockdown - Travel restriction)
310	Jorf Lasfar, Morocco	Total, Shell, Borealis, Rightship, Equinor, Adnoc	04-May	Local inspector unavailable. (Covid-19 related)
311	Jorf Lasfar, Morocco	Lukoil	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. (local inspector available and appointed)
312	Jorf Lasfar, Morocco	CDI	06-May	Local inspector unavailable. (Covid-19 related)
313	Jorf Lasfar, Morocco	SIRE	05-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
314	Jorf Lasfar, Morocco	CDI	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
315	Kaarsto, Norway	Chevron, IMT	04-Jun	Inspector unavailability
316	Kakinada, India	CDI	24-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
317	Kakinada, India	EQUINOR	06-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

318	Kakinada, India	BP	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
319	Kakinada, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
320	Kalundborg, Denmark	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
321	Kandla, India	Rightship, Adnoc, Total, Shell, Bienco	25-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
322	Kandla, India	Adnoc, Total, Shell, Bienco	28-Apr	Local inspector unavailable. (Covid-19 related)
323	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
324	Kaohsiung, Taiwan	Valero	17-Apr	Covid 19 - travel restrictions
325	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
326	Kaohsiung, Taiwan	Gazprom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
327	Kaohsiung, Taiwan	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
328	Kaohsiung, Taiwan	Petron	18-Apr	Local inspector unavailable. (Covid-19 related)
329	Kaohsiung, Taiwan	Equinor	26-Jun	Due to the COVID-19 travel restrictions and local inspector unavailable.
330	Kaohsiung,Taiwan	ENOC	Apr-20	Inspector can not enter Taiwan due to restriction of entry policy for control of Covid 19
331	Kaohsiung,Taiwan	Idemitsu, Shell, BHP	March	Inspection not allowed by Terminal due to COVID – 19
332	Kaoshiung, Taiwan	SHELL, BP, CHEVRON, ENOC	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19 unavailable. (Covid-19 related)
333	Kaoshiung, Taiwan	ENOC	20-Apr	Local inspector unavailable. (Covid-19 related)
334	Kaoshiung, Taiwan	BHP	17-May	Travel restriction imposed in the country due to COVID 19.
335	Kaoshiung, Taiwan	Idemitsu	17-May	Travel restriction imposed in the country due to COVID 19.
336	Karachi, Pakistan	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
337	Karachi, Pakistan.	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
338	Karratha, Australia	BP	01-May	Terminal restrictions
339	Karratha, Australia	BP	01-May	Terminal restrictions
340	Karsto, Norway	CDI	15-Apr	Local inspector unavailable. (Covid-19 related)
341	Karsto, Norway	CDI	15-May	Local inspector unavailable. (Covid-19 related)
342	Kawasaki, Japan	SHELL	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
343	Kawasaki, Japan	P66	30-Apr	Travel/border restrictions being imposed due to COVID-19
344	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
345	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
346	Kingston,Jamaica		25-May	Not possible due to COVID-19 restrictions and country is under lockdown.
347	Klaipeda, Lithuania	BHP / P66 / Chevron	06-Jun	Due to COVID-19 travel restrictions
348	Koper , Slovenia	Q8	Feb-20	Restriction due to Covid 19
349	Kotka, Finland	Preem, Lukoil, Koch	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19;

				Local inspector unavailable. (Covid-19 related)
350	Kozmino, Russia	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
351	Kuantan, Malaysia	Gazprom	02-Apr	All hotels closed therefore inspector who was driving 6 hours refused to attend - only local inspectors allowed as there are travel restrictions
352	Kwinana, Australia	BP	01-Apr	Terminal restrictions
353	Kwinana, Australia	Chevron	15-Apr	Covid 19 - travel restrictions
354	Kwinana, Australia	BHP	26-May	Panned: Until further notice all non-essential and non- cargo operation visits such as SIRE inspections and routine technician visits will not be permitted during STS operations or when vessels are alongside the refinery jetties.
355	Kwinana, Australia	IMT	28-Jun	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
356	Kwinana, Australia	IMT	24-May	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
357	Kwinana, South Africa	IMT	28-Jun	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
358	La Libertad, Ecuador	Lukoil, Equinor, Rightship, BP, Koch	03-Apr	Local inspector unavailable. (Covid-19 related)
359	La Pampilla, Peru	IMT, Repsol, YPF, Sonangol, Maxcom, Gazprom, Phillips66, Shell	31-Mar	
360	La Pampilla, Peru	IMT	31-Mar	Covid 19 - travel restrictions
361	La Pampilla, Peru	Repsol	31-Mar	Covid 19 - travel restrictions
362	La Pampilla, Peru	YPF	31-Mar	Covid 19 - travel restrictions
363	La Pampilla, Peru	Sonangol	31-Mar	Covid 19 - travel restrictions
364	La Pampilla, Peru	Maxcom	31-Mar	Covid 19 - travel restrictions
365	La Pampilla, Peru	PMI	01-Apr	Covid 19 - travel restrictions
366	La Skhira, Tunisia			Terminal not allowed or non-availability of any local inspector due COVID – 19
367	Lagos, Nigeria	ENOC	10-Apr	Local inspector unavailable. (Covid-19 related)
368	Lagos, Nigeria	Total	28-Apr	Not inspecting in Africa currently
369	Lagos, Nigeria	Nobody invited as informed by Agents	04-Apr	other - complete lockdown due to COVID19
370	Las Minas, Panama	BHP	27-May	Local inspector unavailable. (Covid-19 related)
371	Las Minas, Panama	BHP	27-May	A local inspector is unavailable. (Covid-19 related)
372	Las Palmas, Spain	ENOC	24-Apr	Covid 19 - travel restrictions
373	Las Palmas, Spain	CEPSA	24-Apr	Covid 19 - travel restrictions
374	Las Palmas, Spain	Repsol	27-Apr	Covid 19 - travel restrictions
375	Las Palmas, Spain	Cepsa	30-May	MOC is not authorized to perform inspections outside Cepsa Terminals at Huelva, Algeciras or Tenerife.
376	Las Palmas, Spain	Repsol	01-Jun	Repsol does not inspect any vessel except special situations due to Covid-19
377	Lavera, France	KOCH	06-Apr	Not be able to plan the attendance due to COVID 19 travel restrictions

378	Lavera, France	BHP	06-Apr	Do not have available inspectors due to present virus situation. Flight and transport restriction beyond our control
379	Lavera, France	CDI	24-Apr	Travel restriction.
380	Lavera, Portugal	POT	10-Apr	Others - Due to COVID-19, POT do not inspect vessels temporarily.
381	Lavera, Portugal	GAZPROM	10-Apr	Local inspector unavailable.
382	Lavera, Portugal	P66	09-Apr	Local inspector unavailable.
383	Lavera, Portugal	ENOC	09-Apr	Local inspector unavailable.
384	Lavera, Portugal	BHP	06-Apr	Local inspector unavailable.
385	Lavera, Portugal	KOCH	06-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period.
386	Le Havre, France	CDI	25-Mar	Tech. manager decided to do not proceed with inspection in France to do not put crew in unnecessary risk – requested for CDI validity extension (successfully).
387	Le port, Reunion			Terminal not allowed or non-availability of any local inspector due COVID – 19
388	Leixioes, Portugal	Maxcom	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
389	Lianyungang , PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
390	Lianyungang , PRC	P66	03-May	No inspector available due to COVID-19 travel/border restrictions
391	Lianyungang, China	CDI, Xinrongtai	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
392	Lianyungang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
393	Lianyungang, PRC	Maxcom, ALMA	14-Apr	Covid 19 - travel restrictions
394	Lianyungang, PRC	BHP, Lukoil	14-Apr	Covid 19 - travel restrictions
395	Lianyungang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
396	Lianyungang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
397	Lianyungang, PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
398	Lianyungang, PRC	SHELL	03-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
399	Lianyungangn, PRC	All Majors/CDI	24-Apr	Terminal does not permit inspections due to COVID-19
400	Libreville, Gabon	CDI	March	Inspection not allowed by Terminal due to COVID – 19
401	Limay, Phillipines	IMT	01-Apr	Due to COVID-19 not permitted by terminal
402	Limbe, Cameroon	Shell, Enoc	05-Feb	Local inspector unavailable.
403	Limbe, Cameroon	BP, Maxcom	25-Mar	Inspection cancelled , due to Lockdown and restricted movement by air, road, etc
404	Limetree Bay, US Virgin Islands	P66	17-Apr	Due to the COVID-19 travel restrictions (Lock Down)
405	Lisbon, Portugal	BP	09-May	Understand from our inspectors in the region that Portugal borders are closed till at least 15th May and likely to be extended to June.
406	Lome OPL, Togo	Agent	14-May	Covid 19 - travel restrictions
407	Lome OPL, Togo	Agent	15-May	Covid 19 - travel restrictions
408	Lome OPL, Togo	Alma	15-May	Covid 19 - travel restrictions
409	Lome, Togo	Shell	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
410	Lome, Togo	Lukoil	22-Apr	Lome is locked down
411	Lome, Togo	CDI	16-Mar	Local inspector unavailable. (Covid-19 related)
412	Lome, Togo	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)

413	Lome, Togo	ENOC	27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
414	Lome, Togo	P66	19-Jun	Local inspector unavailable. (Covid-19 related)
415	Long Beach, CA, USA	Shell	30-Mar	Cancelled
416	Loop, USA	Lukoil, ENOC,Maxom	24-Mar	
417	Loop, USA	Lukoil	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
418	Loop, USA	ENOC	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
419	Loop, USA	Maxcom	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
420	Loop, USA	PHILLIPS 66	12-Apr-20	There are travel restrictions in the region. To submit a new inspection request once next berthing orders are known and OM will try to accommodate inspection request.
421	Loop, USA	PHILLIPS 66	12-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
422	Loop, USA	Exxon	14-May	Unable to attend
423	Louisiana, USG	Marathon		Cancelled
424	Luanda, Angola	BHP , Maxcom, P66	13-Mar	Complete lockdown due to COVID19
425	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
426	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
427	Luanda, Angola	Chevron	03-Jun	Covid 19 - travel restrictions
428	Lubuk Guang, Indonesia	P66	18-Jun	Terminal change policy – visitor/inspector need 14 days quarantine due to Covid-19.
429	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
430	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
431	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
432	Mailiao, Taiwan			
433	Mailiao, Taiwan	CDI	29-Mar	Local inspector unavailable. (Covid-19 related)
434	Malta	Lukoil	16-Apr	Due to Malta is locked down
435	Malta	ENOC,Koch, BIECO	27-Apr	Malta is Locked down, local inspector unavailable
436	Malta	IMT/SHELL/TOTAL	15-May	Malta in lockdown due to COVID
437	Malta	NA	05-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19. (ADVISED THROUGH AGENT)
438	Mamonal, Colombia	CHEVRON	15-Apr	Regret to inform that we do not have an inspector available for this inspection
439	Mamonal, Colombia	LUKOIL	15-Apr	Please be informed that due to terminal restrictions inspection cannot be arranged at Mamonal.
440	Mamonal, Colombia	PHILLIPS 66	15-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
441	Manaus, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
442	Mangalore, India	Idemitsu	17-May	Others

443	Manzanillo, Mexico	P66, Shell	April	Inspection not allowed as interstate travel is restricted due to Covid 19
444	Manzanillo, Mexico	P66	14-Apr	Inspection declined due to COVID -19
445	Manzanillo, Mexico	ENOC	14-Apr	Inspection declined due to COVID -19
446	Manzanillo, Mexico	P66	14-Apr	due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
447	Manzanillo, Mexico	Equinor	14-Apr	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available to cover this request at the moment.
448	Manzatlan, Mexico	Shell, Chevron, Maratthon, P66	10-Apr	Due Covid-19 sanction.
449	Map Ta Phut, Thailand	IMT	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
450	Map Ta Phut, Thailand	SHELL	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
451	Map ta Phut, Thailand	Lukoil	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
452	Map Ta Phut, Thailand	Agent	04-May	Covid 19 - travel restrictions
453	Map Ta Phut, Thailand	MMS	28-May	The current situation due to COVID-19 outbreak, PTTLNG terminal not allow to do sire inspection ,Please find attached PTTLNG's guideline for COVID-19 restriction for reference. Noted : The Civil Aviation Authority of Thailand (CAAT) has announced an extension of temporary ban on all international passenger flights to Thailand until 30 June 2020.
454	Map Ta Phut, Thailand	Shell, BP	07-Jun	Local inspector unavailable. (Covid-19 related)
455	Map Ta Phut, Thailand		1-8 Apr	
456	Maptaphut, Thailand	PTT	07-May	According to the "State of Emergency" declaration in Thailand and limitations of Terminal access granted in related to COVID-19 pandemic. PTT Inspection will not be able to assign during this period. Expected the situation will be released by end of this month.
457	Maptaphut, Thailand	Agents	14-Jun	Lockdown due to COVID19 - terminal restrictions also apply not even local inspectors allowed
458	Map-Ta-Phut, Thailand			Terminal not allowed or non-availability of any local inspector due COVID – 19
459	Maptaphut, Thailand	Agents	16-Jun	Lockdown due to COVID19 - terminal restrictions also apply not even local inspectors allowed
460	Maputo, Mozambique	Lukoil	07-Apr	COVID-19 – traveling restrictions. No local inspector available.
461	Maputo, Mozambique	P66	07-Apr	COVID-19 – traveling restrictions. No local inspector available.
462	Maputo, Mozambique	MAXCOM	07-Apr	COVID-19 – traveling restrictions. No local inspector available.
463	Maputo, Mozambique	ENOC	07-Apr	COVID-19 – traveling restrictions. No local inspector available.
464	Maputo, Mozambique	ENOC	14-Apr	COVID-19 – traveling restrictions. No local inspector available.

465	Maputo, Mozambique	Agenta	23-May	Covid 19 - travel restrictions
466	Marcus Hook, USA	CDI	13-Mar	Nominated inspector declined to attend due to COVID
467	Marcus Hook, USA	CDI	31-Mar	No inspector available due to travel restrictions caused by COVID spread. Local inspector unavailable.
468	Marmara, Turkey			Terminal not allowed or non-availability of any local inspector due COVID – 19
469	Marmara, Turkey	IMT, BP, TOTAL, CHEVRON, SHELL.	10-Apr	Terminal lock down
470	Matosinhos, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
471	Mazatlan, Mexico		10-Apr	No local inspectors available
472	Mazatlan, Mexico	Chevron	15-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
473	Mazatlan, Mexico	PMI	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
474	Mazatlan, Mexico	Enoc	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
475	Mazatlan, Mexico	IMT	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
476	Mazatlan, Mexico	Shell	08-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
477	Mazatlan, Mexico	BHP	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
478	Mazatlan, Mexico	Total	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
479	Mejillones, Mexico	CDI	12-May	Local inspector unavailable. (Covid-19 related)
480	Melbourne, Australia	BHP	March	Inspection not allowed by Terminal due to COVID – 19
481	Merak, Indonesia	PHILLIPS66	13-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
482	Merak, Indonesia	ENOC	02-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
483	Merak, Indonesia	ENOC	07-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
484	Mesaieed, Qatar	Shell	19-May	OM - We regret we are unable to carry out the inspection at this time. We do not have any local inspectors available
485	Mesaieed, Qatar	BP	19-May	OM - our inspectors in the region are unable to make it due to travel restrictions in place for COVID-19 pandemic.

486	Mesaieed, Qatar	IMT	22-May	OM - Due to COVID-19 pandemic worldwide , with travel/border restrictions being imposed in many countries, we regret to inform that we are currently unable to arrange as your request.
487	Mesaieed, Qatar	TOTAL	22-May	OM - Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling.
488	Midia, Romania	All Majors/CDI	01-May	Inspections are not possible in Romania due to travel restrictions due to COVID-19 pandemic
489	Milazzo , Italy	ENI	1-8 Apr	
490	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
491	Mina Al Ahmadi, Kuwait	IMT	12-Apr	country under lockdown - travelling prohibited within country
492	Mina Al Ahmadi, Kuwait	CDI	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
493	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
494	Mina Al-Ahmadi, Kuwait	KOCH	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
495	Mina Al-Ahmadi, Kuwait	ENOC	10-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
496	Mina Al-Mahadi, Kuwait	BHP	06-May	Unfortunately the UAE /Gulf countries have not yet provided a clear indications as to when flights will resume. In that regards, visas too will not be issued.
497	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
498	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
499	Mobile, Alabama	Koch	02-Apr	Declined inspection as no inspector available. Likely due to COVID19
500	Mobile, Alabama	Lukoil	10-Apr	Inspector could not make in time due to delay at travel checkpoints en route
501	Mohammedia, Morrocco	CDI	26-Apr	Local inspector unavailable. (Covid-19 related)
502	Mombasa, Kenya	BHP	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
503	Monroe Terminal, Philadelphia, USEC			Not permitted as vetting considered non essential
504	Monteverde, Portugal	P66, ConocoPhillips	01-Apr	Local inspector unavailable. (Covid-19 related)
505	Montoir, France			
506	Morocco	All Majors/CDI	10-Apr	Morocco is locked down due to COVID-19 and no inspections can be arranged
507	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
508	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
509	Muara, Brunei	ENOC	11-Jun	Covid 19 - travel restrictions
510	Muara, Brunei	BHP	11-Jun	Covid 19 - travel restrictions
511	Mumbai - JNPT, India	ENOC	03-Apr	Not possible due to COVID-19 Restrictions lockdown
512	Mumbai, India	Chevron	07-Apr	Travelling restrictions
513	Mumbai, India	Phillips 66	12-Apr	Complete lockdown in India due to COVID 19. No public or private transportation's are available.
514	Mumbai, India	ENOC	25-Apr	Covid 19 - travel restrictions
515	Mumbai, India	Lukoil	24-Apr	Covid 19 - travel restrictions

516	Mumbai, India	EQUINOR	15-May	Inspector while trying to attempt to go onboard the subject vessel for conducting SIRE inspection, he was unable to embark the vessel due to excessive swell (embarking on Eagle Victoria was aborted after making several attempts to board the vessel).
517	Mundra, India	Chevron	06-Apr	Travelling restrictions
518	Murmansk, Russia	SHELL	29-Apr	Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections Russia until further notice.
519	Murmansk, Russia	GAZPROM	28-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
520	Murmansk, Russia	LUKOIL	24-Apr	As per agents quarantine isolation for two weeks is imposed at airport for the passengers arriving from Moscow.
521	Murmansk, Russia	LUKOIL	22-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
522	Murmansk, Russia	TOTAL	18-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
523	Naantali, Finland	LUKOIL	25-Mar	E-mail from LUKOIL 23 March: We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.
524	Naantali, Finland	LUKOIL	#####	E-mail from LUKOIL 23 March: We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.
525	Nanjing, PRC	Shell, Preem	15-Apr	Local inspector unavailable. (Covid-19 related)
526	Nanjing, PRC	ConocoPhillips	15-Apr	All inspections paused due to Covid-19
527	Nanjing, PRC	CDI	06-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
528	Nansha, PRC	Shell	30-Mar	
529	Nansha, PRC	Shell	30-Mar	Covid 19 - terminal restrictions
530	Nantong, PRC	P66	27-Apr	Port authorities imposed 14 days quarantine for inspectors after inspection
531	Nantong, PRC	Lukoil	06-Jun	Covid 19 - travel restrictions
532	Nantong, PRC	IMT	24-Jun	OM - Due to current COVID-19 pandemic situation worldwide , we regret to inform that we are currently unable to arrange as your request.
533	Nantong, PRC	IMT	24-Jun	OM- Due to current COVID-19 pandemic situation worldwide , we regret to inform that we are currently unable to arrange as your request
534	Napier, France	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
535	Napier, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
536	Napier, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
537	New plymouth, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
538	New plymouth, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)

539	New Plymouth, New Zeland	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
540	New York, USA			
541	New York, USA	Lukoil	25-Apr	Lukoil cancelled the inspection due to COVID-19.
542	Newcastle, Australia	IMT	Apr	Due to current rapidly increasing severity of COVID-19 pandemic worldwide and with travel/border restrictions being imposed in many countries, we regret to inform you that we are unable to arrange as your request for the subject vessel.
543	Newcastle, Australia			Terminal not allowed or non-availability of any local inspector due COVID – 19
544	Newyork / US	Total	14-Apr	Due to the unavailability of an inspector in the port
545	Ningbo, PRC	Koch	02-Apr	Terminal not allowed any visitors due to Covid-19
546	NingBo, PRC	Petron	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
547	NingBo, PRC	EQUINOR	03-Apr	Due to COVID-19 not permitted by terminal
548	Ningbo, PRC	BP	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
549	Ningbo, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
550	Ningbo, PRC	Lukoil	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
551	Ningbo, PRC		25-May	COVID-19 restrictions
552	Nipah, Indonesia	IMT, Lukoil, Shell, BP, Maxcom	10-Apr	No inspectors available.
553	Nipah, Indonesia	Idemitsu	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
554	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-23
555	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-25
556	Ocoa Bay, Dominican Republic	All Majors	03-Apr	No local inspectors available in Dominican Republic
557	Omoa, Honduras	Equinor, KOCH	07-May	No available local inspectors; travelling restrictions
558	Onsan, SK		20-Mar	Due to COVID-19 not permitted by terminal
559	Onsan, SK	Shell	March	Inspection not allowed by Terminal due to COVID – 19
560	Ornskoldsvik, Sweden	Lukoil	29-Apr	Declined due to COVID-19 travel restrictions
561	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
562	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
563	Pajaritos, Mexico	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
564	Pajaritos, Mexico	Lukoil	05-May	Not Inspected. Terminal don't allow the permission for Vetting inspector.
565	Panama			Local restriction
566	Panama	BHP		Not permitted as didn't have local presence.
567	Panama	GAZPROM	09-Mar	Not permitted
568	Paradip, India		1-8 Apr	
569	Paradip, India	N/A	09-Apr	Other (National Lockdown - Travel restriction)
570	Paradip, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
571	Paranagua, Brazil			Imposed restrictions

572	Paranagua, Brazil	Equinor, P66, Koch, Shell	01-Apr	Local inspector unavailable.
573	Paranagua, Brazil	Equinor	03-Apr	Local inspector unavailable. (Covid-19 related)
574	Pasir Gudang, Malaysia	Petron	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic
575	Pembroke, UK	EQUINOR	22-May	Planned: According to information received from agent, terminal does not allow inspections to be carried out due to restrictions in force.
576	Pengerang, Malaysia		08-Apr	Due to COVID-19 not permitted by terminal
577	Pengerang, Malaysia	Petronas	14-Apr	MMS does not allow inspector to stay overnight on vessel, As per terminal, inspector to board prior berthing and disembark upon departure from terminal
578	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-19
579	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-20
580	Peru	Repsol	24-Apr	Covid 19 - travel restrictions
581	Philippines	All Majors/CDI	29-May	Information: Inspections not permitted in Phillipines due to COVID-19 pandemic. All foreigners arriving Phillipines need to serve 14 days quarantine period.
582	Pinkenba, Australia			
583	PISCO	KOCH	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
584	Pisco, Peru	EXXON	11-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
585	Point Comfort, USA	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)
586	Point Lisas, Trinidad & Tobago	Lukoil, Savonetta, SP#2 South & SP#4	30-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
587	Point Lisas, Trinidad & Tobago	CDI	21-Apr	Local inspector unavailable. (Covid-19 related)
588	Point Lisas, Trinidad & Tobago	Lukoil, Shell, Rightship, Equinor	10-Apr	Local inspector unavailable. (Covid-19 related)
589	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
590	Point Lisas, Trinidad & Tobago	CDI	05-Apr	Local inspector unavailable. (Covid-19 related)
591	Point Lisas, Trinidad & Tobago	CDI	25-Apr	Local inspector unavailable. (Covid-19 related)
592	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
593	Point Lisas, Trinidad and Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
594	Point Lisas, Trnindad and Tobago	All Majors	03-Apr	No local inspectors available in Point Lisas and airport closed down till further notice.
595	Port Allan, USA	EQUINOR	24-Apr	Covid 19 - travel restrictions
596	Port Allan, USA	ENOC	27-Apr	Covid 19 - travel restrictions
597	Port Dickson, Malaysia	Idemitsu	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic .
598	Port Dickson, Malaysia	CDI	16-Apr	lockdown due to COVID19 - Foreign inspectors not allowed to travel to Malaysia
599	Port Elizabeth, South Africa		16-Apr	no visitor/inspector allowed due to Covid-19
600	Port Elizabeth, South Africa	CDI	04-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
601	Port Esquivel, Jamaica	BHP	30-Mar	
602	Port Esquivel, Jamaica	BHP	30-Mar	Covid 19 - travel restrictions

603	Port Esquivel, Jamaica	Maxcom	01-Apr	Covid 19 - travel restrictions
604	Port Everglades, USA	ENOC	24-Apr	Local inspector unavailable. (Covid-19 related)
605	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
606	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
607	Port Klang, Malaysia	CDI	01-May	Malaysia lock down till 12th May as per message from agents. Only local inspectors allowed to carry out the inspection subject to terminal permission. CDI does not have any local inspector in Malaysia.
608	Port Louis, Mauritius	CDI	01-Jun	Local inspector unavailable. (Covid-19 related)
609	Port Moresby, Papua New Guinea	Chevron, BHP	27-May	Due to the COVID-19 travel restrictions
610	Port Moresby, Papua New Guinea	Chevron	27-May	Due to the COVID-19 travel restrictions
611	Port Moresby, Papua New Guinea	BHP	25-May	A local inspector is unavailable. (Covid-19 related)
612	Port Moresby, Papua New Guinea	Equinor	02-Jun	Papua New Guinea that no shoreside personnel are permitted onboard any vessels
613	Port Reunion	CDI	03-Apr	No local inspectors available.
614	Port Said, Egypt	Gazprom	28-Apr	Complete lockdown No Vetting inspections allowed
615	Port Said, Egypt	CDI	24-May	Local inspector unavailable. (Covid-19 related)
616	Port Sudan, Sudan	Enoc	28-Jun	Regret due to COVID 19 travel restrictions we are unable to attend the vessel.
617	Porto Do Acu, Brazil	ENOC	15-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
618	Pozos Colorados, Colombia			
619	Priolo, Italy	CDI	28-May	
620	Pt. Lisas, USA	CDI	08-Apr	Due to the current travel restrictions CDI unable to assign inspector at T & T
621	Puerto Bahia, Colombia		10-Apr	No inspectors available
622	Puerto Cortes, Honduras	CDI	14-Apr	Covid 19 - travel restrictions
623	Puerto Cortes, Honduras	Agents	14-Apr	Covid 19 - travel restrictions
624	Puerto Moin, Costa Rica	Lukoil	04-May	Not Inspected. Vetting inspections are not allowed to be performed alongside (only at anchorage)
625	Puerto Santo Tomas, Guatemala			Terminal not allowed or non-availability of any local inspector due COVID – 19
626	Pyeongtaek, South Korea	CDI, SPTT	17-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
627	Qidong, PRC	ENOC	06-Apr	Terminal restrictions
628	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
629	Qingdao, PRC	ENOC	01-May	Terminal restrictions
630	Qingdao, PRC	Petron	05-May	Terminal rejection of the inspector
631	Qingdao, PRC			
632	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
633	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
634	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
635	Qingdao, PRC	BHP	13-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.

636	Qingdao, PRC	PHILLIPS66	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
637	Qingdao, PRC	TOTAL, P66	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
638	Qingdao, PRC	SHELL	11-Jun	Pls be advised inspector is not allowed to get on board according to Qingdao terminal's latest regulation. Fyi: No person is allowed to get on board except boarding agent and CIQ officers.
639	Qingdao, PRC	BP	22-Jun	Terminal policy- no visitor/inspector allowed due to Covid-19
640	Quanzhou, China	Lukoil, Powershell Terminal	11-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
641	Quanzhou, PRC	P66	Mar-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
642	Quanzhou, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
643	Quanzhou, PRC	TOTAL	04-Jun	Due to unavailability of local inspector
644	Quanzhou, PRC	P66	05-Jun	Agents cannot confirm that permit will be granted by local authorities
645	Quintero, Chile	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
646	Quintero, Chile	Marathon	16-Apr	Due to COVID-19, the terminal is no allowing inspections
647	Quintero, Mexico			
648	Rades, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions
649	Ras Al Khair, Saudi Arabia	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
650	Ras Al Khair, Saudi Arabia	ENOC	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
651	Ras Al Khair, Saudi Arabia	Adnoc, Rightship, Koch, Shell	10-Apr	Local inspector unavailable. (Covid-19 related)
652	Ras Al Khair, Saudi Arabia	CDI	14-Mar	Local inspector unavailable. (Covid-19 related)
653	Ras Al Khair, Saudi Arabia	CDI	10-Apr	Local inspector unavailable. (Covid-19 related)
654	Ras Laffan, Qatar		23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
655	Ras Tanura, Saudi Arabia	ENOC	31-Mar	Covid 19 - travel restrictions
656	Ras Tanura, Saudi Arabia	Maxcom	31-Mar	Covid 19 - travel restrictions
657	Ras Tanura, Saudi Arabia	BHP	01-Apr	Covid 19 - travel restrictions
658	Ras Tanura, Saudi Arabia	ENI	01-Apr	Covid 19 - travel restrictions
659	Ras Tanura. Saudi Arabia	ENOC, Maxcom, BHP, ENI	01-Apr	
660	Ras Tanurah, Saudi Arabia	Adnoc, Saudi Aramco, Total, Lukoil, P66	26-Apr	Local inspector unavailable. (Covid-19 related)
661	Rayong, Thailand		27-Apr	Agents - Covid 19 - travel restrictions
662	Rayong, Thailand	Equinor	26-Jun	
663	Reunion	CDI	03-Apr	No local inspectors available.
664	Richard's Bay, South Africa	Rightship, Total, Shell, Neste, Respol, YPF, Conocophilips,Preem	23-Apr	Local inspector unavailable. (Covid-19 related)
665	Richmond, USA	Lukoil	03-Apr	Not possible due to COVID-19 Restrictions. Only critical personnel allowed.
666	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.

667	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.
668	Rijeka, Croatia	LUKOIL	10-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
669	Rio de Janeiro, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
670	Rio Grande, Brazil			Imposed restrictions
671	Rio Haina, Dominican Republic	CDI	09-May	Local inspector unavailable. (Covid-19 related)
672	Rizhao, PRC	Shell and Maxcom	25-Jan	Inspector's not willing to go due to COVID19
673	Rizhao, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
674	Rizhao, PRC	Chevron	08-May	No available local inspectors; travelling restrictions
675	Rizhao, PRC	P66	05-Jun	Covid 19 - travel restrictions
676	Rizhao, PRC		1-8 Apr	
677	Rotterdam, Netherland	CDI	20-Mar	Inspector refused travelling to Rotterdam due to airport closure at ISLE OF MAN
678	Rotterdam, Netherlands	SHELL	25-May	We regret we are unable to carry out the inspection at this time, as we do not have any local inspectors available. Please request again at a later date.
679	Rotterdam, Netherlands	Equinor	08-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
680	Rovigo, Itali	Shell	05-May	Inspector required to embark by launch
681	Rovigo, Itali	Repsol	05-May	Inspection deemed 'not exceptional' due to Covid-19
682	Rovigo, Itali	BP	05-May	Inspection declined as inspector would have had to remain onboard overnight
683	Rudong, PRC	Phillips66	03-Apr	Terminal restrictions
684	Ruwais, Qatar	Shell	22-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
685	Ruwais, Qatar	Adnoc, Total, Preem, P66	22-Apr	Local inspector unavailable. (Covid-19 related)
686	Ruwais, Qatar	Bienco	22-Apr	No response from OM
687	Ruwais, UAE	ADNOC	12-Apr	Travel restrictions due to COVID - Terminal restrictions due to security sensitivity of the area
688	Sabine Pass, USA	Rightship, Shell	25-May	Cancelled due to unsafe access - adjusted boarding measures (Covid-19 related)
689	Sabine Pass, USA	BP	28-May	
690	Saint Nicolas, France	CDI	20-May	Local inspector unavailable. (Covid-19 related)
691	Saldana Bay, South Africa	BHP, P66	04-Apr	other - complete lockdown due to COVID19
692	Salina Cruiz, Mexico	Lukoil	16-Apr	Foreign Inspector travel ban
693	Salina Cruiz, Mexico	P66	16-Apr	Foreign Inspector travel ban
694	Salvador, Brazil	ENOC	23-Apr	Planned - Due to COVID-19 I will not be able to attend you in Salvador as I am requiring flight from Rio De Janeiro. I can attend you in Rio De Janeiro or in São Sebastião therefore keep me posted when you have program to attend one of these two ports.
695	Salvador, Brazil	ENOC	01-May	Inspector is unable to attend at this call due to prior commitments.

696	Salvador, Brazil	ENOC	01-May	The inspector is unable to attend at this call due to prior commitments. Please advise us her next convenient port.
697	Salvador, Brazil	KOCH	43977	Terminal Change policy - access through terminal forbidden
698	Santos, Brazil			Imposed restrictions
699	Santos, Brazil	Koch, Petrobras	02-Apr	Local inspector unavailable.
700	Santos, Brazil	Phillips66	13-Apr	
701	Santos, Brazil	Shell, BHP	14-Apr	Shell - Not covering; BHP Not performing inspection.
702	Santos, Brazil	Petrobras	15-Apr	Petrobras - Not performing inspections until further, KOCH - No available local inspectors; travelling restrictions
703	Santos, Brazil	Shell	01-May	Not covering
704	Santos, Brazil	ENOC	02-May	
705	Santos, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
706	Sao Luis, Brazil	Idemitsu	18-Mar	
707	Sao Luis, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
708	São Sebastião, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
709	Sariaya, Philippines	BHP-Rightship, Equinor	24-Apr	Inspection cancelled.
710	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
711	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
712	Sfax, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions
713	Shanghai, China	Shell	March	Inspection not allowed by Terminal due to COVID – 19
714	Shiudong, PRC	Lukoil	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
715	Shiudong, PRC		08-May	Inspector who is from abroad is not permitted to come for inspection. Chinese is permitted. If inspector is Chinese , he need to arrive Maoming for quarantine 3 days before on board, and go to hospital for Nucleic acid detection. Launch cost to the terminal will be around 18,000/-USD
716	Shuidong, PRC	BHP	28-May	Covid 19 - travel restrictions
717	Shuidong, PRC	Alma	29-May	Covid 19 - travel restrictions
718	Sierra Leone	Lukoil, Alma	29-Mar	
719	Sierra Leone & Conakry	Lukoil & Alma	29-Mar	Covid 19 - travel restrictions
720	Sikka India	IDEMITSU	12-May	Lockdown in India due to Covid 19 pandemic.
721	Sikka, India	CDI	30-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
722	Sikka, India		1-8 Apr	
723	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
724	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
725	Sines, Portugal			Imposed restrictions

726	Sines, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
727	Sines, Portugal	Lukoil, POT, Saras, Maxcom, Erg, Neste	20-Apr	No local Inspectors and Covid-19 travel restrictions
728	Sines, Portugal	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC	20-Apr	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC - Local inspector unavailable. (Covid-19 related)
729	Sines, Portugal	Cepsa	01-May	Declined due to COVID-19 travel restrictions
730	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
731	Singapore	Enoc	21-Apr	Due to terminal restriction (Singapore Petrochemical Complex Olefin I)
732	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
733	Singapore	Idemitsu	19-May	Singapore Terminal Restricted for inspection due to COVID 19 pandemic
734	Singapore	Idemitsu	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
735	Singapore	Idemitsu	15-Jun	OM - regret to inform you that nominated Terminal (Vopak Penjaru) is not allowing any inspections/visitors due to ongoing COVID-19 restrictions.
736	Singapore	Total	10-Jun	OM - Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling.
737	Singapore, Shell Bukom	Gazprom	17-Apr	Terminal declined inspector's boarding at their terminal due to COVID 19
738	Singapore, Vopak Penjuru	Gazprom	15-Apr	Rejected due to terminal disapproved of any visitors or auditor during current Covid -19 situation
739	Sohar, Oman	CDI, Oiltanking Odfjell	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
740	Sohar, Oman	BHP, Equinor, Gazprom, Repsol, KOCH, ENI, P66,Lukoil, BP, Total, ENOC	30-Apr	Local inspector unavailable. (Covid-19 related)
741	Sohar, Oman	Shell, BP	10-May	Local inspector unavailable. (Covid-19 related)
742	Sohar, Oman	All Majors/CDI	15-May	All routes closed in Oman, foreigners cannot arrive to carry out inspection due to COVID-19
743	Sohar, Oman	Equinor	21-May	Due to travel restrictions imposed by the covid19 outbreak, there are no inspectors available to cover.
744	Sohar, Oman	ENOC, ADNOC, KOCH	21-May	Local inspectors not available; travelling restrictions
745	Sohar, Oman	Idemitsu	22-May	No available local inspectors; travelling restrictions

746	Sohar, Oman	Equinor, ENOC, ADNOC, Idemitsu, KOCH	29-May	Local inspector unavailable. (Covid-19 related)
747	South Africa ports		02-Apr	Heightened level of Security level protocols within the South African Port System during the lockdown period.
748	Southwold, UK	Chevron/Total/Equinor/Shell	25-May	Declined due to unavailability of inspectors
749	Southwold, UK	Lukoil	10-Jun	delay operations
750	Sri Racha, Thailand			Not permitted
751	Sri Racha, Thailand	Lukoil	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
752	St' Charles, Barbados	BHP	02-Apr	Last minute cancellation as terminal change policy - no visitor/inspector allowed due to COVID19
753	St Croix, US Virgin Islands		02-Apr	Not possible due to COVID-19 restrictions
754	St Croix, USA (Virgin Island)	TOTAL	20-Apr	Local inspector unavailable. (Covid-19 related)
755	St. Eustatius		14-Apr	Not possible due to COVID-19
756	St. James, LA USA	Maxcom	01-May	No local inspector available in Louisiana (covid-19 related) normal Texas based inspector to attend but not ready to serve quarantine period when return to Texas
757	Stenungsund, Sweden	CDI	17-Mar	Nominated Inspector declined due to COVID
758	Stignaes, Denmark			Imposed restrictions
759	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April. We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
760	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April. Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
761	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April. Thank you for your email. Please note we not have any local inspectors in Sweden.
762	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April: We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
763	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April: Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
764	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April: Please note we not have any local inspectors in Sweden.
765	Suape, Barzil	IMT/SHELL/CHEVRON	15-May	Due to COVID-19 travel restrictions
766	Suape, Brazil			Imposed restrictions
767	Suape, Brazil	ENOC	17-Apr	Due to COVID 19 travel restrictions we are unable to attend the vessel.
768	Suape, Brazil	IMT/SHELL/CHEVRON	15-May	Due to COVID-19 travel restrictions
769	Suape, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
770	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
771	Suez, Egypt	Agents	22-May	Covid 19 - travel restrictions
772	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
773	Suez, Egypt	IMT	29-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.

774	Sumed, Egypt	Lukoil	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
775	Sumed, Egypt	Shell	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
776	Taicang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
777	Taicang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
778	Taicang, PRC	Maxcom, ALMA, BHP,Lukoil	14-Apr	Covid 19 - travel restrictions
779	Taicang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
780	Taicang, PRC	BP	09-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
781	Taicang, PRC	Idemitsu	29-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
782	Taicang, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
783	Taicang, Taiwan	Petron, P66	05-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
784	Taichung, Taiwan	Koch, Shell, Total, Rightship, Adnoc	20-Apr	Local inspector unavailable. (Covid-19 related)
785	Taichung, Taiwan	BHP, Gazprom	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
786	Tainjin, PRC			
787	Taipei, Taiwan	CDI	27-Apr	Travel/border restrictions being imposed due to COVID-21
788	Taixing, PRC		10-Apr	Terminal didn't allowed
789	Taixing, PRC	CDI	11-Apr	Terminal rejected additional personnel to enter.
790	Taixing, PRC	Lukoil	01-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
791	Taixing, PRC	IMT,Chevron,Petron	01-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19.
792	Taizhuo, PRC	Lukoil	08-May	Covid 19 - travel restrictions
793	Taizhuo, PRC	Agent	07-May	Covid 19 - travel restrictions
794	Tallinn, Estonia	Lukoil	16-Apr	
795	Tallinn, Portugal	LUKOIL	16-Apr	
796	Tamatave, Madagascar (Toamasina)	Maxcom	16-Apr	Covid 19 - travel restrictions
797	Tamatave, Madagascar (Toamasina)	Lukoil,Total,BHP, ENOC,P66,Aethon,Koch, agents	14-Apr	Covid 19 - travel restrictions
798	Tangier MED, Morroco	ENOC	02-Apr	Travelling restrictions
799	Tangier, Morocco		07-Apr	Not allowed due to COVID-19 restrictions
800	Tangier, Morocco	IPLOM	09-Jun	Due to local restrictions imposed the permission to drive/travel to Port-Tangier
801	Tanjung Pelepas, Malaysia	KOCH	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
802	Tanjung Pelepas, Malaysia	P66	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
803	Tanjung Bin, Malaysia	Koch	26-Mar	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
804	Tanjung Priok, FSRU Nusentara, Indonesia	BP	10-May	Travel restriction imposed in th country due to COVID 19.

805	Tarragona, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
806	Tarragona, Spain	Equinor	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
807	Tarragona, Spain	Equinor	05-Jun	no European inspectors are available in Tarragona due to travel restrictions
808	Tarragona, Spain	SHELL	04-Jun	Due to the use of barge / launch boat
809	Tauranga, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
810	Tauranga, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
811	Teesport, UK	Exxon	02-Apr	No available local inspectors; travelling restrictions
812	Tema, Ghana	CDI	19-Mar	Local inspector unavailable. (Covid-19 related)
813	Tema, Ghana	ENOC, KOCH	30-Apr	Local inspector unavailable. (Covid-19 related)
814	Tetney, UK	BP	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
815	Tetney, UK	EQUINOR	13-Apr	Local inspector unavailable.
816	Tetney, UK	BP	20-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
817	Thanh Hoa, Vietnam	PETROVIETNAM KOCH	16-Jun	We have only one local inspector and he will cover few inspections of other vessels from 14 to 20 June. So he will not be available to cover inspection of your vessel. Regret to inform you that we will not be able to arrange the subject vessel inspection, due to the Covid19, Vietnamese Government still not allow International flights up to now.
818	Thanh Hoa, Vietnam	PETROVIETNAM KOCH	16-Jun	We have only one local inspector and he will cover few inspections of other vessels from 14 to 20 June. So he will not be available to cover inspection of your vessel. Regret to inform you that we will not be able to arrange the subject vessel inspection, due to the Covid19, Vietnamese Government still not allow International flights up to now.
819	Thessaloniki, Greece	P66	07-May	Local inspector unavailable. (Covid-19 related)

820	Thessaloniki, Greece	Repsol	07-May	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
821	Tianjin, PRC	CDI	10-Apr	No inspection was not allowed by port authority
822	Tianjin, PRC	IMT, Chevron, Shell, Total	Feb	Inspection not allowed by Terminal due to COVID – 19
823	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
824	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
825	Tianjin, PRC	Lukoil	28-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
826	Tianjin, PRC	Equinor, BHP, Gazprom, Lukoil, KOCH, Idemitsu	09-Feb	Inspector's not willing to go due to safety/health reasons + terminal change policy - no visitor/inspector allowed due to Covid-19.
827	Tianjin, PRC	CDI	11-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
828	Tokuyama, Japan	Equinor, Idemitsui	04-Jun	Regret inform you that we are unable to attend this vessel at Tokuyama. We regret to say we could not find the inspector able to attend your good vessel tomorrow. Sorry for causing your inconvenience.
829	Townsville, Australia	Chevron	March	Inspection not allowed by Terminal due to COVID – 19
830	Tramandai, Brazil	Lukoil	18-Apr	Due to the COVID-19 travel restrictions (Unavailability of Flights)
831	Tramandai, Brazil		24-Apr	Not allowed due to COVID-19 restrictions
832	Tramandai, Brazil	Lukoil	07-May	Covid 19 - travel restrictions
833	Tramandai, Brazil	PMI	04-May	Covid 19 - travel restrictions
834	Tramandai, Brazil	Koch	03-May	Covid 19 - travel restrictions
835	Tramandai, Brazil	Maxcom	02-May	Covid 19 - travel restrictions
836	Tranmere, UK	ENOC	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
837	Tuban, Indonesia	ENOC	05-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
838	Tuban, Indonesia	Rightship	07-Apr	Not possible due to border closures and quarantine requirements due to COVID-19
839	Tuban, Indonesia	Cocophillips	16-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
840	Tuban, Indonesia	Exxon, P66	16-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
841	Tuban, Indonesia	ENOC	12-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
842	Tuticorin, India	CDI	19-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19

843	Tuxpan, Mexico	VIVO	31-Mar	
844	Tuxpan, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
845	Tuxpan, Mexico			Do not allow inspectors onboard.
846	Tuxpan, Mexico	Shell	25-Jun	OM- We regret we are unable to carry out the inspection at this time. We do not currently cover this Country due to COVID-19 restrictions. Please request again at a later date at a different port.
847	Ulsan, SK	NESTEOIL	22-May	(Planned) - Neste not performing any inspections due to the COVID 19 situation.
848	Ulsan, SK	IMT,SHELL	10-Apr	Travel restriction
849	Ulsan, SK	All Majors/CDI	15-May	SK Energy terminal in Ulsan do not permit any inspections to be carried out during cargo operations. Option provided is to carry out the inspection at anchorage which will be an idle inspection and not serve the purpose.
850	Ust Lega,Russia	EXXON	07-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels. We will maintain our pragmatic approach in evaluating TC vessels and SIRE inspections reports will be reviewed on a case by case basis accordingly
851	Ust Lega,Russia	EXXON	07-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
852	Vadinar, India			
853	Vadinar, India	Maxcom	09-Apr	Covid 19 - travel restrictions
854	Vadinar, India	BHP	06-Apr	Covid 19 - travel restrictions
855	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
856	Vadinar, India	ENOC	01-May	Covid 19 - travel restrictions
857	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
858	Valencia, Spain	BHP	29-May	OM - Unfortunately do not have available inspectors and will decline inspection due to current health/virus/quarantine /travel problems , no flights etc..
859	Valencia, Spain	P66	29-May	OM - Unable to schedule the inspection due to the conflict that the Suggested date is within 30 days of an already planned SIRE/OVID inspection with another member.
860	Vatso, Italy	CDI	March	Inspection not allowed by Terminal due to COVID – 19
861	VeraCruz, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
862	VeraCruz, Mexico			Do not allow inspectors onboard.
863	Veracruz, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
864	Veracruz/Altamira, Mexici	CDI	14-Apr	Covid 19 - travel restrictions
865	Vietnam OPL	P66 / PTT	14-Jun	Others – due to COVID-19 travel restrictions
866	Virgin Islands, USA	All Majors/CDI	10-Apr	All ports in USVI is locked down due to COVID-19 and no inspections can be arranged
867	Vizag, India	Koch	08-Apr	Other (National Lockdown - Travel restriction)
868	Vizag, India	CDI	15-Apr	India lockdown due to COVID
869	Vizag, India	Koch	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
870	Vizag, India	Equinor	20-May	Due to several restrictions imposed by the covid-19 outbreak on this given location, the inspector will not be able to attend.

871	Vizag, India	Koch	06-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
872	Vizag, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
873	Vungtau, Vietnam	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
874	Vungtau, Vietnam	NESTEOIL	02-May	At this moment Neste does not carry out sire inspection
875	Vungtau, Vietnam	P66	02-May	Travel/border restrictions being imposed due to COVID-20
876	Walvis Bay, Namibia		April	Namibian authorities suspended Visa issue for 1 month thus NO inspector available
877	Walvis Bay, Namibia	BHP	06-Apr	Lockdown in that area and restricted movement by air, road or rail Not be possible to inspect the subject vessel.
878	Walvis Bay, Namibia	BHP	06-Apr	Local inspector unavailable.
879	Wenzhou, PRC		10-Apr	Terminal didn't allowed
880	Whiffenhead, Canada	BP	16-Apr	Foreign Inspector travel ban
881	Wilhelmshaven, Germany			Imposed restrictions
882	Wilhelmshaven, Germany	BP	29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
883	Yabucao, Puerto Rico	ENOC/BHP/Lukoil/Equinor	03-Apr	Not possible due to COVID-19 Restrictions
884	Yanbu, Saudi Arabia	ADNOC	28-Apr	Travel restrictions - Lockdown
885	Yanbu, Saudi	Enoc	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
886	Yanbu, Saudi	Shell	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
887	Yanbu, Saudi Arabia	CDI, Koch, Shell	12-Apr	Other (National Lockdown - Travel restriction)
888	Yanbu, Saudi Arabia	CDI	11-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
889	Yanbu, Saudi Arabia	CDI / Gas	26-May	No available local inspectors; travelling restrictions
890	Yanbu, Saudi Arabia	CDI	01-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
891	Yanbu, Saudia Arabia	Koch	29-Apr	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
892	Yangpu, PRC	Idemitsu	12-Apr	No inspection was not allowed at the terminal
893	Yangpu, PRC	Idemitsu	12-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
894	Yangpu, PRC	CDI	17-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
895	Yangshan, PRC	MMS	16-May	Present stage, visitor is not allowed in Yangshan LNG terminal.
896	Yantai, PRC	Chevron, Shell, Koch,	Feb	Inspection not allowed by Terminal due to COVID – 19
897	Yantai, PRC	Lukoil, P66	21-Feb	Local inspector unavailable. (Covid-19 related)
898	Yantai, PRC	CDI	21-Feb	Local inspector unavailable. (Covid-19 related)
899	Yeosu, SK		05-Jan	Terminal poilcy- no visitor/inspector allowed due to Covid-19
900	Yeosu,SK		25-Mar	Due to COVID-19 not permitted by terminal
901	Yeosu,SK	EXXON	08-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.

902	Yingkou, PRC	NA	17-May	The following restrictions applies: 1. Inspector should hold Two times (24 interval) nucleic acid testing before onboard date. (Send agent the test reports and other required documents in advance) a. Test can be done at local hospital, 1st test to be done 7 days prior to attendance. 2. 14 days isolation in Yingkou hotel arranged by local port authorities after departure from vessel 3. Other documents will inform him directly if confirmed. 4. Inspectors will most preferably not from the high risk area. (HUBEI, JILIN, HEILONGJIANG province)
903	Yingkou, PRC	Shell, BIECO, Idemitsui	16-17- Jun	No visitor/inspector allowed due to Covid-19.
904	Yingkou, PRC	GAZPROM	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
905	Yizheng, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
906	Yokkaichi, Japan	Shell	15-Jun	Launch service required
907	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
908	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
909	Yumurtalik, Turkey	CDI	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
910	Yung An, Taiwan			
911	Yung An, Taiwan	Chevron	02-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
912	Yung An, Taiwan	KOCH	01-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
913	Yung An, Taiwan	GAZPROM	15-Apr	Local inspector unavailable.
914	Yung An, Taiwan	BP	14-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
915	Zeebrugge, Belgium	REPSOL	14-Apr	Other - Due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
916	Zeebrugge, Belgium	PREEM	05-May	Inspector refused to follow precautions stipulated by the Company SMS.
917	Zhangjiagang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
918	Zhangjiagang, PRC	Maxcom ALMA, BHP, LukOil,	14-Apr	Covid 19 - travel restrictions
919	Zhangjiagang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
920	Zhangjiagang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions

921	Zhangjiagang, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
922	Zhangjiang, PRC	BP	18-Feb	As per BP's message they stated due to terminal restrictions but found out inspector did not want to use launch boat as we managed to book inspection with another oil major
923	Zhapu, PRC	BP	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
924	Zhapu, PRC	Lukoil, BHP Rightship	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
925	Zhapu, PRC	Petron/Chevron	09-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
926	Zhoushan, PRC	Shell	02-Apr	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
927	Zhoushan, PRC	ENOC	13-Apr	Terminal restrictions
928	Zhoushan, PRC		21-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
929	Zhoushan, PRC	SHELL	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
930	Zhoushan, PRC	SHELL	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
931	Zhoushan, PRC		26-Jun	Terminal policy- no visitor/inspector allowed due to Covid-19
932	Zhoushan, PRC		08-May	Terminal restriction for sire inspection is in place.
933	Zhoushan, PRC	EQUINOR	14-May	Terminal policy- no visitor/inspector allowed due to Covid-19
934		BASF	Apr	Rejected for business based on CDI more that 12 months old / no physical CDI could be completed prior to last CDI expiring 12mnths.