

Date : 22/06/2020

INSPECTION CANCELLED OR DECLINE		(blue font - new entry since last weekly update)		
No	Port	OM	Date	Remark
1	Adelaide, Australia	Koch, Shell	March	Inspection not allowed by Terminal due to COVID – 19
2	A Corunna, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
3	A.D.Reis, Brazil	EQUINOR	05-Jan	Declined due to travel restrictions
4	A.D.Reis, Brazil	TOTAL	05-Apr	Declined due to unavailability of inspectors
5	Abidjan, Ivory Coast	CDI	15-Mar	Local inspector unavailable. (Covid-19 related)
6	Adabiyah, Egypt	Statoil	22-Apr	No flights into Egypt, Statoil cancelled request
7	Adabiyah, Egypt	CDI	25-May	Rejected for business based on SIRE more than 6 months old / no physical SIRE could be completed prior to last SIRE expiring 6mths/12mths.
8	Adelaide, Australia	Shell, BP, Idemitsu, Viva	April	Inspection not allowed as interstate travel is restricted due to Covid 19
9	Ain Sukhna Sonkar Terminal, Egypt	Shell	20-May	Others – Unable to carry out the inspection at this time, do not cover this Country.
10	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
11	Ain Sukhna, Egypt	Lukoil, Adnoc, Maxcom	03-May	Covid 19 - travel restrictions
12	Ain Sukhna, Egypt	ENOC	02-May	Covid 19 - travel restrictions
13	Ain Sukhna, Egypt	P66	04-May	Covid 19 - travel restrictions
14	Ain Sukhna, Egypt	MOH	04-May	Covid 19 - travel restrictions
15	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
16	Alcudia, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
17	Alexandria, Egypt	Enoc	18-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
18	Alexandria, Egypt	Koch	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
19	Alexandria, Egypt	Maxcom	23-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

20	Aliaga, Turkey			Imposed restrictions
21	Aliaga, turkey	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
22	Aliaga, Turkey	All Majors/CDI	15-May	Inspections not permitted to be carried out due to COVID-19. Local inspector was appointed, however he was denied entry to the terminal for the purpose of inspection.
23	Aliaga, Turkey	GAZPROM	09-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
24	Aliaga, Turkey	GAZPROM	09-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
25	AL-Jubail, Saudi Arabia	Idemitsu	15-Jun	All air-flights to or from Saudi Arabia has been suspended due to COVID-19 until further instructions.
26	All ports in India	All Majors	03-Apr	Locked down till 14-Apr, no inspections can be scheduled
27	Altamira, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
28	Altamira, Mexico			Do not allow inspectors onboard.
29	Altamira, Mexico	Maxcom	27-Mar	All arranged, port closed over night for non-locals, even as inspector was Mexican
30	Altamira, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
31	Altamira, Mexico	Maxcom	08-May	Covid 19 - travel restrictions
32	Altamira, Mexico	ALMA	07-May	Covid 19 - travel restrictions
33	Altamira, Mexico	ENOC	07-May	Covid 19 - travel restrictions
34	Amsterdam, Netherland	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
35	Amsterdam, Netherland	P66	Apr	No inspector available
36	Amsterdam, Netherlands	Neste	18-May	At this moment Neste does not carry out any sire inspections.
37	Antifer, France	BP	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
38	Antwerp, Belgium	Gazprom	06-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. From agent: We received terminal ATPC instructions from that due COVID nobody is allowed on the terminal anymore till further notice
39	Arzew, Algeria		07-Apr	Not allowed due to COVID-19 restrictions
40	Arzew, Algeria	CDI	27-May	Local inspector unavailable. (Covid-19 related)
41	Ashklelon, Isreal	Gazprom	04-Mar	Last minute cancellation as inspector's were not allowed to enter Israel if previously travelled to high risk COVID19 countries in Europe
42	Aughinish, Ireland	P66	25-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
43	Aughinish, Ireland	Koch, VIVO	25-Apr	Local inspector unavailable. (Covid-19 related)

44	Augusta, Sicily	BHP	29-May	The Sicily region have still travel limitation until at least the 7th June. Not residents in Sicily cannot travel to Augusta. In view of restriction, we will decline the inspection invitation.
45	Aviero, Portugal	CDI	28-Mar	Terminal requirements not to allow any inspections due to COVID-19
46	Bahia Blanca, Argentina	KOCH, Idemitsu	31-Mar	Local inspector unavailable. KOCH and Idemitsu were not able to find available inspectors due to COVID
47	Banática, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
48	Bangkok & Maptaphut, Thailand	PTT	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
49	Banjul, SK	Maxcom	16-Apr	Covid 19 - travel restrictions
50	Banjul, SK	Maxcom	15-Apr	Covid 19 - travel restrictions
51	Banjul, SK	Total, ENOC, Maxcom	14-Apr	Covid 19 - travel restrictions
52	Banjul, SK	BHP	14-Apr	Covid 19 - travel restrictions
53	Banjul, SK	Aethon/Koch	14-Apr	Covid 19 - travel restrictions
54	Barcelona, Spain	Cepsa	01-Jun	Declined on 20 May 2020 due to COVID-19 travel restrictions
55	Barranquilla, Colombia	BEICO	10-Apr	Port does not allow till further notice.
56	Basamuk, PNG			
57	Bataan, Philiphine	PETRON	18-May	Regret to inform you that visiting inspector is not allowed as of the moment due to COVID-19 and we are still on community quarantine until May 30.
58	Beaumont, USA	Exxon/IMT	05-Apr	
59	Beira, Mozambique	ENOC	20-May	Covid 19 - travel restrictions
60	Beira, Mozambique	P66	27-Apr	Local inspector unavailable. (Covid-19 related)
61	Beira, Mozambique	Lukoil	27-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
62	Belem, Barzil	Petrobras	10-Apr	Petrobras are not carrying out inspections worldwide due to COVID-19
63	Belize	EQUINOR	19-May	Covid 19 - travel restrictions
64	Belize,	Equinor	01-Jun	Covid 19 - travel restrictions
65	Benicia, CA, USA	Phillips66	07-Apr	Terminal not allowed
66	Bilbao, Brazil			Imposed restrictions

67	Bilbao, Spain	PETRONOR	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
68	Bintulu OPL, Malaysia	Petronas	20-Apr	During Movement Control Order period, all personal enter Sarawak have to be complete compulsory quarantine for 14 days at hotel / hospital arrange by local government. After complete compulsory quarantine 14 days, auditor to need pass Port health screening before permitted to board vessel at anchorage. As per the above and also travel restrictions and safety of the inspector; we regret to inform cannot cover the inspection.
69	Bintulu, Malaysia	MMS	27-May	Due to COVID-19 and movement restriction, inspector need to be quarantine at Sarawak for 14 days before the inspection.
70	Bizerte, Tunisia	BP	09-Jun	short notice
71	Bizerte, Tunisia	Shell	08-Jun	unable to conduct inspection in Tunisia
72	Bonny, Nigeria	Petron	16-May	Terminal change policy – visitor/inspector need 14 days quarantine due to Covid-19.
73	Bontang , Indonesia	Idemitsu	17-Apr	No available local inspectors; travelling restrictions
74	Bordeaux, France	EQUINOR	17-May	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available for the given port/date to cover this request at the moment.
75	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
76	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
77	Botany Bay,	VIVA	15-Apr	Local inspector unavailable.
78	Botany Bay, Australia	Ampol	02-Apr	Due to situation of Coronavirus outbreak, OM are unable to process the inspection request.
79	Botany Bay, Australia	BP, Total, IMT, Lukoil, Ampol and Shell	10-Apr	Shell eventually took the inspection but finally terminal did not allow.
80	Botany Bay, Australia	BP	02-Apr	Travel restriction imposed in th country due to COVID 19
81	Bourgas, Bulgaria	SHELL	09-Apr	Local inspector unavailable.
82	Bourgas, Bulgaria	BP	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
83	Bourgas, Bulgaria	Chevrom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
84	Brisbane, Australia		03-Apr	Allowed- boarding of inspectors only 3hours after berthing. Check with agents.
85	Brisbane, Australia	ENOC	14-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.

86	Brisbane, Australia	P66	17-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
87	Brisbane, Australia	CHEVRON	28-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
88	Brunei	Gazprom, idemitsu, Equinor, Maxcom	04-Apr	other - complete lockdown due to COVID19
89	Brunei	All Majors/CDI	29-May	Information: Inspections not permitted in Brunei due to COVID-19 pandemic. All foreigners arriving Brunei need to serve 14 days quarantine period.
90	Burgas, Bulgaria	All Majors/CDI	01-May	Bulgaria is locked down due to COVID-19
91	Busan, SK		05-May	Not possible due to COVID 19 restrictions
92	Busan, SK		05-May	Not possible due to COVID 19 restrictions
93	Cabo Negro, Chile	CDI	16-May	Other - Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
94	Cabo Negro, Chile	CDI	16-May	Local inspector unavailable. (Covid-19 related)
95	Cabo Negro, Morocco	CDI	16-May	Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
96	Cabo Negro, Morocco	CDI	16-May	Local inspector unavailable. (Covid-19 related)
97	Caldera, Chile	Marathon	22-Apr	Terminal restriction
98	Callao, Peru	ConocoPhillips	23-Apr	ConocoPhillips declined request due to Covid
99	Callao, Peru	CDI	08-May	Local inspector unavailable. (Covid-19 related)
100	Callao, Peru	Any OM	15-Jun	Foreign Inspector travel ban. Airports closed due Emergency declared till June 30th.
101	Canaport, Canada	Chevron	17-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
102	Canaport, Canada	Equinor	15-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
103	Canaport, Canada			Terminal quarantines vessel if inspector boards prior berthing. Not permitted during discharge. Vessel must be at sea for >14 days prior berthing. Post discharge you are allowed everything at the anchorage.
104	Caoeger Bay, South Africa	ENOC, Equinor	05-May	Local inspector unavailable. (Covid-19 related)
105	Caofeidian, PRC	Enoc, Total, Shell, P66, Bioco, Koch, BHP, IMT, Chevron	Feb	Inspection not allowed by Terminal due to COVID – 19
106	Cartagena, Colombia	Chevron	19-May	Inspector unavailability

107	Cartagena, Spain			Terminal not allowed or non-availability of any local inspector due COVID – 19
108	Cartagena, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
109	Cartagena, Spain	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
110	Castellon, Spain	Enoc	March	Inspection not allowed by Terminal due to COVID – 19
111	Castellon, Spain	Equinor	21-Mar	Terminal change policy - no visitor/inspector allowed due to Covid-19
112	Ceuta, Spain	Lukoil,Cepsa, OMV, Total. Maxcom, POT, Repsol, P66, Enoc	16-Apr	No local Inspectors and Covid-19 travel restrictions
113	Ceyhan, Turkey	ENOC	08-May	ENOC are unable to attend the vessel.
114	Ceyhan, Turkey		22-Apr	Checked with Agents - Complete lockdown No Vetting inspections allowed
115	Chang Xing, PRC	All OM	06-May	Terminal restriction
116	Changzhou Huarun, PRC		13-May	As per agents - not allowed
117	Changzhou, PRC	CDI	09-Jun	Pls kindly note subject vessel fixed calling Jiangyin/Changzhou/Taizhou. After checked with each port, Changzhou and Taizhou tml don't permit inspection nowadays due to COVID-19 even Chinese. For Jiangyin, as our agent reported, jgn port authorities need 14 days quarantine after inspection to government appointed hotel waiting 14 days.
118	Chennai, India	Chevron	04-Apr	other - complete lockdown due to COVID19
119	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
120	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
121	Chiba, Japan		22-Apr	Not allowed due to COVID-19 restrictions
122	Chiriqui Grande, Panama		16-Apr	Not possible due to COVID-19 restrictions

123	Chiriqui Grande, Panama	P66. Equinor	30-Apr	Not possible due to COVID 19 travel restrictions. No local inspector.
124	Chittagong	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
125	Chittagong, Bangladesh	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
126	Chittagong, Bangladesh	BP	Apr	Terminal not allowing to board BP vetting inspector due to restriction.
127	Chittagong, Bangladesh	EQUINOR	12-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
128	Chittagong, Bangladesh	MAXCOM	11-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
129	Ciudad Madero, Mexico	Equinor	20-Apr	Due to the COVID-19 travel restrictions (Lock Down)
130	Coassa, Panama	All	10-May-20	Terminal under security level 2 – no visitor/inspector allowed due to Covid-19.
131	Coatzacoalcos, Mexico	EQUINOR	06-Apr	Covid 19 - travel restrictions
132	Coazacoalcos, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
133	Coazacoalcos, Mexico			Do not allow inspectors onboard.
134	Coega Bay, South Africa	Equinor	15-May	Local inspector unavailable. (Covid-19 related)
135	Conarky, Guinea	Lukoil, Alma	29-Mar	
136	Concepcion Bay, Chile	CHEVRON	10-Apr	Not able to attend due the new restriction during easter holidays, travel problems due to COVID19. At this time the inspection is now cancelled.
137	Concepcion Bay, Chile	CHEVRON	11-Apr	Regret we will not be able to attend this one due the new restriction during easter holidays, travel problems due to COVID19. Thank you very much for your help, at this time the inspection is now cancelled.
138	Conchan, Peru	CHEVRON	17-Mar	Peruvian Government has restricted citizens' movement within their homes and closed international travel with effect from 16 March to 1 April.
139	Conchan, Peru	REPSOL	18-Mar	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
140	Conchan, Peru	Any OM	15-Jun	Foreign Inspector travel ban. Airports closed due Emergency declared till June 30th.
141	Corpus Christi, USA	Koch	15-May	Covid 19 - travel restrictions
142	Corpus Christi, USA	Equinor	25-May	Personal issues with the inspector

143	Coruna, Spain	Cepsa	29-Apr	Only at their terminals at Huelva, Tenerife and Algeciras
144	Cotonou, Benin	CDI	17-Mar	Local inspector unavailable. (Covid-19 related)
145	Cotonou, Benin	CDI	21-Mar	Local inspector unavailable. (Covid-19 related)
146	Cotonou, Benin	Lukoil	16-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
147	Cotonou, Republic of Benin	Agent	07-May	Covid 19 - travel restrictions
148	Covenas, Colombia	NA	15-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19. (ADVISED THROUGH AGENT)
149	Covenas, Columbia		16-Apr	Not possible due to COVID-19 restrictions
150	Covenas, Columbia	ENOC	18-Apr	Permission not granted by terminal due to COVID-19 restrictions
151	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice
152	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
153	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
154	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice. Exception is if the inspector is a local, however permission is required.
155	Cristobal, Panama		27-Mar	Travel restriction
156	Daesan, SK	TOTAL	05-Apr	Declined due to unavailability of inspectors
157	Daesan, SK	Total	31-May	Terminal prohibited any job other than cargo operation at berth. The same was explained you earlier and we have arranged his on / off schedule at the anchorage. However, the vessel's ETB delayed several hours again today as the terminal changed our vessel's jetty. And the inspector suddenly informed that he should cancel the inspection.
158	Daesan, SK			Not permitted by terminal
159	Daesan, SK	ENOC	12-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
160	Daesan, SK	IMT & BP	14-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
161	Dahej, India		01-May	Agents information due to terminal restrictions and lock-down
162	Dakar, Primorsk Oil Terminal, Senegal		10-Jun	Due to COVID restrictions, our inspectors are unable to reach Dakar and carry out the inspection onboard the vessel
163	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
164	Dakar, Senegal	Maxcom	14-Apr	Covid 19 - travel restrictions
165	Dakar, Senegal	ENOC, BHP, agents	13-Apr	Covid 19 - travel restrictions

166	Dakar, Senegal	Koch, Aethon, Total	13-Apr	Covid 19 - travel restrictions
167	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
168	Dalian, PRC			
169	Dalian, PRC		13-May	As per agents - not allowed
170	Dalian, PRC	Shell, Chevron	27-May	Terminal restrictions; local inspectors only
171	Dapeng, PRC	MMS	07-May	Visitor enter terminal must stay in this city "Shenzhen" longer than 14 days; Visitor should need Nucleic acid test of COVID-19 3 days before ship arrival, then we can make the application; Terminal will consider to approve or not base on Customs' quarantine pre examination on the vessel about 2-3 days before ship arrival(base on vessel's port calls records, crews conditions etc.
172	Dominican Republic	P66	13-Apr	Due to the COVID-19 travel restrictions
173	Dominican Republic	Lukoil	13-Apr	Due to Dominican Republic is locked down
174	Donges, France	Enoc	23-May	OM - Regret due to COVID 19 we cannot attend this vessel.
175	Donges, France	P66	23-May	Unfortunately due to COVID 19, there are travel or terminal restrictions in the location you requested this inspection to be conducted in
176	Dongguan, PRC	any OM	03-Apr	Covid 19 - country lock down
177	Dongguan, PRC	BHP	18-Apr	Dongguan Immigration is not allowed the SIRE inspector to visit ship for this calling due to Dongguan got two confirmed COVID-19 cases in last week which from foreign ships.
178	Dongguan, PRC	BHP	22-Apr	We do not have available inspectors at the moment due to various virus restrictions and will decline inspections.
179	Dongguan, PRC	Shell	19-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
180	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Insepction at the moment yet.
181	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Insepction at the moment yet.
182	Dongguan, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
183	Dongjiakou, {PRC	BHP	25-May	Covid 19 - travel restrictions
184	Dongjiakou, PRC			
185	Dongjiakou, PRC	Maxcom	07-Apr	Terminal is closed as per covid 19 restrictions
186	Dongjiakou, PRC	MAXCOM	07-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
187	Dongjiakou, PRC	Chevron	10-Apr	Plan 17/04/2020 - Chevron do not schedule SIRE inspection at China port at the moment.
188	Dongjiakou, PRC	Shell	10-Apr	Plan 17/04/2020 - Rejected due to COVID-19

189	Dongying, PRC	EQUINOR	20-May	Covid 19 - travel restrictions
190	Dongying, PRC	BHP	21-May	Covid 19 - travel restrictions
191	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
192	Dongying, PRC	ENOC	23-May	Covid 19 - travel restrictions
193	Dongying, PRC	Maxcom	21-May	Covid 19 - travel restrictions
194	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
195	Douala, Cameroon			Terminal not allowed or non-availability of any local inspector due COVID – 19
196	Douala, Cameroon	Gazprom,Total	01-Jun	Lockdown due to COVID19 - no local inspectors available
197	Dumai, Indonesia	BHP, Neste oil	05-Jun	Due to COVID-19 travel restrictions
198	Durban, South Africa	Shell	26-Mar	
199	Durban, South Africa	Shell	24-Mar	Covid 19 - country lock down
200	Durban, South Africa	Shell	26-Mar	Covid 19 - country lock down
201	El Segundo, California, USA		22-Apr	no visitor/inspector allowed due to Covid-19
202	El Segundo, USWC	Chevron, P66	21-May	Terminal change policy – visitor/inspector allowed due to Covid-19.
203	El Segundo, USWC	Chevron		Terminal does not permit
204	El Segundo, USWC	P66	09-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19. (Terminal belong to Chevron and operator requested them to inspect - tbc)
205	Ennore, India	Shell	04-Jun	Planned: Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections in India until further notice.
206	Ennore, India	ENOC	05-May	Terminal rejection of the inspector
207	Fawley, UK	EXXON	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
208	Fawley, UK			
209	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March:Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
210	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March:Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
211	Fawley, UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
212	Fawley,UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
213	Fos, France			Member reported info from agent, now possible to do inspection

214	Fos, France	TOTAL & OMV	23-May	Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling. We have just received the answer from the last Inspector, unfortunately, he is not available. In view of the above, we are force to postpone the inspection.
215	Freeport , USA	P66	25-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
216	Freeport ,USA	P66	25-Apr	Planned - Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
217	Freeport, Bahamas		10-Apr	Due to Lockdown
218	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
219	Fujairah, UAE	SHELL	22-Apr	Due to launch required for boarding
220	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
221	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
222	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
223	Gabes, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions
224	Galveston Offshore lightering area	Chevron	24-Apr	Unavailability of inspector for this inspection
225	Ganyu, PRC	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
226	Gdansk, Poland	ENOC, KOCH	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
227	Geismar, USA	Conocophillips	27-Mar	OM advised they have cancelled due to COVID 19
228	Geismar, USA	Equinor	27-Mar	Equinor did not have inspector due to COVID 19
229	Gemlik, Turkey	CDI	09-Apr	Local inspector unavailable.
230	Geoje, SK		01-Jun	Not allowed by terminal
231	Ghent, Belgium	Neste	14-Apr	Due to corona restrictions within the Company
232	Gijón, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
233	Gizan, Saudi Arabia	Aramco	15-Jun	No third party attendance possible due to the security reasons. Aramco declined due to travel restrictions.

234	Goeje Yard, SK	PETROBRAS	21-May	Planned: Due to the outbreak of the COVID-19, currently we are not performing SIRE inspections in any port of the world
235	Guam, USA	BP,CHEVRON,P66,GA ZPROM	10-Apr	Travel restrictions 14 days quarantine resulted to no inspectors available
236	Guam/Saipan, USA			Terminal not allowed or non-availability of any local inspector due COVID – 19
237	Guayanilla, Puerto Rico		16-Apr	Not possible due to COVID-19 restrictions
238	Guaynilla, Puerto Rico		20-May	Not possible as no local inspector and no flights operating to the island
239	Gulei, PRC		22-Mar	Due to COVID-19 not permitted by terminal
240	Gulei, PRC	Maxcom	09-May	Terminal restricions
241	Gulei, PRC	ENOC	May-20	Terminal change policy – no visitor/inspector allowed due to Covid-19.
242	Hadera, Israel	Repsol	22-May	"Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception"
243	Hadera, Israel	Rightship, Total	22-May	Local inspector unavailable. (Covid-19 related)
244	Haldia, India		Apr	Terminal informed they will not allow vetting inspector to board due to restriction. India under lockdown.
245	Haldia, India	Idemitsu	04-May	India Lock down.
246	Haldia, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
247	Hamriyah, UAE	P66	Apr	Terminal did not allow BP vetting inspector to board due to COVID 19 restriction
248	Hazira, India	Rightship	01-Apr	country under lockdown - travelling prohibited within country
249	Hong Kong, PRC			
250	Honninggsvag, Norway	BP	03-Apr	Due the COVID-19 there is borders restriction to any non-residents (except for transit passengers).
251	Honninggsvag, Norway			
252	Honolulu, USA	SHELL	25-May	Travel restriction imposed in th country due to COVID 19.
253	Houston, USA	Equinor	Mar	Master has raised concerns about safety & health of the crew and has requested for deferring the inspection so as to avoiding/limit contact with visitors to the bare minimum. Tech. Manager agreed and postponed inspection.
254	Houston, USA	REPSOL	05-Apr-20	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information.These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
255	Houston, USA	Repsol	13-Apr	

256	Houston, USA	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
257	Houston, USA	Repsol	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
258	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-22
259	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-24
260	Huelva, Spain			Imposed restrictions
261	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
262	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected, Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
263	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
264	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected. Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
265	Huelva, Spain		18-May	Not possible due to COVID-19 restrictions in port.
266	Huizhou, PRC	Shell	Apr-20	Terminal’s policy – not allow Sire inspector to board the vessel due to Covid -19
267	Huizhou, PRC	P66	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
268	Huizhou, PRC	Petron	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
269	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April. Equinor do not have any available Inspector at Iceland due to COVID-19
270	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April: Equinor do not have any available Inspector at Iceland due to COVID-19
271	Ilo, Peru	Total	09-Jun	Due to the unavailability of an inspector in the port
272	Ilo, Peru	P66	08-Jun	Due to the COVID-19 travel or terminal restrictions

273	Immingham, UK	Ineos, Borealis, Shell	12-Apr	Local inspector unavailable. (Covid-19 related)
274	Incheon, SK			Not permitted by terminal
275	Iskendrun, Turkey		29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
276	Itaqui, Brazil	BHP	17-Apr	We regret will not be able to cover vessel's inspection.
277	Itaqui, Brazil	ENOC	17-Apr	Regret due to COVID 19 travel restrictions we are unable to attend the vessel.
278	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.
279	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.
280	Itaqui, Brazil	BP	24-May	OM - our inspectors are unable to cover Itaqui as the city it falls in Sao Luis is in lockdown
281	Itaqui, Brazil	Maxcom	24-May	OM- Much to our regret we can't cover as per Covid restrictions
282	Jasaan, Philippines	P66/BHP/Petron	28-May	No domestic flights available.
283	Jebel-Ali, UAE	Equinor	14-Apr	Inspection rejected - due to Hamriyah Terminal Restriction Not Allowed (COVID-19 pandemic).
284	Jebel-Ali, UAE	BP	11-Apr	Vessel had berth at SOET terminal, where SIRE Inspection are not permitted at COVID 19.
285	Jeddah, Saudi Arabia	BIECO	22-Apr	Terminal restriction
286	Jeddah, Saudi Arabia	Lukoil	26-Apr	Terminal restriction
287	Jeddah, Saudi Arabia	Any OM	09-Jun	Aramco Jeddah restricts to conduct any kind of inspection on their Terminals.
288	Jiangsu, PRC		27-Apr	Terminal restrictions
289	Jiangyin, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
290	Jiangyin, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
291	Jiangyin, PRC	P66	03-Jun	COVID 19 travel or terminal restrictions in the location you requested this inspection to be conducted in.
292	Jisan, Saudi Arabia	Total, ENOC, AMPOL	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
293	JNPT India	Idemitsu	05-Jun	Dy. Conservator JNPT not allowing any inspection at JNPT.
294	Jorf Lasfar, Morocco			Terminal not allowed or non-availability of any local inspector due COVID – 19
295	Jorf Lasfar, Morocco	CDI	Early March	CDI was postponed on the beginning of March intentionally. Planning was to perform CDI under new management after takeover in discharging port. Takeover plans were postponed due to COVID and therefore CDI inspection too.
296	Jorf Lasfar, Morocco	CDI	26-Mar	Local inspector unavailable. No inspector available due to COVID.

297	Jorf Lasfar, Morocco	SIRE	03-Apr	Other (National Lockdown - Travel restriction)
298	Jorf Lasfar, Morocco	Total, Shell, Borealis, Rightship, Equinor, Adnoc	04-May	Local inspector unavailable. (Covid-19 related)
299	Jorf Lasfar, Morocco	Lukoil	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. (local inspector available and appointed)
300	Jorf Lasfar, Morocco	CDI	06-May	Local inspector unavailable. (Covid-19 related)
301	Jorf Lasfar, Morocco	SIRE	05-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
302	Jorf Lasfar, Morocco	CDI	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
303	Kaarsto, Norway	Chevron, IMT	04-Jun	Inspector unavailability
304	Kakinada, India	CDI	24-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
305	Kakinada, India	EQUINOR	06-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
306	Kakinada, India	BP	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
307	Kakinada, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
308	Kalundborg, Denmark	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
309	Kandla, India	Rightship, Adnoc, Total, Shell, Bieco	25-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
310	Kandla, India	Adnoc, Total, Shell, Bieco	28-Apr	Local inspector unavailable. (Covid-19 related)
311	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
312	Kaohsiung, Taiwan	Valero	17-Apr	Covid 19 - travel restrictions
313	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
314	Kaohsiung, Taiwan	Gazprom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
315	Kaohsiung, Taiwan	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
316	Kaohsiung, Taiwan	Petron	18-Apr	Local inspector unavailable. (Covid-19 related)
317	Kaohsiung, Taiwan	ENOC	Apr-20	Inspector can not enter Taiwan due to restriction of entry policy for control of Covid 19
318	Kaohsiung, Taiwan	Idemitsu, Shell, BHP	March	Inspection not allowed by Terminal due to COVID – 19
319	Kaoshiung, Taiwan	SHELL, BP, CHEVRON, ENOC	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19 unavailable. (Covid-19 related)

320	Kaoshiung, Taiwan	ENOC	20-Apr	Local inspector unavailable. (Covid-19 related)
321	Kaoshiung, Taiwan	BHP	17-May	Travel restriction imposed in th country due to COVID 19.
322	Kaoshiung, Taiwan	Idemitsu	17-May	Travel restriction imposed in th country due to COVID 19.
323	Karachi, Pakistan	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
324	Karachi, Pakistan.	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
325	Karratha, Australia	BP	01-May	Terminal restrictions
326	Karratha, Australia	BP	01-May	Terminal restrictions
327	Karsto, Norway	CDI	15-Apr	Local inspector unavailable. (Covid-19 related)
328	Karsto, Norway	CDI	15-May	Local inspector unavailable. (Covid-19 related)
329	Kawasaki, Japan	SHELL	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
330	Kawasaki, Japan	P66	30-Apr	Travel/border restrictions being imposed due to COVID-19
331	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
332	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
333	Kingston,Jamaica		25-May	Not possible due to COVID-19 restrictions and country is under lockdown.
334	Klaipeda, Lithuania	BHP / P66 / Chevron	06-Jun	Due to COVID-19 travel restrictions
335	Koper , Slovenia	Q8	Feb-20	Restriction due to Covid 19
336	Kotka, Finland	Preem, Lukoil, Koch	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19; Local inspector unavailable. (Covid-19 related)
337	Kozmino, Russia	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
338	Kuantan, Malaysia	Gazprom	02-Apr	All hotels closed therefore inspector who was driving 6 hours refused to attend - only local inspectors allowed as there are travel restrictions
339	Kwinana, Australia	BP	01-Apr	Terminal restrictions
340	Kwinana, Australia	Chevron	15-Apr	Covid 19 - travel restrictions
341	Kwinana, Australia	BHP	26-May	Panned: Until further notice all non-essential and non- cargo operation visits such as SIRE inspections and routine technician visits will not be permitted during STS operations or when vessels are alongside the refinery jetties.
342	Kwinana, Australia	IMT	28-Jun	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
343	Kwinana, Australia	IMT	24-May	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.

344	La Libertad, Ecuador	Lukoil, Equinor, Rightship, BP, Koch	03-Apr	Local inspector unavailable. (Covid-19 related)
345	La Pampilla, Peru	IMT, Repsol, YPF, Sonangol, Maxcom, Gazprom, Phillips66, Shell	31-Mar	
346	La Pampilla, Peru	IMT	31-Mar	Covid 19 - travel restrictions
347	La Pampilla, Peru	Repsol	31-Mar	Covid 19 - travel restrictions
348	La Pampilla, Peru	YPF	31-Mar	Covid 19 - travel restrictions
349	La Pampilla, Peru	Sonangol	31-Mar	Covid 19 - travel restrictions
350	La Pampilla, Peru	Maxcom	31-Mar	Covid 19 - travel restrictions
351	La Pampilla, Peru	PMI	01-Apr	Covid 19 - travel restrictions
352	La Skhira, Tunisia			Terminal not allowed or non-availability of any local inspector due COVID – 19
353	Lagos, Nigeria	ENOC	10-Apr	Local inspector unavailable. (Covid-19 related)
354	Lagos, Nigeria	Total	28-Apr	Not inspecting in Africa currently
355	Lagos, Nigeria	Nobody invited as informed by Agents	04-Apr	other - complete lockdown due to COVID19
356	Las Minas, Panama	BHP	27-May	Local inspector unavailable. (Covid-19 related)
357	Las Minas, Panama	BHP	27-May	A local inspector is unavailable. (Covid-19 related)
358	Las Palmas, Spain	ENOC	24-Apr	Covid 19 - travel restrictions
359	Las Palmas, Spain	CEPSA	24-Apr	Covid 19 - travel restrictions
360	Las Palmas, Spain	Repsol	27-Apr	Covid 19 - travel restrictions
361	Las Palmas, Spain	Cepsa	30-May	MOC is not authorized to perform inspections outside Cepsa Terminals at Huelva, Algeciras or Tenerife.
362	Las Palmas, Spain	Repsol	01-Jun	Repsol does not inspect any vessel except special situations due to Covid-19
363	Lavera, France	KOCH	06-Apr	Not be able to plan the attendance due to COVID 19 travel restrictions
364	Lavera, France	BHP	06-Apr	Do not have available inspectors due to present virus situation. Flight and transport restriction beyond our control
365	Lavera, France	CDI	24-Apr	Travel restriction.
366	Lavera, Portugal	POT	10-Apr	Others - Due to COVID-19, POT do not inspect vessels temporarily.
367	Lavera, Portugal	GAZPROM	10-Apr	Local inspector unavailable.

368	Lavera, Portugal	P66	09-Apr	Local inspector unavailable.
369	Lavera, Portugal	ENOC	09-Apr	Local inspector unavailable.
370	Lavera, Portugal	BHP	06-Apr	Local inspector unavailable.
371	Lavera, Portugal	KOCH	06-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period.
372	Le Havre, France	CDI	25-Mar	Tech. manager decided to do not proceed with inspection in France to do not put crew in unnecessary risk – requested for CDI validity extension (successfully).
373	Le port, Reunion			Terminal not allowed or non-availability of any local inspector due COVID – 19
374	Leixioes, Portugal	Maxcom	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
375	Lianyungang , PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
376	Lianyungang , PRC	P66	03-May	No inspector available due to COVID-19 travel/border restrictions
377	Lianyungang, China	CDI, Xinrongtai	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
378	Lianyungang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
379	Lianyungang, PRC	Maxcom, ALMA	14-Apr	Covid 19 - travel restrictions
380	Lianyungang, PRC	BHP, Lukoil	14-Apr	Covid 19 - travel restrictions
381	Lianyungang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
382	Lianyungang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
383	Lianyungang, PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
384	Lianyungang, PRC	SHELL	03-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
385	Lianyungangn, PRC	All Majors/CDI	24-Apr	Terminal does not permit inspections due to COVID-19
386	Libreville, Gabon	CDI	March	Inspection not allowed by Terminal due to COVID – 19
387	Limay, Phillipines	IMT	01-Apr	Due to COVID-19 not permitted by terminal
388	Limbe, Cameroon	Shell, Enoc	05-Feb	Local inspector unavailable.
389	Limbe, Cameroon	BP, Maxcom	25-Mar	Inspection cancelled , due to Lockdown and restricted movement by air, road, etc
390	Limetree Bay, US Virgin Islands	P66	17-Apr	Due to the COVID-19 travel restrictions (Lock Down)
391	Lisbon, Portugal	BP	09-May	Understand from our inspectors in the region that Portugal borders are closed till at least 15th May and likely to be extended to June.

392	Lome OPL, Togo	Agent	14-May	Covid 19 - travel restrictions
393	Lome OPL, Togo	Agent	15-May	Covid 19 - travel restrictions
394	Lome OPL, Togo	Alma	15-May	Covid 19 - travel restrictions
395	Lome, Togo	Shell	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
396	Lome, Togo	Lukoil	22-Apr	Lome is locked down
397	Lome, Togo	CDI	16-Mar	Local inspector unavailable. (Covid-19 related)
398	Lome, Togo	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)
399	Lome, Togo	ENOC	27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
400	Lome, Togo	P66	19-Jun	Local inspector unavailable. (Covid-19 related)
401	Long Beach, CA, USA	Shell	30-Mar	Cancelled
402	Loop, USA	Lukoil, ENOC,Maxom	24-Mar	
403	Loop, USA	Lukoil	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
404	Loop, USA	ENOC	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
405	Loop, USA	Maxcom	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
406	Loop, USA	PHILLIPS 66	12-Apr-20	There are travel restrictions in the region. To submit a new inspection request once next berthing orders are known and OM will try to accommodate inspection request.
407	Loop, USA	PHILLIPS 66	12-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
408	Loop, USA	Exxon	14-May	Unable to attend
409	Louisiana, USG	Marathon		Cancelled
410	Luanda, Angola	BHP , Maxcom, P66	13-Mar	Complete lockdown due to COVID19
411	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
412	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
413	Luanda, Angola	Chevron	03-Jun	Covid 19 - travel restrictions
414	Lubuk Guang, Indonesia	P66	18-Jun	Terminal change policy – visitor/inspector need 14 days quarantine due to Covid-19.
415	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
416	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
417	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
418	Mailiao, Taiwan			
419	Mailiao, Taiwan	CDI	29-Mar	Local inspector unavailable. (Covid-19 related)
420	Malta	Lukoil	16-Apr	Due to Malta is locked down

421	Malta	ENOC,Koch, BIECO	27-Apr	Malta is Locked down, local inspector unavailable
422	Malta	IMT/SHELL/TOTAL	15-May	Malta in lockdown due to COVID
423	Malta	NA	05-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19. (ADVISED THROUGH AGENT)
424	Mamonal, Colombia	CHEVRON	15-Apr	Regret to inform that we do not have an inspector available for this inspection
425	Mamonal, Colombia	LUKOIL	15-Apr	Please be informed that due to terminal restrictions inspection cannot be arranged at Mamonal.
426	Mamonal, Colombia	PHILLIPS 66	15-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
427	Mangalore, India	Idemitsu	17-May	Others
428	Manzanillo, Mexico	P66, Shell	April	Inspection not allowed as interstate travel is restricted due to Covid 19
429	Manzanillo, Mexico	P66	14-Apr	Inspection declined due to COVID -19
430	Manzanillo, Mexico	ENOC	14-Apr	Inspection declined due to COVID -19
431	Manzanillo, Mexico	P66	14-Apr	due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
432	Manzanillo, Mexico	Equinor	14-Apr	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available to cover this request at the moment.
433	Manzatlán, Mexico	Shell, Chevron, Marathon, P66	10-Apr	Due Covid-19 sanction.
434	Map Ta Phut, Thailand	IMT	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
435	Map Ta Phut, Thailand	SHELL	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
436	Map ta Phut, Thailand	Lukoil	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
437	Map Ta Phut, Thailand	Agent	04-May	Covid 19 - travel restrictions
438	Map Ta Phut, Thailand	MMS	28-May	The current situation due to COVID-19 outbreak, PTTLNG terminal not allow to do sire inspection ,Please find attached PTTLNG's guideline for COVID-19 restriction for reference. Noted : The Civil Aviation Authority of Thailand (CAAT) has announced an extension of temporary ban on all international passenger flights to Thailand until 30 June 2020.
439	Map Ta Phut, Thailand	Shell, BP	07-Jun	Local inspector unavailable. (Covid-19 related)
440	Map Ta Phut, Thailand		1-8 Apr	

441	Maptaphut, Thailand	PTT	07-May	According to the "State of Emergency" declaration in Thailand and limitations of Terminal access granted in related to COVID-19 pandemic. PTT Inspection will not be able to assign during this period. Expected the situation will be released by end of this month.
442	Maptaphut, Thailand	Agents	14-Jun	Lockdown due to COVID19 - terminal restricitions also apply not even local inspectors allowed
443	Map-Ta-Phut, Thailand			Terminal not allowed or non-availability of any local inspector due COVID – 19
444	Maptaphut,Thailand	Agents	16-Jun	Lockdown due to COVID19 - terminal restricitions also apply not even local inspectors allowed
445	Maputo, Mozambique	Lukoil	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
446	Maputo, Mozambique	P66	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
447	Maputo, Mozambique	MAXCOM	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
448	Maputo, Mozambique	ENOC	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
449	Maputo, Mozambique	ENOC	14-Apr	COVID-19 – traveling restrictions.No local inspector available.
450	Maputo, Mozambique	Agenta	23-May	Covid 19 - travel restrictions
451	Marcus Hook, USA	CDI	13-Mar	Nominated inspector declined to attend due to COVID
452	Marcus Hook, USA	CDI	31-Mar	No inspector available due to travel restricions caused by COVID spread. Local inspector unavailable.
453	Marmara, Turkey			Terminal not allowed or non-availability of any local inspector due COVID – 19
454	Marmara, Turkey	IMT, BP,TOTAL,CHEVRON, SHELL.	10-Apr	Terminal lock down
455	Matosinhos, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information.These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
456	Mazatlan, Mexico		10-Apr	No local inspectors available
457	Mazatlan, Mexico	Chevron	15-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
458	Mazatlan, Mexico	PMI	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
459	Mazatlan, Mexico	Enoc	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
460	Mazatlan, Mexico	IMT	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
461	Mazatlan, Mexico	Shell	08-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
462	Mazatlan, Mexico	BHP	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

463	Mazatlan, Mexico	Total	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
464	Mejillones, Mexico	CDI	12-May	Local inspector unavailable. (Covid-19 related)
465	Melbourne, Australia	BHP	March	Inspection not allowed by Terminal due to COVID – 19
466	Merak, Indonesia	PHILLIPS66	13-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
467	Merak, Indonesia	ENOC	02-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
468	Merak, Indonesia	ENOC	07-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
469	Mesaieed, Qatar	Shell	19-May	OM - We regret we are unable to carry out the inspection at this time. We do not have any local inspectors available
470	Mesaieed, Qatar	BP	19-May	OM - our inspectors in the region are unable to make it due to travel restrictions in place for COVID-19 pandemic.
471	Mesaieed, Qatar	IMT	22-May	OM - Due to COVID-19 pandemic worldwide , with travel/border restrictions being imposed in many countries, we regret to inform that we are currently unable to arrange as your request.
472	Mesaieed, Qatar	TOTAL	22-May	OM - Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling.
473	Midia, Romania	All Majors/CDI	01-May	Inspections are not possible in Romania due to travel restrictions due to COVID-19 pandemic
474	Milazzo , Italy	ENI	1-8 Apr	
475	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
476	Mina Al Ahmadi, Kuwait	IMT	12-Apr	country under lockdown - travelling prohibited within country
477	Mina Al Ahmadi, Kuwait	CDI	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
478	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
479	Mina Al-Ahmadi, Kuwait	KOCH	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
480	Mina Al-Ahmadi, Kuwait	ENOC	10-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
481	Mina Al-Mahadi, Kuwait	BHP	06-May	Unfortunately the UAE /Gulf countries have not yet provided a clear indications as to when flights will resume. In that regards, visas too will not be issued.
482	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)

483	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
484	Mobile, Alabama	Koch	02-Apr	Declined inspection as no inspector available. Likely due to COVID19
485	Mobile, Alabama	Lukoil	10-Apr	Inspector could not make in time due to delay at travel checkpoints enroute
486	Mohammedia, Morocco	CDI	26-Apr	Local inspector unavailable. (Covid-19 related)
487	Mombasa, Kenya	BHP	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
488	Monroe Terminal, Philadelphia, USEC			Not permitted as vetting considered non essential
489	Monteverde, Portugal	P66, ConocoPhillips	01-Apr	Local inspector unavailable. (Covid-19 related)
490	Montoir, France			
491	Morocco	All Majors/CDI	10-Apr	Morocco is locked down due to COVID-19 and no inspections can be arranged
492	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
493	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
494	Muara, Brunei	ENOC	11-Jun	Covid 19 - travel restrictions
495	Muara, Brunei	BHP	11-Jun	Covid 19 - travel restrictions
496	Mumbai - JNPT, India	ENOC	03-Apr	Not possible due to COVID-19 Restrictions lockdown
497	Mumbai, India	Chevron	07-Apr	Travelling restrictions
498	Mumbai, India	Phillips 66	12-Apr	Complete lockdown in India due to COVID 19. No public or private transportation's are available.
499	Mumbai, India	ENOC	25-Apr	Covid 19 - travel restrictions
500	Mumbai, India	Lukoil	24-Apr	Covid 19 - travel restrictions
501	Mumbai, India	EQUINOR	15-May	Inspector while trying to attempt to go onboard the subject vessel for conducting SIRE inspection, he was unable to embark the vessel due to excessive swell (embarking on Eagle Victoria was aborted after making several attempts to board the vessel).
502	Mundra, India	Chevron	06-Apr	Travelling restrictions
503	Murmansk, Russia	SHELL	29-Apr	Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections Russia until further notice.
504	Murmansk, Russia	GAZPROM	28-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
505	Murmansk, Russia	LUKOIL	24-Apr	As per agents quarantine isolation for two weeks is imposed at airport for the passengers arriving from Moscow.
506	Murmansk, Russia	LUKOIL	22-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
507	Murmansk, Russia	TOTAL	18-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
508	Naantali, Finland	LUKOIL	25-Mar	E-mail from LUKOIL 23 March:We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.

509	Naantali, Finland	LUKOIL	25/03/2020	E-mail from LUKOIL 23 March:We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.
510	Nanjing, PRC	Shell, Preem	15-Apr	Local inspector unavailable. (Covid-19 related)
511	Nanjing, PRC	ConocoPhillips	15-Apr	All inspections paused due to Covid-19
512	Nanjing, PRC	CDI	06-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
513	Nansha, PRC	Shell	30-Mar	
514	Nansha, PRC	Shell	30-Mar	Covid 19 - terminal restrictions
515	Nantong, PRC	P66	27-Apr	Port authorities imposed 14 days quarantine for inspectors after inspection
516	Nantong, PRC	Lukoil	06-Jun	Covid 19 - travel restrictions
517	Napier, France	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
518	Napier, New Zealand	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
519	Napier, New Zealand	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
520	New plymouth, New Zealand	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
521	New plymouth, New Zealand	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
522	New Plymouth, New Zealand	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
523	New York, USA			
524	New York, USA	Lukoil	25-Apr	Lukoil cancelled the inspection due toCOVID-19.
525	Newcastle, Australia	IMT	Apr	Due to current rapidly increasing severity of COVID-19 pandemic worldwide and with travel/border restrictions being imposed in many countries, we regret to inform you that we are unable to arrange as your request for the subject vessel.
526	Newcastle, Australia			Terminal not allowed or non-availability of any local inspector due COVID – 19
527	Newyork / US	Total	14-Apr	Due to the unavailability of an inspector in the port
528	Ningbo, PRC	Koch	02-Apr	Terminal not allowed any visitors due to Covid-19
529	NingBo, PRC	Petron	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
530	NingBo, PRC	EQUINOR	03-Apr	Due to COVID-19 not permitted by terminal
531	Ningbo, PRC	BP	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
532	Ningbo, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.

533	Ningbo, PRC	Lukoil	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
534	Ningbo, PRC		25-May	COVID-19 restrictions
535	Nipah, Indonesia	IMT, Lukoil, Shell, BP, Maxcom	10-Apr	No inspectors available.
536	Nipah, Indonesia	Idemitsu	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
537	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-23
538	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-25
539	Ocoa Bay, Dominican Republic	All Majors	03-Apr	No local inspectors available in Dominican Republic
540	Omoa, Honduras	Equinor, KOCH	07-May	No available local inspectors; travelling restrictions
541	Onsan, SK		20-Mar	Due to COVID-19 not permitted by terminal
542	Onsan, SK	Shell	March	Inspection not allowed by Terminal due to COVID – 19
543	Ornskoldsvik, Sweden	Lukoil	29-Apr	Declined due to COVID-19 travel restrictions
544	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
545	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
546	Pajaritos, Mexico	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
547	Pajaritos, Mexico	Lukoil	05-May	Not Inspected. Terminal don't allow the permission for Vetting inspector.
548	Panama			Local restriction
549	Panama	BHP		Not permitted as didn't have local presence.
550	Panama	GAZPROM	09-Mar	Not permitted
551	Paradip, India		1-8 Apr	
552	Paradip, India	N/A	09-Apr	Other (National Lockdown - Travel restriction)
553	Paradip, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
554	Paranagua, Brazil			Imposed restrictions
555	Paranagua, Brazil	Equinor, P66, Koch, Shell	01-Apr	Local inspector unavailable.
556	Paranagua, Brazil	Equinor	03-Apr	Local inspector unavailable. (Covid-19 related)
557	Pasir Gudang, Malaysia	Petron	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic
558	Pembroke, UK	EQUINOR	22-May	Planned: According to information received from agent, terminal does not allow inspections to be carried out due to restrictions in force.
559	Pengerang, Malaysia		08-Apr	Due to COVID-19 not permitted by terminal
560	Pengerang, Malaysia	Petronas	14-Apr	MMS does not allow insepctor to stay overnight on vessel, As per terminal, inspector to board prior berthing and disembark upon depature from terminal

561	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-19
562	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-20
563	Peru	Repsol	24-Apr	Covid 19 - travel restrictions
564	Philippines	All Majors/CDI	29-May	Information: Inspections not permitted in Phillipines due to COVID-19 pandemic. All foreigners arriving Philippines need to serve 14 days quarantine period.
565	Pinkenba, Australia			
566	PISCO	KOCH	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
567	Pisco, Peru	EXXON	11-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
568	Point Comfort, USA	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)
569	Point Lisas, Trinidad & Tobago	Lukoil, Savonetta, SP#2 South & SP#4	30-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
570	Point Lisas, Trinidad & Tobago	CDI	21-Apr	Local inspector unavailable. (Covid-19 related)
571	Point Lisas, Trinidad & Tobago	Lukoil, Shell, Rightship, Equinor	10-Apr	Local inspector unavailable. (Covid-19 related)
572	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
573	Point Lisas, Trinidad & Tobago	CDI	05-Apr	Local inspector unavailable. (Covid-19 related)
574	Point Lisas, Trinidad & Tobago	CDI	25-Apr	Local inspector unavailable. (Covid-19 related)
575	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
576	Point Lisas, Trinidad and Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
577	Point Lisas, Trnindad and Tobago	All Majors	03-Apr	No local inspectors available in Point Lisas and airport closed down till furthe notice.
578	Port Allan, USA	EQUINOR	24-Apr	Covid 19 - travel restrictions
579	Port Allan, USA	ENOC	27-Apr	Covid 19 - travel restrictions
580	Port Dickson, Malaysia	Idemitsu	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic .
581	Port Dickson, Malaysia	CDI	16-Apr	lockdown due to COVID19 - Foreign inspectors not allowed to travel to Malaysia
582	Port Elizabeth, South Africa		16-Apr	no visitor/inspector allowed due to Covid-19

583	Port Elizabeth, South Africa	CDI	04-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
584	Port Esquivel, Jamaica	BHP	30-Mar	
585	Port Esquivel, Jamaica	BHP	30-Mar	Covid 19 - travel restrictions
586	Port Esquivel, Jamaica	Maxcom	01-Apr	Covid 19 - travel restrictions
587	Port Everglades, USA	ENOC	24-Apr	Local inspector unavailable. (Covid-19 related)
588	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
589	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
590	Port Klang, Malaysia	CDI	01-May	Malaysia lock down till 12th May as per message from agents. Only local inspectors allowed to carry out the inspection subject to terminal permission. CDI does not have any local inspector in Malaysia.
591	Port Louis, Mauritius	CDI	01-Jun	Local inspector unavailable. (Covid-19 related)
592	Port Moresby, Papua New Guinea	Chevron, BHP	27-May	Due to the COVID-19 travel restrictions
593	Port Moresby, Papua New Guinea	Chevron	27-May	Due to the COVID-19 travel restrictions
594	Port Moresby, Papua New Guinea	BHP	25-May	A local inspector is unavailable. (Covid-19 related)
595	Port Moresby, Papua New Guinea	Equinor	02-Jun	Papua New Guinea that no shoreside personell are permitted onboard any vessels
596	Port Reunion	CDI	03-Apr	No local inspectors available.
597	Port Said, Egypt	Gazprom	28-Apr	Complete lockdown No Vetting inspections allowed
598	Port Said, Egypt	CDI	24-May	Local inspector unavailable. (Covid-19 related)
599	Pozos Colorados, Colombia			
600	Priolo, Italy	CDI	28-May	
601	Pt. Lisas, USA	CDI	08-Apr	Due to the current travel restrictions CDI unable to assign inspector at T & T
602	Puerto Bahia, Colombia		10-Apr	No inspectors available
603	Puerto Cortes, Honduras	CDI	14-Apr	Covid 19 - travel restrictions
604	Puerto Cortes, Honduras	Agents	14-Apr	Covid 19 - travel restrictions
605	Puerto Moin, Costa Rica	Lukoil	04-May	Not Inspected. Vetting inspections are not allowed to be performed alongside (only at anchorage)
606	Puerto Santo Tomas, Guatemala			Terminal not allowed or non-availability of any local inspector due COVID – 19

607	Pyeongtaek, South Korea	CDI, SPTT	17-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
608	Qidong, PRC	ENOC	06-Apr	Terminal restrictions
609	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
610	Qingdao, PRC	ENOC	01-May	Terminal restrictions
611	Qingdao, PRC	Petron	05-May	Terminal rejection of the inspector
612	Qingdao, PRC			
613	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
614	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
615	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
616	Qingdao, PRC	BHP	13-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
617	Qingdao, PRC	PHILLIPS66	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
618	Qingdao, PRC	TOTAL, P66	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
619	Qingdao, PRC	SHELL	11-Jun	Pls be advised inspector is not allowed to get on board according to Qingdao terminal's latest regulation. Fyi: No person is allowed to get on board except boarding agent and CIQ officers.
620	Quanzhou, China	Lukoil, Powershell Terminal	11-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
621	Quanzhou, PRC	P66	Mar-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
622	Quanzhou, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
623	Quanzhou, PRC	TOTAL	04-Jun	Due to unavailability of local inspector
624	Quanzhou, PRC	P66	05-Jun	Agents cannot confirm that permit will be granted by local authorities
625	Quintero, Chile	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
626	Quintero, Chile	Marathon	16-Apr	Due to COVID-19, the terminal is no allowing inspections
627	Quintero, Mexico			
628	Rades, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions
629	Ras Al Khair, Saudi Arabia	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
630	Ras Al Khair, Saudi Arabia	ENOC	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
631	Ras Al Khair, Saudi Arabia	Adnoc, Rightship, Koch, Shell	10-Apr	Local inspector unavailable. (Covid-19 related)
632	Ras Al Khair, Saudi Arabia	CDI	14-Mar	Local inspector unavailable. (Covid-19 related)
633	Ras Al Khair, Saudi Arabia	CDI	10-Apr	Local inspector unavailable. (Covid-19 related)

634	Ras Laffan, Qatar		23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
635	Ras Tanura, Saudi Arabia	ENOC	31-Mar	Covid 19 - travel restrictions
636	Ras Tanura, Saudi Arabia	Maxcom	31-Mar	Covid 19 - travel restrictions
637	Ras Tanura, Saudi Arabia	BHP	01-Apr	Covid 19 - travel restrictions
638	Ras Tanura, Saudi Arabia	ENI	01-Apr	Covid 19 - travel restrictions
639	Ras Tanura. Saudi Arabia	ENOC, Maxcom, BHP, ENI	01-Apr	
640	Ras Tanurah, Saudi Arabia	Adnoc, Saudi Aramco, Total, Lukoil, P66	26-Apr	Local inspector unavailable. (Covid-19 related)
641	Rayong, Thailand		27-Apr	Agents - Covid 19 - travel restrictions
642	Reunion	CDI	03-Apr	No local inspectors available.
643	Richard's Bay, South Africa	Rightship, Total, Shell, Neste, Respol, YPF, Conocophilips,Preem	23-Apr	Local inspector unavailable. (Covid-19 related)
644	Richmond, USA	Lukoil	03-Apr	Not possible due to COVID-19 Restrictions. Only critical personnel allowed.
645	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.
646	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.
647	Rijeka, Croatia	LUKOIL	10-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
648	Rio Grande, Brazil			Imposed restrictions
649	Rio Haina, Dominican Republic	CDI	09-May	Local inspector unavailable. (Covid-19 related)
650	Rizhao, PRC	Shell and Maxcom	25-Jan	Inspector's not willing to go due to COVID19
651	Rizhao, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
652	Rizhao, PRC	Chevron	08-May	No available local inspectors; travelling restrictions
653	Rizhao, PRC	P66	05-Jun	Covid 19 - travel restrictions
654	Rizhao, PRC		1-8 Apr	

655	Rotterdam, Netherland	CDI	20-Mar	Inspector refused travelling to Rotterdam due to airport closure at ISLE OF MAN
656	Rotterdam, Netherlands	SHELL	25-May	We regret we are unable to carry out the inspection at this time, as we do not have any local inspectors available. Please request again at a later date.
657	Rotterdam, Netherlands	Equinor	08-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
658	Rovigo, Itali	Shell	05-May	Inspector required to embark by launch
659	Rovigo, Itali	Repsol	05-May	Inspection deemed 'not exceptional' due to Covid-19
660	Rovigo, Itali	BP	05-May	Inspection declined as inspector would have had to remain onboard overnight
661	Rudong, PRC	Phillips66	03-Apr	Terminal restrictions
662	Ruwais, Qatar	Shell	22-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
663	Ruwais, Qatar	Adnoc, Total, Preem, P66	22-Apr	Local inspector unavailable. (Covid-19 related)
664	Ruwais, Qatar	Bienco	22-Apr	No response from OM
665	Ruwais, UAE	ADNOC	12-Apr	Travel restrictions due to COVID - Terminal restrictions due to security sensitivity of the area
666	Sabine Pass, USA	Rightship, Shell	25-May	Cancelled due to unsafe access - adjusted boarding measures (Covid-19 related)
667	Sabine Pass, USA	BP	28-May	
668	Saint Nicolas, France	CDI	20-May	Local inspector unavailable. (Covid-19 related)
669	Saldana Bay, South Africa	BHP, P66	04-Apr	other - complete lockdown due to COVID19
670	Salina Cruz, Mexico	Lukoil	16-Apr	Foreign Inspector travel ban
671	Salina Cruz, Mexico	P66	16-Apr	Foreign Inspector travel ban
672	Salvador, Brazil	ENOC	23-Apr	Planned - Due to COVID-19 I will not be able to attend you in Salvador as I am requiring flight from Rio De Janeiro. I can attend you in Rio De Janeiro or in São Sebastião therefore keep me posted when you have program to attend one of these two ports.
673	Salvador, Brazil	ENOC	01-May	Inspector is unable to attend at this call due to prior commitments.
674	Salvador, Brazil	ENOC	01-May	The inspector is unable to attend at this call due to prior commitments. Please advise us her next convenient port.
675	Salvador, Brazil	KOCH	43977	Terminal Change policy - access through terminal forbidden
676	Santos, Brazil			Imposed restrictions
677	Santos, Brazil	Koch, Petrobras	02-Apr	Local inspector unavailable.
678	Santos, Brazil	Phillips66	13-Apr	
679	Santos, Brazil	Shell, BHP	14-Apr	Shell - Not covering; BHP Not performing inspection.
680	Santos, Brazil	Petrobras	15-Apr	Petrobras - Not performing inspections until further, KOCH - No available local inspectors; travelling restrictions
681	Santos, Brazil	Shell	01-May	Not covering

682	Santos, Brazil	ENOC	02-May	
683	Sao Luis, Brazil	Idemitsu	18-Mar	
684	Sariaya, Philippines	BHP-Rightship, Equinor	24-Apr	Inspection cancelled.
685	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
686	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
687	Sfax, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions
688	Shanghai, China	Shell	March	Inspection not allowed by Terminal due to COVID – 19
689	Shiudong, PRC	Lukoil	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
690	Shiudong, PRC		08-May	Inspector who is from abroad is not permitted to come for inspection. Chinese is permitted. If inspector is Chinese , he need to arrive Maoming for quarantine 3 days before on board, and go to hospital for Nucleic acid detection.Launch cost to the terminal will be around 18,000/-USD
691	Shuidong, PRC	BHP	28-May	Covid 19 - travel restrictions
692	Shuidong, PRC	Alma	29-May	Covid 19 - travel restrictions
693	Sierra Leone	Lukoil, Alma	29-Mar	
694	Sierra Leone & Conakry	Lukoil & Alma	29-Mar	Covid 19 - travel restrictions
695	Sikka India	IDEMITSU	12-May	Lockdown in India due to Covid 19 pandemic.
696	Sikka, India	CDI	30-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
697	Sikka, India		1-8 Apr	
698	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
699	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
700	Sines, Portugal			Imposed restrictions
701	Sines, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information.These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
702	Sines, Portugal	Lukoil, POT, Saras, Maxcom, Erg, Neste	20-Apr	No local Inspectors and Covid-19 travel restrictions
703	Sines, Portugal	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC	20-Apr	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC - Local inspector unavailable. (Covid-19 related)
704	Sines, Portugal	Cepsa	01-May	Declined due to COVID-19 travel restrictions

705	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
706	Singapore	Enoc	21-Apr	Due to terminal restriction (Singapore Petrochemical Complex Olefin I)
707	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
708	Singapore	Idemitsu	19-May	Singapore Terminal Restricted for inspection due to COVID 19 pandemic
709	Singapore	Idemitsu	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
710	Singapore, Shell Bukom	Gazprom	17-Apr	Terminal declined inspector's boarding at their terminal due to COVID 19
711	Singapore, Vopak Penjuru	Gazprom	15-Apr	Rejected due to terminal disapproved of any visitors or auditor during current Covid -19 situation
712	Sohar, Oman	CDI, Oiltanking Odfjell	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
713	Sohar, Oman	BHP, Equinor, Gazprom, Repsol, KOCH, ENI, P66,Lukoil, BP, Total, ENOC	30-Apr	Local inspector unavailable. (Covid-19 related)
714	Sohar, Oman	Shell, BP	10-May	Local inspector unavailable. (Covid-19 related)
715	Sohar, Oman	All Majors/CDI	15-May	All routes closed in Oman, foreigners cannot arrive to carry out inspection due to COVID-19
716	Sohar, Oman	Equinor	21-May	Due to travel restrictions imposed by the covid19 outbreak, there are no inspectors available to cover.
717	Sohar, Oman	ENOC, ADNOC, KOCH	21-May	Local inspectors not available; travelling restrictions
718	Sohar, Oman	Idemitsu	22-May	No available local inspectors; travelling restrictions
719	Sohar, Oman	Equinor, ENOC, ADNOC, Idemitsu, KOCH	29-May	Local inspector unavailable. (Covid-19 related)
720	South Africa ports		02-Apr	Heighted level of Security level protocols within the South African Port System during the lockdown period.
721	Southwold, UK	Chevron/Total/Equinor/Shell	25-May	Declined due to unavailability of inspectors
722	Southwold, UK	Lukoil	10-Jun	delay operations
723	Sri Racha, Thailand			Not permitted

724	Sri Racha, Thailand	Lukoil	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
725	St' Charles, Barbados	BHP	02-Apr	Last muute cancellation as terminal change policy - no visitor/inspector allowed due to COVID19
726	St Croix, US Virgin Islands		02-Apr	Not possible due to COVID-19 restrictions
727	St Croix, USA (Virgin Island)	TOTAL	20-Apr	Local inspector unavailable. (Covid-19 related)
728	St. Eustatius		14-Apr	Not possible due to COVID-19
729	St. James, LA USA	Maxcom	01-May	No local inspector available in Louisiana (covid-19 related) normal Texas based inspector to attend but not ready to serve quarantine period when return to Texas
730	Stenungsund, Sweden	CDI	17-Mar	Nominated Inspector declined due to COVID
731	Stignaes, Denmark			Imposed restrictions
732	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April. We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
733	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April. Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
734	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April. Thank you for your email. Please note we not have any local inspectors in Sweden.
735	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April: We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
736	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April: Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
737	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April: Please note we not have any local inspectors in Sweden.
738	Suape, Barzil	IMT/SHELL/CHEVRON	15-May	Due to COVID-19 travel restrictions
739	Suape, Brazil			Imposed restrictions
740	Suape, Brazil	ENOC	17-Apr	Due to COVID 19 travel restrictions we are unable to attend the vessel.
741	Suape, Brazil	IMT/SHELL/CHEVRON	15-May	Due to COVID-19 travel restrictions
742	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
743	Suez, Egypt	Agents	22-May	Covid 19 - travel restrictions
744	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
745	Suez, Egypt	IMT	29-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
746	Sumed, Egypt	Lukoil	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.

747	Sumed, Egypt	Shell	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
748	Taicang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
749	Taicang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
750	Taicang, PRC	Maxcom, ALMA, BHP,Lukoil	14-Apr	Covid 19 - travel restrictions
751	Taicang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
752	Taicang, PRC	BP	09-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
753	Taicang, PRC	Idemitsu	29-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
754	Taicang, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
755	Taicang, Taiwan	Petron, P66	05-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
756	Taichung, Taiwan	Koch, Shell, Total, Rightship, Adnoc	20-Apr	Local inspector unavailable. (Covid-19 related)
757	Taichung, Taiwan	BHP, Gazprom	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
758	Tainjin, PRC			
759	Taipei, Taiwan	CDI	27-Apr	Travel/border restrictions being imposed due to COVID-21
760	Taixing, PRC		10-Apr	Terminal didn't allowed
761	Taixing, PRC	CDI	11-Apr	Terminal rejected additional personnel to enter.
762	Taixing, PRC	Lukoil	01-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
763	Taizhuo, PRC	Lukoil	08-May	Covid 19 - travel restrictions
764	Taizhuo, PRC	Agent	07-May	Covid 19 - travel restrictions
765	Tallinn, Estonia	Lukoil	16-Apr	
766	Tallinn, Portugal	LUKOIL	16-Apr	
767	Tamatave, Madagascar (Toamasina)	Maxcom	16-Apr	Covid 19 - travel restrictions
768	Tamatave, Madagascar (Toamasina)	Lukoil,Total,BHP, ENOC,P66,Aethon,Koch, agents	14-Apr	Covid 19 - travel restrictions
769	Tangier MED, Morroco	ENOC	02-Apr	Travelling restrictions
770	Tangier, Morocco		07-Apr	Not allowed due to COVID-19 restrictions
771	Tangier, Morocco	IPLOM	09-Jun	Due to local restrictions imposed the permission to drive/travel to Port-Tangier
772	Tanjung Pelepas, Malaysia	KOCH	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
773	Tanjung Pelepas, Malaysia	P66	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.

774	Tanjung Bin, Malaysia	Koch	26-Mar	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
775	Tanjung Priok, FSRU Nusentara, Indonesia	BP	10-May	Travel restriction imposed in th country due to COVID 19.
776	Tarragona, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
777	Tarragona, Spain	Equinor	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
778	Tarragona, Spain	Equinor	05-Jun	no European inspectors are available in Tarragona due to travel restrictions
779	Tarragona, Spain	SHELL	04-Jun	Due to the use of barge / launch boat
780	Tauranga, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
781	Tauranga, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
782	Teesport, UK	Exxon	02-Apr	No available local inspectors; travelling restrictions
783	Tema, Ghana	CDI	19-Mar	Local inspector unavailable. (Covid-19 related)
784	Tema, Ghana	ENOC, KOCH	30-Apr	Local inspector unavailable. (Covid-19 related)
785	Tetney, UK	BP	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
786	Tetney, UK	EQUINOR	13-Apr	Local inspector unavailable.
787	Tetney, UK	BP	20-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
788	Thanh Hoa, Vietnam	PETROVIETNAM KOCH	16-Jun	We have only one local inspector and he will cover few inspections of other vessels from 14 to 20 June. So he will not be available to cover inspection of your vessel. Regret to inform you that we will not be able to arrange the subject vessel inspection, due to the Covid19, Vietnamese Government still not allow International flights up to now.
789	Thanh Hoa, Vietnam	PETROVIETNAM KOCH	16-Jun	We have only one local inspector and he will cover few inspections of other vessels from 14 to 20 June. So he will not be available to cover inspection of your vessel. Regret to inform you that we will not be able to arrange the subject vessel inspection, due to the Covid19, Vietnamese Government still not allow International flights up to now.
790	Thessaloniki, Greece	P66	07-May	Local inspector unavailable. (Covid-19 related)

791	Thessaloniki, Greece	Repsol	07-May	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
792	Tianjin, PRC	CDI	10-Apr	No inspection was not allowed by port authority
793	Tianjin, PRC	IMT, Chevron, Shell, Total	Feb	Inspection not allowed by Terminal due to COVID – 19
794	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
795	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
796	Tianjin, PRC	Lukoil	28-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
797	Tianjin, PRC	Equinor, BHP, Gazprom, Lukoil, KOCH, Idemitsu	09-Feb	Inspector's not willing to go due to safety/health reasons + terminal change policy - no visitor/inspector allowed due to Covid-19.
798	Tianjin, PRC	CDI	11-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
799	Tokuyama, Japan	Equinor, Idemitsu	04-Jun	Regret inform you that we are unable to attend this vessel at Tokuyama. We regret to say we could not find the inspector able to attend your good vessel tomorrow. Sorry for causing your inconvenience.
800	Townsville, Australia	Chevron	March	Inspection not allowed by Terminal due to COVID – 19
801	Tramandai, Brazil	Lukoil	18-Apr	Due to the COVID-19 travel restrictions (Unavailability of Flights)
802	Tramandai, Brazil		24-Apr	Not allowed due to COVID-19 restrictions
803	Tramandai, Brazil	Lukoil	07-May	Covid 19 - travel restrictions
804	Tramandai, Brazil	PMI	04-May	Covid 19 - travel restrictions
805	Tramandai, Brazil	Koch	03-May	Covid 19 - travel restrictions
806	Tramandai, Brazil	Maxcom	02-May	Covid 19 - travel restrictions
807	Tranmere, UK	ENOC	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
808	Tuban, Indonesia	ENOC	05-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
809	Tuban, Indonesia	Rightship	07-Apr	Not possible due to border closures and quarantine requirements due to COVID-19

810	Tuban, Indonesia	Cocophillips	16-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
811	Tuban, Indonesia	Exxon, P66	16-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
812	Tuban, Indonesia	ENOC	12-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
813	Tuticorin, India	CDI	19-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
814	Tuxpan, Mexico	VIVO	31-Mar	
815	Tuxpan, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
816	Tuxpan, Mexico			Do not allow inspectors onboard.
817	Ulsan, SK	NESTEOIL	22-May	(Planned) - Neste not performing any inspections due to the COVID 19 situation.
818	Ulsan, SK	IMT,SHELL	10-Apr	Travel restriction
819	Ulsan, SK	All Majors/CDI	15-May	SK Energy terminal in Ulsan do not permit any inspections to be carried out during cargo operations. Option provided is to carry out the inspection at anchorage which will be an idle inspection and not serve the purpose.
820	Ust Lega,Russia	EXXON	07-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels. We will maintain our pragmatic approach in evaluating TC vessels and SIRE inspections reports will be reviewed on a case by case basis accordingly
821	Ust Lega,Russia	EXXON	07-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
822	Vadinar, India			
823	Vadinar, India	Maxcom	09-Apr	Covid 19 - travel restrictions
824	Vadinar, India	BHP	06-Apr	Covid 19 - travel restrictions
825	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
826	Vadinar, India	ENOC	01-May	Covid 19 - travel restrictions
827	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
828	Valencia, Spain	BHP	29-May	OM - Unfortunately do not have available inspectors and will decline inspection due to current health/virus/quarantine /travel problems , no flights etc..
829	Valencia, Spain	P66	29-May	OM - Unable to schedule the inspection due to the conflict that the Suggested date is within 30 days of an already planned SIRE/OVID inspection with another member.
830	Vatso, Italy	CDI	March	Inspection not allowed by Terminal due to COVID – 19
831	VeraCruz, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
832	VeraCruz, Mexico			Do not allow inspectors onboard.
833	Veracruz, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
834	Veracruz/Altamira, Mexici	CDI	14-Apr	Covid 19 - travel restrictions

835	Vietnam OPL	P66 / PTT	14-Jun	Others – due to COVID-19 travel restrictions
836	Virgin Islands, USA	All Majors/CDI	10-Apr	All ports in USVI is locked down due to COVID-19 and no inspections can be arranged
837	Vizag, India	Koch	08-Apr	Other (National Lockdown - Travel restriction)
838	Vizag, India	CDI	15-Apr	India lockdown due to COVID
839	Vizag, India	Koch	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
840	Vizag, India	Equinor	20-May	Due to several restrictions imposed by the covid-19 outbreak on this given location, the inspector will not be able to attend.
841	Vizag, India	Koch	06-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
842	Vizag, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
843	Vungtau, Vietnam	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
844	Vungtau, Vietnam	NESTEOIL	02-May	At this moment Neste does not carry out sire inspection
845	Vungtau, Vietnam	P66	02-May	Travel/border restrictions being imposed due to COVID-20
846	Walvis Bay, Namibia		April	Namibian authorities suspended Visa issue for 1 month thus NO inspector available
847	Walvis Bay, Namibia	BHP	06-Apr	Lockdown in that area and restricted movement by air, road or rail Not be possible to inspect the subject vessel.
848	Walvis Bay, Namibia	BHP	06-Apr	Local inspector unavailable.
849	Wenzhou, PRC		10-Apr	Terminal didn't allowed
850	Whiffenhead, Canada	BP	16-Apr	Foreign Inspector travel ban
851	Wilhelmshaven, Germany			Imposed restrictions
852	Wilhelmshaven, Germany	BP	29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
853	Yabucaco, Puerto Rico	ENOC/BHP/Lukoil/Equinor	03-Apr	Not possible due to COVID-19 Restrictions
854	Yanbu, Saudi Arabia	ADNOC	28-Apr	Travel restrictions - Lockdown
855	Yanbu, Saudi	Enoc	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
856	Yanbu, Saudi	Shell	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
857	Yanbu, Saudi Arabia	CDI, Koch, Shell	12-Apr	Other (National Lockdown - Travel restriction)
858	Yanbu, Saudi Arabia	CDI	11-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
859	Yanbu, Saudi Arabia	CDI / Gas	26-May	No available local inspectors; travelling restrictions
860	Yanbu, Saudi Arabia	CDI	01-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

861	Yanbu, Saudia Arabia	Koch	29-Apr	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
862	Yangpu, PRC	Idemitsu	12-Apr	No inspection was not allowed at the terminal
863	Yangpu, PRC	Idemitsu	12-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
864	Yangpu, PRC	CDI	17-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
865	Yangshan, PRC	MMS	16-May	Present stage, visitor is not allowed in Yangshan LNG terminal.
866	Yantai, PRC	Chevron, Shell, Koch,	Feb	Inspection not allowed by Terminal due to COVID – 19
867	Yantai, PRC	Lukoil, P66	21-Feb	Local inspector unavailable. (Covid-19 related)
868	Yantai, PRC	CDI	21-Feb	Local inspector unavailable. (Covid-19 related)
869	Yeosu, SK		05-Jan	Terminal poilcyy- no visitor/inspector allowed due to Covid-19
870	Yeosu,SK		25-Mar	Due to COVID-19 not permitted by terminal
871	Yeosu,SK	EXXON	08-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
872	Yingkou, PRC	NA	17-May	The following restrictions applies: 1. Inspector should hold Two times (24 interval) nucleic acid testing before onboard date. (Send agent the test reports and other required documents in advance) a. Test can be done at local hospital, 1st test to be done 7 days prior to attendance. 2. 14 days isolation in Yingkou hotel arranged by local port authorities after departure from vessel 3. Other documents will inform him directly if confirmed. 4. Inspectors will most preferably not from the high risk area. (HUBEI, JILIN, HEILONGJIANG province)
873	Yingkou, PRC	Shell, BIECO, Idemitsui	16-17- Jun	No visitor/inspector allowed due to Covid-19.
874	Yingkou, PRC	GAZPROM	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
875	Yizheng, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
876	Yokkaichi, Japan	Shell	15-Jun	Launch service required
877	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
878	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
879	Yumurtalik, Turkey	CDI	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
880	Yung An, Taiwan			
881	Yung An, Taiwan	Chevron	02-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan

882	Yung An, Taiwan	KOCH	01-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
883	Yung An, Taiwan	GAZPROM	15-Apr	Local inspector unavailable.
884	Yung An, Taiwan	BP	14-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
885	Zeebrugge, Belgium	REPSOL	14-Apr	Other - Due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
886	Zeebrugge, Belgium	PREEM	05-May	Inspector refused to follow precautions stipulated by the Company SMS.
887	Zhangjiagang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
888	Zhangjiagang, PRC	Maxcom ALMA, BHP, LukOil,	14-Apr	Covid 19 - travel restrictions
889	Zhangjiagang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
890	Zhangjiagang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
891	Zhangjiagang, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
892	Zhangjiang, PRC	BP	18-Feb	As per BP's message they stated due to terminal restrictions but found out inspector did not want to use launch boat as we managed to book inspection with another oil major
893	Zhapu, PRC	BP	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
894	Zhapu, PRC	Lukoil, BHP Rightship	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
895	Zhapu, PRC	Petron/Chevron	09-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
896	Zhoushan, PRC	Shell	02-Apr	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
897	Zhoushan, PRC	ENOC	13-Apr	Terminal restrictions
898	Zhoushan, PRC		21-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
899	Zhoushan, PRC	SHELL	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
900	Zhoushan, PRC	SHELL	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

901	Zhoushan, PRC		08-May	Terminal restriction for sire inspection is in place.
902	Zhoushan,PRC	EQUINOR	14-May	Terminal poilcy- no visitor/inspector allowed due to Covid-19
903		BASF	Apr	Rejected for business based on CDI more that 12 months old / no pyhsical CDI could be completed prior to last CDI expiring 12mnths.