

Date : 15/06/2020

INSPECTION CANCELLED OR DECLINE				
No	Port	OM	Date	Remark
1	Adelaide, Australia	Koch, Shell	March	Inspection not allowed by Terminal due to COVID – 19
2	A Corunna, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
3	A.D.Reis, Brazil	EQUINOR	05-Jan	Declined due to travel restrictions
4	A.D.Reis, Brazil	TOTAL	05-Apr	Declined due to unavailability of inspectors
5	Abidjan, Ivory Coast	CDI	15-Mar	Local inspector unavailable. (Covid-19 related)
6	Adabiyah, Egypt	Statoil	22-Apr	No flights into Egypt, Statoil cancelled request
7	Adabiyah, Egypt	CDI	25-May	Rejected for business based on SIRE more than 6 months old / no physical SIRE could be completed prior to last SIRE expiring 6mths/12mths.
8	Adelaide, Australia	Shell, BP, Idemitsu, Viva	April	Inspection not allowed as interstate travel is restricted due to Covid 19
9	Ain Sukhna Sonkar Terminal, Egypt	Shell	20-May	Others – Unable to carry out the inspection at this time, do not cover this Country.
10	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
11	Ain Sukhna, Egypt	Lukoil, Adnoc, Maxcom	03-May	Covid 19 - travel restrictions
12	Ain Sukhna, Egypt	ENOC	02-May	Covid 19 - travel restrictions
13	Ain Sukhna, Egypt	P66	04-May	Covid 19 - travel restrictions
14	Ain Sukhna, Egypt	MOH	04-May	Covid 19 - travel restrictions
15	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
16	Alcudia, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
17	Alexandria, Egypt	Enoc	18-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
18	Alexandria, Egypt	Koch	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
19	Alexandria, Egypt	Maxcom	23-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
20	Aliaga, Turkey			Imposed restrictions
21	Aliaga, turkey	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
22	Aliaga, Turkey	All Majors/CDI	15-May	Inspections not permitted to be carried out due to COVID-19. Local inspector was appointed, however he was denied entry to the terminal for the purpose of inspection.
23	Aliaga, Turkey	GAZPROM	09-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

24	Aliaga, Turkey	GAZPROM	09-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
25	AL-Jubail, Saudi Arabia	Idemitsu	15-Jun	All air-flights to or from Saudi Arabia has been suspended due to COVID-19 until further instructions.
26	All ports in India	All Majors	03-Apr	Locked down till 14-Apr, no inspections can be scheduled
27	Altamira, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
28	Altamira, Mexico			Do not allow inspectors onboard.
29	Altamira, Mexico	Maxcom	27-Mar	All arranged, port closed over night for non-locals, even as inspector was Mexican
30	Altamira, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
31	Altamira, Mexico	Maxcom	08-May	Covid 19 - travel restrictions
32	Altamira, Mexico	ALMA	07-May	Covid 19 - travel restrictions
33	Altamira, Mexico	ENOC	07-May	Covid 19 - travel restrictions
34	Amsterdam, Netherland	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
35	Amsterdam, Netherland	P66	Apr	No inspector available
36	Amsterdam, Netherlands	Neste	18-May	At this moment Neste does not carry out any sire inspections.
37	Antifer, France	BP	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
38	Antwerp, Belgium	Gazprom	06-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. From agent: We received terminal ATPC instructions from that due COVID nobody is allowed on the terminal anymore till further notice
39	Arzew, Algeria		07-Apr	Not allowed due to COVID-19 restrictions
40	Arzew, Algeria	CDI	27-May	Local inspector unavailable. (Covid-19 related)
41	Ashklelon, Isreal	Gazprom	04-Mar	Last minute cancellation as inspector's were not allowed to enter Israel if previously travelled to high risk COVID19 countries in Europe
42	Aughinish, Ireland	P66	25-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
43	Aughinish, Ireland	Koch, VIVO	25-Apr	Local inspector unavailable. (Covid-19 related)
44	Augusta, Sicily	BHP	29-May	The Sicily region have still travel limitation until at least the 7th June. Not residents in Sicily cannot travel to Augusta. In view of restriction, we will decline the inspection invitation.
45	Aviero, Portugal	CDI	28-Mar	Terminal requirements not to allow any inspections due to COVID-19
46	Bahia Blanca, Argentina	KOCH, Idemitsu	31-Mar	Local inspector unavailable. KOCH and Idemitsu were not able to find available inspectors due to COVID
47	Banática, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
48	Bangkok & Maptaphut, Thailand	PTT	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
49	Banjul, SK	Maxcom	16-Apr	Covid 19 - travel restrictions
50	Banjul, SK	Maxcom	15-Apr	Covid 19 - travel restrictions
51	Banjul, SK	Total, ENOC, Maxcom	14-Apr	Covid 19 - travel restrictions

52	Banjul, SK	BHP	14-Apr	Covid 19 - travel restrictions
53	Banjul, SK	Aethon/Koch	14-Apr	Covid 19 - travel restrictions
54	Barcelona, Spain	Cepsa	01-Jun	Declined on 20 May 2020 due to COVID-19 travel restrictions
55	Barranquilla, Colombia	BEICO	10-Apr	Port does not allow till further notice.
56	Basamuk, PNG			
57	Bataan, Philiphine	PETRON	18-May	Regret to inform you that visiting inspector is not allowed as of the moment due to COVID-19 and we are still on community quarantine until May 30.
58	Beaumont, USA	Exxon/IMT	05-Apr	
59	Beira, Mozambique	ENOC	20-May	Covid 19 - travel restrictions
60	Beira, Mozambique	P66	27-Apr	Local inspector unavailable. (Covid-19 related)
61	Beira, Mozambique	Lukoil	27-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
62	Belem, Barzil	Petrobras	10-Apr	Petrobras are not carrying out inspections worldwide due to COVID-19
63	Belize	EQUINOR	19-May	Covid 19 - travel restrictions
64	Belize,	Equinor	01-Jun	Covid 19 - travel restrictions
65	Benicia, CA, USA	Phillips66	07-Apr	Terminal not allowed
66	Bilbao, Brazil			Imposed restrictions
67	Bilbao, Spain	PETRONOR	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
68	Bintulu OPL, Malaysia	Petronas	20-Apr	During Movement Control Order period, all personal enter Sarawak have to be complete compulsory quarantine for 14 days at hotel / hospital arrange by local government. After complete compulsory quarantine 14 days, auditor to need pass Port health screening before permitted to board vessel at anchorage. As per the above and also travel restrictions and safety of the inspector; we regret to inform cannot cover the inspection.
69	Bintulu, Malaysia	MMS	27-May	Due to COVID-19 and movement restriction, inspector need to be quarantine at Sarawak for 14 days before the inspection.
70	Bizerte, Tunisia	BP	09-Jun	short notice
71	Bizerte, Tunisia	Shell	08-Jun	unable to conduct inspection in Tunisia
72	Bonny, Nigeria	Petron	16-May	Terminal change policy – visitor/inspector need 14 days quarantine due to Covid-19.
73	Bontang , Indonesia	Idemitsu	17-Apr	No available local inspectors; travelling restrictions
74	Bordeaux, France	EQUINOR	17-May	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available for the given port/date to cover this request at the moment.
75	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
76	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
77	Botany Bay,	VIVA	15-Apr	Local inspector unavailable.
78	Botany Bay, Australia	Ampol	02-Apr	Due to situation of Coronavirus outbreak, OM are unable to process the inspection request.

79	Botany Bay, Australia	BP, Total, IMT, Lukoil, Ampol and Shell	10-Apr	Shell eventually took the inspection but finally terminal did not allow.
80	Botany Bay, Australia	BP	02-Apr	Travel restriction imposed in th country due to COVID 19
81	Bourgas, Bulgaria	SHELL	09-Apr	Local inspector unavailable.
82	Bourgas, Bulgaria	BP	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
83	Bourgas, Bulgaria	Chevrom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
84	Brisbane, Australia		03-Apr	Allowed- boarding of inspectors only 3hours after berthing. Check with agents.
85	Brunei	Gazprom, idemitsu, Equinor, Maxcom	04-Apr	other - complete lockdown due to COVID19
86	Brunei	All Majors/CDI	29-May	Information: Inspections not permitted in Brunei due to COVID-19 pandemic. All foreigners arriving Brunei need to serve 14 days quarantine period.
87	Burgas, Bulgaria	All Majors/CDI	01-May	Bulgaria is locked down due to COVID-19
88	Busan, SK		05-May	Not possible due to COVID 19 restrictions
89	Busan, SK		05-May	Not possible due to COVID 19 restrictions
90	Cabo Negro, Chile	CDI	16-May	Other - Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
91	Cabo Negro, Chile	CDI	16-May	Local inspector unavailable. (Covid-19 related)
92	Cabo Negro, Morocco	CDI	16-May	Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
93	Cabo Negro, Morocco	CDI	16-May	Local inspector unavailable. (Covid-19 related)
94	Caldera, Chile	Marathon	22-Apr	Terminal restriction
95	Callao, Peru	ConocoPhillips	23-Apr	ConocoPhillips declined request due to Covid
96	Callao, Peru	CDI	08-May	Local inspector unavailable. (Covid-19 related)
97	Canaport, Canada	Chevron	17-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
98	Canaport, Canada	Equinor	15-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
99	Canaport, Canada			Terminal quarantines vessel if inspector boards prior berthing. Not permitted during discharge. Vessel must be at sea for >14 days prior berthing. Post discharge you are allowed everything at the anchorage.
100	Caoger Bay, South Africa	ENOC, Equinor	05-May	Local inspector unavailable. (Covid-19 related)
101	Caofeidian, PRC	Enoc, Total, Shell, P66, Bieco, Koch, BHP, IMT, Chevron	Feb	Inspection not allowed by Terminal due to COVID – 19

102	Cartagena, Colombia	Chevron	19-May	Inspector unavailability
103	Cartagena, Spain			Terminal not allowed or non-availability of any local inspector due COVID – 19
104	Cartagena, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
105	Cartagena, Spain	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
106	Castellon, Spain	Enoc	March	Inspection not allowed by Terminal due to COVID – 19
107	Castellon, Spain	Equinor	21-Mar	Terminal change policy - no visitor/inspector allowed due to Covid-19
108	Ceuta, Spain	Lukoil,Cepsa, OMV, Total. Maxcom, POT, Repsol, P66, Enoc	16-Apr	No local Inspectors and Covid-19 travel restrictions
109	Ceyhan, Turkey	ENOC	08-May	ENOC are unable to attend the vessel.
110	Ceyhan, Turkey		22-Apr	Checked with Agents - Complete lockdown No Vetting inspections allowed
111	Chang Xing, PRC	All OM	06-May	Terminal restriction
112	Changzhou Huarun, PRC		13-May	As per agents - not allowed
113	Changzhou, PRC	CDI	09-Jun	Pls kindly note subject vessel fixed calling Jiangyin/Changzhou/Taizhou. After checked with each port, Changzhou and Taizhou tml don't permit inspection nowadays due to COVID-19 even Chinese. For Jiangyin, as our agent reported, jgn port authorities need 14 days quarantine after inspection to government appointed hotel waiting 14 days.
114	Chennai, India	Chevron	04-Apr	other - complete lockdown due to COVID19
115	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
116	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
117	Chiba, Japan		22-Apr	Not allowed due to COVID-19 restrictions
118	Chiriqui Grande, Panama		16-Apr	Not possible due to COVID-19 restrictions
119	Chiriqui Grande, Panama	P66. Equinor	30-Apr	Not possible due to COVID 19 travel restrictions. No local inspector.
120	Chittagong	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
121	Chittagong, Bangladesh	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.

122	Chittagong, Bangladesh	BP	Apr	Terminal not allowing to board BP vetting inspector due to restriction.
123	Chittagong, Bangladesh	EQUINOR	12-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
124	Chittagong, Bangladesh	MAXCOM	11-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
125	Ciudad Madero, Mexico	Equinor	20-Apr	Due to the COVID-19 travel restrictions (Lock Down)
126	Coassa, Panama	All	10-May-20	Terminal under security level 2 – no visitor/inspector allowed due to Covid-19.
127	Coatzacoalcos, Mexico	EQUINOR	06-Apr	Covid 19 - travel restrictions
128	Coazacoalcos, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
129	Coazacoalcos, Mexico			Do not allow inspectors onboard.
130	Coega Bay, South Africa	Equinor	15-May	Local inspector unavailable. (Covid-19 related)
131	Conarky, Guinea	Lukoil, Alma	29-Mar	
132	Concepcion Bay, Chile	CHEVRON	10-Apr	Not able to attend due the new restriction during easter holidays, travel problems due to COVID19. At this time the inspection is now cancelled.
133	Concepcion Bay, Chile	CHEVRON	11-Apr	Regret we will not be able to attend this one due the new restriction during easter holidays, travel problems due to COVID19. Thank you very much for your help, at this time the inspection is now cancelled.
134	Conchan, Peru	CHEVRON	17-Mar	Peruvian Government has restricted citizens' movement within their homes and closed international travel with effect from 16 March to 1 April.
135	Conchan, Peru	REPSOL	18-Mar	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
136	Corpus Christi, USA	Koch	15-May	Covid 19 - travel restrictions
137	Corpus Christi, USA	Equinor	25-May	Personal issues with the inspector
138	Coruna, Spain	Cepsa	29-Apr	Only at their terminals at Huelva, Tenerife and Algeciras
139	Cotonou, Benin	CDI	17-Mar	Local inspector unavailable. (Covid-19 related)
140	Cotonou, Benin	CDI	21-Mar	Local inspector unavailable. (Covid-19 related)
141	Cotonou, Republic of Benin	Agent	07-May	Covid 19 - travel restrictions
142	Covenas, Colombia	NA	15-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19. (ADVISED THROUGH AGENT)
143	Covenas, Columbia		16-Apr	Not possible due to COVID-19 restrictions
144	Covenas, Columbia	ENOC	18-Apr	Permission not granted by terminal due to COVID-19 restrictions
145	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice
146	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
147	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
148	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice. Exception is if the inspector is a local, however permission is required.
149	Cristobal, Panama		27-Mar	Travel restriction

150	Daesan, SK	TOTAL	05-Apr	Declined due to unavailability of inspectors
151	Daesan, SK	Total	31-May	Terminal prohibited any job other than cargo operation at berth. The same was explained you earlier and we have arranged his on / off schedule at the anchorage. However, the vessel's ETB delayed several hours again today as the terminal changed our vessel's jetty. And the inspector suddenly informed that he should cancel the inspection.
152	Daesan, SK			Not permitted by terminal
153	Daesan, SK	ENOC	12-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
154	Daesan, SK	IMT & BP	14-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
155	Dahej, India		01-May	Agents information due to terminal restrictions and lock-down
156	Dakar, Primorsk Oil Terminal, Senegal		10-Jun	Due to COVID restrictions, our inspectors are unable to reach Dakar and carry out the inspection onboard the vessel
157	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
158	Dakar, Senegal	Maxcom	14-Apr	Covid 19 - travel restrictions
159	Dakar, Senegal	ENOC, BHP, agents	13-Apr	Covid 19 - travel restrictions
160	Dakar, Senegal	Koch, Aethon, Total	13-Apr	Covid 19 - travel restrictions
161	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
162	Dalian, PRC			
163	Dalian, PRC		13-May	As per agents - not allowed
164	Dalian, PRC	Shell, Chevron	27-May	Terminal restrictions; local inspectors only
165	Dapeng, PRC	MMS	07-May	Visitor enter terminal must stay in this city "Shenzhen" longer than 14 days; Visitor should need Nucleic acid test of COVID-19 3 days before ship arrival, then we can make the application; Terminal will consider to approve or not base on Customs' quarantine pre examination on the vessel about 2-3 days before ship arrival(base on vessel's port calls records, crews conditions etc.
166	Dominican Republic	P66	13-Apr	Due to the COVID-19 travel restrictions
167	Dominican Republic	Lukoil	13-Apr	Due to Dominican Republic is locked down
168	Donges, France	Enoc	23-May	OM - Regret due to COVID 19 we cannot attend this vessel.
169	Donges, France	P66	23-May	Unfortunately due to COVID 19, there are travel or terminal restrictions in the location you requested this inspection to be conducted in
170	Dongguan, PRC	any OM	03-Apr	Covid 19 - country lock down
171	Dongguan, PRC	BHP	18-Apr	Dongguan Immigration is not allowed the SIRE inspector to visit ship for this calling due to Dongguan got two confirmed COVID-19 cases in last week which from foreign ships.
172	Dongguan, PRC	BHP	22-Apr	We do not have available inspectors at the moment due to various virus restrictions and will decline inspections.
173	Dongguan, PRC	Shell	19-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
174	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Insepction at the moment yet.

175	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE inspection at the moment yet.
176	Dongguan, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
177	Dongjiakou, PRC	BHP	25-May	Covid 19 - travel restrictions
178	Dongjiakou, PRC			
179	Dongjiakou, PRC	Maxcom	07-Apr	Terminal is closed as per covid 19 restrictions
180	Dongjiakou, PRC	MAXCOM	07-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
181	Dongjiakou, PRC	Chevron	10-Apr	Plan 17/04/2020 - Chevron do not schedule SIRE inspection at China port at the moment.
182	Dongjiakou, PRC	Shell	10-Apr	Plan 17/04/2020 - Rejected due to COVID-19
183	Dongying, PRC	EQUINOR	20-May	Covid 19 - travel restrictions
184	Dongying, PRC	BHP	21-May	Covid 19 - travel restrictions
185	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
186	Dongying, PRC	ENOC	23-May	Covid 19 - travel restrictions
187	Dongying, PRC	Maxcom	21-May	Covid 19 - travel restrictions
188	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
189	Douala, Cameroon			Terminal not allowed or non-availability of any local inspector due COVID – 19
190	Douala, Cameroon	Gazprom,Total	01-Jun	Lockdown due to COVID19 - no local inspectors available
191	Dumai, Indonesia	BHP, Neste oil	05-Jun	Due to COVID-19 travel restrictions
192	Durban, South Africa	Shell	26-Mar	
193	Durban, South Africa	Shell	24-Mar	Covid 19 - country lock down
194	Durban, South Africa	Shell	26-Mar	Covid 19 - country lock down
195	El Segundo, California, USA		22-Apr	no visitor/inspector allowed due to Covid-19
196	El Segundo, USWC	Chevron, P66	21-May	Terminal change policy – visitor/inspector allowed due to Covid-19.
197	El Segundo, USWC	Chevron		Terminal does not permit
198	El Segundo, USWC	P66	09-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19. (Terminal belong to Chevron and operator requested them to inspect - tbc)
199	Ennore, India	Shell	04-Jun	Planned: Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections in India until further notice.
200	Ennore, India	ENOC	05-May	Terminal rejection of the inspector
201	Fawley, UK	EXXON	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
202	Fawley, UK			
203	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March:Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
204	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March:Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.

205	Fawley, UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
206	Fawley,UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
207	Fos, France			Member reported info from agent, now possible to do inspection
208	Fos, France	TOTAL & OMV	23-May	Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling. We have just received the answer from the last Inspector, unfortunately, he is not available. In view of the above, we are force to postpone the inspection.
209	Freeport , USA	P66	25-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
210	Freeport ,USA	P66	25-Apr	Planned - Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
211	Freeport, Bahamas		10-Apr	Due to Lockdown
212	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
213	Fujairah, UAE	SHELL	22-Apr	Due to launch required for boarding
214	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
215	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
216	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
217	Galveston Offshore lightering area	Chevron	24-Apr	Unavailability of inspector for this inspection
218	Ganyu, PRC	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
219	Gdansk, Poland	ENOC, KOCH	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
220	Geismar, USA	Conocophillips	27-Mar	OM advised they have cancelled due to COVID 19
221	Geismar, USA	Equinor	27-Mar	Equinor did not have inspector due to COVID 19
222	Gemlik, Turkey	CDI	09-Apr	Local inspector unavailable.
223	Geoje, SK		01-Jun	Not allowed by terminal
224	Ghent, Belgium	Neste	14-Apr	Due to corona restrictions within the Company
225	Gijón, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
226	Goeje Yard, SK	PETROBRAS	21-May	Planned: Due to the outbreak of the COVID-19, currently we are not performing SIRE inspections in any port of the world

227	Guam, USA	BP,CHEVRON, P66,GAZPROM	10-Apr	Travel restrictions 14 days quarantine resulted to no inspectors available
228	Guam/Saipan, USA			Terminal not allowed or non-availability of any local inspector due COVID – 19
229	Guayanilla, Puerto Rico		16-Apr	Not possible due to COVID-19 restrictions
230	Guaynilla, Puerto Rico		20-May	Not possible as no local inspector and no flights operating to the island
231	Gulei, PRC		22-Mar	Due to COVID-19 not permitted by terminal
232	Gulei, PRC	Maxcom	09-May	Terminal restricions
233	Gulei, PRC	ENOC	May-20	Terminal change policy – no visitor/inspector allowed due to Covid-19.
234	Hadera, Israel	Repsol	22-May	"Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception"
235	Hadera, Israel	Rightship, Total	22-May	Local inspector unavailable. (Covid-19 related)
236	Haldia, India		Apr	Terminal informed they wil not allow vetting inspector to board due to restriction. India under lockdown.
237	Haldia, India	Idemitsu	04-May	India Lock down.
238	Haldia, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
239	Hamriyah, UAE	P66	Apr	Terminal did not allow BP vetting inspector to board due to COVID 19 restriction
240	Hazira, India	Rightship	01-Apr	country under lockdown - travelling prohibited within country
241	Hong Kong, PRC			
242	Honninggsvag, Norway	BP	03-Apr	Due the COVID-19 there is borders restriction to any non-residents (except for transit passengers).
243	Honninggsvag, Norway			
244	Honolulu, USA	SHELL	25-May	Travel restriction imposed in th country due to COVID 19.
245	Houston, USA	Equinor	Mar	Master has raised concerns about safety & health of the crew and has requested for deferring the inspection so as to avoiding/limit contact with visitors to the bare minimum. Tech. Manager agreed and postponed inspection.
246	Houston, USA	REPSOL	05-Apr- 20	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
247	Houston, USA	Repsol	13-Apr	
248	Houston, USA	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.

249	Houston, USA	Repsol	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
250	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-22
251	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-24
252	Huelva, Spain			Imposed restrictions
253	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
254	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected, Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
255	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
256	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected. Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
257	Huelva, Spain		18-May	Not possible due to COVID-19 restrictions in port.
258	Huizhou, PRC	Shell	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
259	Huizhou, PRC	P66	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
260	Huizhou, PRC	Petron	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
261	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April. Equinor do not have any available Inspector at Iceland due to COVID-19
262	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April: Equinor do not have any available Inspector at Iceland due to COVID-19
263	Ilo, Peru	Total	09-Jun	Due to the unavailability of an inspector in the port
264	Ilo, Peru	P66	08-Jun	Due to the COVID-19 travel or terminal restrictions
265	Immingham, UK	Ineos, Borealis, Shell	12-Apr	Local inspector unavailable. (Covid-19 related)
266	Incheon, SK			Not permitted by terminal
267	Iskenderun, Turkey		29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
268	Itaqui, Brazil	BHP	17-Apr	We regret will not be able to cover vessel's inspection.
269	Itaqui, Brazil	ENOC	17-Apr	Regret due to COVID 19 travel restrictions we are unable to attend the vessel.
270	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.
271	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.

272	Itaqui, Brazil	BP	24-May	OM - our inspectors are unable to cover Itaqui as the city it falls in Sao Luis is in lockdown
273	Itaqui, Brazil	Maxcom	24-May	OM- Much to our regret we can't cover as per Covid restrictions
274	Jasaan, Philippines	P66/BHP/Petron	28-May	No domestic flights available.
275	Jebel-Ali, UAE	Equinor	14-Apr	Inspection rejected - due to Hamriyah Terminal Restriction Not Allowed (COVID-19 pandemic).
276	Jebel-Ali, UAE	BP	11-Apr	Vessel had berth at SOET terminal, where SIRE Inspection are not permitted at COVID 19.
277	Jeddah, Saudi Arabia	BIECO	22-Apr	Terminal restriction
278	Jeddah, Saudi Arabia	Lukoil	26-Apr	Terminal restriction
279	Jiangsu, PRC		27-Apr	Terminal restrictions
280	Jiangyin, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
281	Jiangyin, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
282	Jianngyin, PRC	P66	03-Jun	COVID 19 travel or terminal restrictions in the location you requested this inspection to be conducted in.
283	Jisan, Saudi Arabia	Total, ENOC, AMPOL	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
284	JNPT India	Idemitsu	05-Jun	Dy. Conservator JNPT not allowing any inspection at JNPT.
285	Jorf Lasfar, Morocco			Terminal not allowed or non-availability of any local inspector due COVID – 19
286	Jorf Lasfar, Morocco	CDI	Early March	CDI was postponed on the beginning of March intentionally. Planning was to perform CDI under new management after takeover in discharging port. Takeover plans were postponed due to COVID and therefore CDI inspection too.
287	Jorf Lasfar, Morocco	CDI	26-Mar	Local inspector unavailable. No inspector available due to COVID.
288	Jorf Lasfar, Morocco	SIRE	03-Apr	Other (National Lockdown - Travel restriction)
289	Jorf Lasfar, Morocco	Total, Shell, Borealis, Rightship, Equinor, Adnoc	04-May	Local inspector unavailable. (Covid-19 related)
290	Jorf Lasfar, Morocco	Lukoil	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. (local inspector available and appointed)
291	Jorf Lasfar, Morocco	CDI	06-May	Local inspector unavailable. (Covid-19 related)
292	Jorf Lasfar, Morocco	SIRE	05-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
293	Jorf Lasfar, Morocco	CDI	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
294	Kaarsto, Norway	Chevron, IMT	04-Jun	Inspector unavailability
295	Kakinada, India	CDI	24-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
296	Kakinada, India	EQUINOR	06-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
297	Kakinada, India	BP	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

298	Kakinada, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
299	Kalundborg, Denmark	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
300	Kandla, India	Rightship, Adnoc, Total, Shell, Bieco	25-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
301	Kandla, India	Adnoc, Total, Shell, Bieco	28-Apr	Local inspector unavailable. (Covid-19 related)
302	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
303	Kaohsiung, Taiwan	Valero	17-Apr	Covid 19 - travel restrictions
304	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
305	Kaohsiung, Taiwan	Gazprom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
306	Kaohsiung, Taiwan	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
307	Kaohsiung, Taiwan	Petron	18-Apr	Local inspector unavailable. (Covid-19 related)
308	Kaohsiung, Taiwan	ENOC	Apr-20	Inspector can not enter Taiwan due to restriction of entry policy for control of Covid 19
309	Kaohsiung, Taiwan	Idemitsu, Shell, BHP	March	Inspection not allowed by Terminal due to COVID – 19
310	Kaoshiung, Taiwan	SHELL, BP, CHEVRON, ENOC	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19 unavailable. (Covid-19 related)
311	Kaoshiung, Taiwan	ENOC	20-Apr	Local inspector unavailable. (Covid-19 related)
312	Kaoshiung, Taiwan	BHP	17-May	Travel restriction imposed in th country due to COVID 19.
313	Kaoshiung, Taiwan	Idemitsu	17-May	Travel restriction imposed in th country due to COVID 19.
314	Karachi, Pakistan	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
315	Karachi, Pakistan.	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
316	Karratha, Australia	BP	01-May	Terminal restrictions
317	Karratha, Australia	BP	01-May	Terminal restrictions
318	Karsto, Norway	CDI	15-Apr	Local inspector unavailable. (Covid-19 related)
319	Karsto, Norway	CDI	15-May	Local inspector unavailable. (Covid-19 related)
320	Kawasaki, Japan	SHELL	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
321	Kawasaki, Japan	P66	30-Apr	Travel/border restrictions being imposed due to COVID-19
322	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
323	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
324	Kingston, Jamaica		25-May	Not possible due to COVID-19 restrictions and country is under lockdown.
325	Klaipeda, Lithuania	BHP / P66 / Chevron	06-Jun	Due to COVID-19 travel restrictions
326	Koper, Slovenia	Q8	Feb-20	Restriction due to Covid 19
327	Kotka, Finland	Preem, Lukoil, Koch	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19; Local inspector unavailable. (Covid-19 related)
328	Kozmino, Russia	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

329	Kuantan, Malaysia	Gazprom	02-Apr	All hotels closed therefore inspector who was driving 6 hours refused to attend - only local inspectors allowed as there are travel restrictions
330	Kwinana, Australia	BP	01-Apr	Terminal restrictions
331	Kwinana, Australia	Chevron	15-Apr	Covid 19 - travel restrictions
332	Kwinana, Australia	BHP	26-May	Panned: Until further notice all non-essential and non-cargo operation visits such as SIRE inspections and routine technician visits will not be permitted during STS operations or when vessels are alongside the refinery jetties.
333	Kwinana, Australia	IMT	24-May	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
334	La Libertad, Ecuador	Lukoil, Equinor, Rightship, BP, Koch	03-Apr	Local inspector unavailable. (Covid-19 related)
335	La Pampilla, Peru	IMT, Repsol, YPF, Sonangol, Maxcom, Gazprom, Phillips66, Shell	31-Mar	
336	La Pampilla, Peru	IMT	31-Mar	Covid 19 - travel restrictions
337	La Pampilla, Peru	Repsol	31-Mar	Covid 19 - travel restrictions
338	La Pampilla, Peru	YPF	31-Mar	Covid 19 - travel restrictions
339	La Pampilla, Peru	Sonangol	31-Mar	Covid 19 - travel restrictions
340	La Pampilla, Peru	Maxcom	31-Mar	Covid 19 - travel restrictions
341	La Pampilla, Peru	PMI	01-Apr	Covid 19 - travel restrictions
342	La Skhira, Tunisia			Terminal not allowed or non-availability of any local inspector due COVID – 19
343	Lagos, Nigeria	ENOC	10-Apr	Local inspector unavailable. (Covid-19 related)
344	Lagos, Nigeria	Total	28-Apr	Not inspecting in Africa currently
345	Lagos, Nigeria	Nobody invited as informed by Agents	04-Apr	other - complete lockdown due to COVID19
346	Las Minas, Panama	BHP	27-May	Local inspector unavailable. (Covid-19 related)
347	Las Minas, Panama	BHP	27-May	A local inspector is unavailable. (Covid-19 related)
348	Las Palmas, Spain	ENOC	24-Apr	Covid 19 - travel restrictions
349	Las Palmas, Spain	CEPSA	24-Apr	Covid 19 - travel restrictions
350	Las Palmas, Spain	Repsol	27-Apr	Covid 19 - travel restrictions
351	Las Palmas, Spain	Cepsa	30-May	MOC is not authorized to perform inspections outside Cepsa Terminals at Huelva, Algeciras or Tenerife.
352	Las Palmas, Spain	Repsol	01-Jun	Repsol does not inspect any vessel except special situations due to Covid-19
353	Lavera, France	KOCH	06-Apr	Not be able to plan the attendance due to COVID 19 travel restrictions
354	Lavera, France	BHP	06-Apr	Do not have available inspectors due to present virus situation. Flight and transport restriction beyond our control
355	Lavera, France	CDI	24-Apr	Travel restriction.

356	Lavera, Portugal	POT	10-Apr	Others - Due to COVID-19, POT do not inspect vessels temporarily.
357	Lavera, Portugal	GAZPROM	10-Apr	Local inspector unavailable.
358	Lavera, Portugal	P66	09-Apr	Local inspector unavailable.
359	Lavera, Portugal	ENOC	09-Apr	Local inspector unavailable.
360	Lavera, Portugal	BHP	06-Apr	Local inspector unavailable.
361	Lavera, Portugal	KOCH	06-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period.
362	Le Havre, France	CDI	25-Mar	Tech. manager decided to do not proceed with inspection in France to do not put crew in unnecessary risk – requested for CDI validity extension (successfully).
363	Le port, Reunion			Terminal not allowed or non-availability of any local inspector due COVID – 19
364	Leixioes, Portugal	Maxcom	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
365	Lianyungang , PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
366	Lianyungang , PRC	P66	03-May	No inspector available due to COVID-19 travel/border restrictions
367	Lianyungang, China	CDI, Xinrongtai	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
368	Lianyungang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
369	Lianyungang, PRC	Maxcom, ALMA	14-Apr	Covid 19 - travel restrictions
370	Lianyungang, PRC	BHP, Lukoil	14-Apr	Covid 19 - travel restrictions
371	Lianyungang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
372	Lianyungang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
373	Lianyungang, PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
374	Lianyungang, PRC	SHELL	03-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
375	Lianyungangn, PRC	All Majors/CDI	24-Apr	Terminal does not permit inspections due to COVID-19
376	Libreville, Gabon	CDI	March	Inspection not allowed by Terminal due to COVID – 19
377	Limay, Phillipines	IMT	01-Apr	Due to COVID-19 not permitted by terminal
378	Limbe, Cameroon	Shell, Enoc	05-Feb	Local inspector unavailable.
379	Limbe, Cameroon	BP, Maxcom	25-Mar	Inspection cancelled , due to Lockdown and restricted movement by air, road, etc
380	Limetree Bay, US Virgin Islands	P66	17-Apr	Due to the COVID-19 travel restrictions (Lock Down)
381	Lisbon, Portugal	BP	09-May	Understand from our inspectors in the region that Portugal borders are closed till at least 15th May and likely to be extended to June.
382	Lome OPL, Togo	Agent	14-May	Covid 19 - travel restrictions
383	Lome OPL, Togo	Agent	15-May	Covid 19 - travel restrictions
384	Lome OPL, Togo	Alma	15-May	Covid 19 - travel restrictions
385	Lome, Togo	Shell	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
386	Lome, Togo	Lukoil	22-Apr	Lome is locked down
387	Lome, Togo	CDI	16-Mar	Local inspector unavailable. (Covid-19 related)
388	Lome, Togo	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)

389	Lome, Togo	ENOC	27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
390	Long Beach, CA, USA	Shell	30-Mar	Cancelled
391	Loop, USA	Lukoil, ENOC,Maxom	24-Mar	
392	Loop, USA	Lukoil	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
393	Loop, USA	ENOC	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
394	Loop, USA	Maxcom	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
395	Loop, USA	PHILLIPS 66	12-Apr-20	There are travel restrictions in the region. To submit a new inspection request once next berthing orders are known and OM will try to accommodate inspection request.
396	Loop, USA	PHILLIPS 66	12-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
397	Loop, USA	Exxon	14-May	Unable to attend
398	Louisiana, USG	Marathon		Cancelled
399	Luanda, Angola	BHP , Maxcom, P66	13-Mar	Complete lockdown due to COVID19
400	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
401	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
402	Luanda, Angola	Chevron	03-Jun	Covid 19 - travel restrictions
403	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
404	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
405	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
406	Mailiao, Taiwan			
407	Mailiao, Taiwan	CDI	29-Mar	Local inspector unavailable. (Covid-19 related)
408	Malta	Lukoil	16-Apr	Due to Malta is locked down
409	Malta	ENOC,Koch, BIECO	27-Apr	Malta is Locked down, local inspector unavailable
410	Malta	IMT/SHELL/TO TAL	15-May	Malta in lockdown due to COVID
411	Malta	NA	05-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19. (ADVISED THROUGH AGENT)
412	Mamonal, Colombia	CHEVRON	15-Apr	Regret to inform that we do not have an inspector available for this inspection
413	Mamonal, Colombia	LUKOIL	15-Apr	Please be informed that due to terminal restrictions inspection cannot be arranged at Mamonal.
414	Mamonal, Colombia	PHILLIPS 66	15-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
415	Mangalore, India	Idemitsu	17-May	Others
416	Manzanillo, Mexico	P66, Shell	April	Inspection not allowed as interstate travel is restricted due to Covid 19

417	Manzanillo, Mexico	P66	14-Apr	Inspection declined due to COVID -19
418	Manzanillo, Mexico	ENOC	14-Apr	Inspection declined due to COVID -19
419	Manzanillo, Mexico	P66	14-Apr	due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
420	Manzanillo, Mexico	Equinor	14-Apr	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available to cover this request at the moment.
421	Manzatlán, Mexico	Shell, Chevron, Maratthon, P66	10-Apr	Due Covid-19 sanction.
422	Map Ta Phut, Thailand	IMT	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
423	Map Ta Phut, Thailand	SHELL	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
424	Map ta Phut, Thailand	Lukoil	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
425	Map Ta Phut, Thailand	Agent	04-May	Covid 19 - travel restrictions
426	Map Ta Phut, Thailand	MMS	28-May	The current situation due to COVID-19 outbreak, PTTLNG terminal not allow to do site inspection ,Please find attached PTTLNG's guideline for COVID-19 restriction for reference. Noted : The Civil Aviation Authority of Thailand (CAAT) has announced an extension of temporary ban on all international passenger flights to Thailand until 30 June 2020.
427	Map Ta Phut, Thailand	Shell, BP	07-Jun	Local inspector unavailable. (Covid-19 related)
428	Map Ta Phut, Thailand		1-8 Apr	
429	Maptaphut, Thailand	PTT	07-May	According to the "State of Emergency" declaration in Thailand and limitations of Terminal access granted in related to COVID-19 pandemic. PTT Inspection will not be able to assign during this period. Expected the situation will be released by end of this month.
430	Map-Ta-Phut, Thailand			Terminal not allowed or non-availability of any local inspector due COVID – 19
431	Maputo, Mozambique	Lukoil	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
432	Maputo, Mozambique	P66	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
433	Maputo, Mozambique	MAXCOM	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
434	Maputo, Mozambique	ENOC	07-Apr	COVID-19 – traveling restrictions.No local inspector available.
435	Maputo, Mozambique	ENOC	14-Apr	COVID-19 – traveling restrictions.No local inspector available.
436	Maputo, Mozambique	Agenta	23-May	Covid 19 - travel restrictions
437	Marcus Hook, USA	CDI	13-Mar	Nominated inspector declined to attend due to COVID
438	Marcus Hook, USA	CDI	31-Mar	No inspector available due to travel restrictions caused by COVID spread. Local inspector unavailable.

439	Marmara, Turkey			Terminal not allowed or non-availability of any local inspector due COVID – 19
440	Marmara, Turkey	IMT, BP, TOTAL, CHEVRON, SHELL.	10-Apr	Terminal lock down
441	Matosinhos, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
442	Mazatlan, Mexico		10-Apr	No local inspectors available
443	Mazatlan, Mexico	Chevron	15-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
444	Mazatlan, Mexico	PMI	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
445	Mazatlan, Mexico	Enoc	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
446	Mazatlan, Mexico	IMT	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
447	Mazatlan, Mexico	Shell	08-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
448	Mazatlan, Mexico	BHP	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
449	Mazatlan, Mexico	Total	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
450	Mejillones, Mexico	CDI	12-May	Local inspector unavailable. (Covid-19 related)
451	Melbourne, Australia	BHP	March	Inspection not allowed by Terminal due to COVID – 19
452	Merak, Indonesia	PHILLIPS66	13-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
453	Merak, Indonesia	ENOC	02-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
454	Mesaieed, Qatar	Shell	19-May	OM - We regret we are unable to carry out the inspection at this time. We do not have any local inspectors available
455	Mesaieed, Qatar	BP	19-May	OM - our inspectors in the region are unable to make it due to travel restrictions in place for COVID-19 pandemic.
456	Mesaieed, Qatar	IMT	22-May	OM - Due to COVID-19 pandemic worldwide , with travel/border restrictions being imposed in many countries, we regret to inform that we are currently unable to arrange as your request.
457	Mesaieed, Qatar	TOTAL	22-May	OM - Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling.
458	Midia, Romania	All Majors/CDI	01-May	Inspections are not possible in Romania due to travel restrictions due to COVID-19 pandemic
459	Milazzo , Italy	ENI	1-8 Apr	
460	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
461	Mina Al Ahmadi, Kuwait	IMT	12-Apr	country under lockdown - travelling prohibited within country

462	Mina Al Ahmadi, Kuwait	CDI	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
463	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
464	Mina Al-Ahmadi, Kuwait	KOCH	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
465	Mina Al-Ahmadi, Kuwait	ENOC	10-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
466	Mina Al-Mahadi, Kuwait	BHP	06-May	Unfortunately the UAE /Gulf countries have not yet provided a clear indications as to when flights will resume. In that regards, visas too will not be issued.
467	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
468	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
469	Mobile, Alabama	Koch	02-Apr	Declined inspection as no inspector available. Likely due to COVID19
470	Mobile, Alabama	Lukoil	10-Apr	Inspector could not make in time due to delay at travel checkpoints enroute
471	Mohammedia, Morrocco	CDI	26-Apr	Local inspector unavailable. (Covid-19 related)
472	Mombasa, Kenya	BHP	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
473	Monroe Terminal, Philadelphia, USEC			Not permitted as vetting considered non essential
474	Monteverde, Portugal	P66, ConocoPhillips	01-Apr	Local inspector unavailable. (Covid-19 related)
475	Montoir, France			
476	Morocco	All Majors/CDI	10-Apr	Morocco is locked down due to COVID-19 and no inspections can be arranged
477	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
478	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
479	Muara, Brunei	ENOC	11-Jun	Covid 19 - travel restrictions
480	Muara, Brunei	BHP	11-Jun	Covid 19 - travel restrictions
481	Mumbai - JNPT, India	ENOC	03-Apr	Not possible due to COVID-19 Restrictions lockdown
482	Mumbai, India	Chevron	07-Apr	Travelling restrictions
483	Mumbai, India	Phillips 66	12-Apr	Complete lockdown in India due to COVID 19. No public or private transportation's are available.
484	Mumbai, India	ENOC	25-Apr	Covid 19 - travel restrictions
485	Mumbai, India	Lukoil	24-Apr	Covid 19 - travel restrictions
486	Mumbai, India	EQUINOR	15-May	Inspector while trying to attempt to go onboard the subject vessel for conducting SIRE inspection, he was unable to embark the vessel due to excessive swell (embarking on Eagle Victoria was aborted after making several attempts to board the vessel).
487	Mundra, India	Chevron	06-Apr	Travelling restrictions
488	Murmansk, Russia	SHELL	29-Apr	Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections Russia until further notice.
489	Murmansk, Russia	GAZPROM	28-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
490	Murmansk, Russia	LUKOIL	24-Apr	As per agents quarantine isolation for two weeks is imposed at airport for the passengers arriving from Moscow.

491	Murmansk, Russia	LUKOIL	22-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
492	Murmansk, Russia	TOTAL	18-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
493	Naantali, Finland	LUKOIL	25-Mar	E-mail from LUKOIL 23 March:We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.
494	Naantali, Finland	LUKOIL	25/03/2020	E-mail from LUKOIL 23 March:We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.
495	Nanjing, PRC	Shell, Preem	15-Apr	Local inspector unavailable. (Covid-19 related)
496	Nanjing, PRC	ConocoPhilips	15-Apr	All inspections paused due to Covid-19
497	Nanjing, PRC	CDI	06-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
498	Nansha, PRC	Shell	30-Mar	
499	Nansha, PRC	Shell	30-Mar	Covid 19 - terminal restrictions
500	Nantong, PRC	P66	27-Apr	Port authorities imposed 14 days quarantine for inspectors after inspection
501	Nantong, PRC	Lukoil	06-Jun	Covid 19 - travel restrictions
502	Napier, France	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
503	Napier, New Zealand	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
504	Napier, New Zealand	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
505	New plymouth, New Zealand	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
506	New plymouth, New Zealand	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
507	New Plymouth, New Zealand	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
508	New York, USA			
509	New York, USA	Lukoil	25-Apr	Lukoil cancelled the inspection due to COVID-19.
510	Newcastle, Australia	IMT	Apr	Due to current rapidly increasing severity of COVID-19 pandemic worldwide and with travel/border restrictions being imposed in many countries, we regret to inform you that we are unable to arrange as your request for the subject vessel.
511	Newcastle, Australia			Terminal not allowed or non-availability of any local inspector due COVID – 19
512	Newyork / US	Total	14-Apr	Due to the unavailability of an inspector in the port

513	Ningbo, PRC	Koch	02-Apr	Terminal not allowed any visitors due to Covid-19
514	NingBo, PRC	Petron	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
515	NingBo, PRC	EQUINOR	03-Apr	Due to COVID-19 not permitted by terminal
516	Ningbo, PRC	BP	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
517	Ningbo, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
518	Ningbo, PRC	Lukoil	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
519	Ningbo, PRC		25-May	COVID-19 restrictions
520	Nipah, Indonesia	IMT, Lukoil, Shell, BP, Maxcom	10-Apr	No inspectors available.
521	Nipah, Indonesia	Idemitsu	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
522	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-23
523	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-25
524	Ocoa Bay, Dominican Republic	All Majors	03-Apr	No local inspectors available in Dominican Republic
525	Omoa, Honduras	Equinor, KOCH	07-May	No available local inspectors; travelling restrictions
526	Onsan, SK		20-Mar	Due to COVID-19 not permitted by terminal
527	Onsan, SK	Shell	March	Inspection not allowed by Terminal due to COVID – 19
528	Ornskoldsvik, Sweden	Lukoil	29-Apr	Declined due to COVID-19 travel restrictions
529	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
530	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
531	Pajaritos, Mexico	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
532	Pajaritos, Mexico	Lukoil	05-May	Not Inspected. Terminal don't allow the permission for Vetting inspector.
533	Panama			Local restriction
534	Panama	BHP		Not permitted as didn't have local presence.
535	Panama	GAZPROM	09-Mar	Not permitted
536	Paradip, India		1-8 Apr	
537	Paradip, India	N/A	09-Apr	Other (National Lockdown - Travel restriction)
538	Paradip, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
539	Paranagua, Brazil			Imposed restrictions
540	Paranagua, Brazil	Equinor, P66, Koch, Shell	01-Apr	Local inspector unavailable.
541	Paranagua, Brazil	Equinor	03-Apr	Local inspector unavailable. (Covid-19 related)
542	Pasir Gudang, Malaysia	Petron	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic
543	Pembroke, UK	EQUINOR	22-May	Planned: According to information received from agent, terminal does not allow inspections to be carried out due to restrictions in force.
544	Pengerang, Malaysia		08-Apr	Due to COVID-19 not permitted by terminal

545	Pengerang, Malaysia	Petronas	14-Apr	MMS does not allow insepector to stay overnight on vessel, As per terminal, inspector to board prior berthing and disembark upon depature from terminal
546	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-19
547	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-20
548	Peru	Repsol	24-Apr	Covid 19 - travel restrictions
549	Philippines	All Majors/CDI	29-May	Information: Inspections not permitted in Phillipines due to COVID-19 pandemic. All foreigners arriving Phillipines need to serve 14 days quarantine period.
550	Pinkenba, Australia			
551	PISCO	KOCH	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
552	Pisco, Peru	EXXON	11-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
553	Point Comfort, USA	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)
554	Point Lisas, Trinidad & Tobago	Lukoil, Savonetta, SP#2 South & SP#4	30-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
555	Point Lisas, Trinidad & Tobago	CDI	21-Apr	Local inspector unavailable. (Covid-19 related)
556	Point Lisas, Trinidad & Tobago	Lukoil, Shell, Rightship, Equinor	10-Apr	Local inspector unavailable. (Covid-19 related)
557	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
558	Point Lisas, Trinidad & Tobago	CDI	05-Apr	Local inspector unavailable. (Covid-19 related)
559	Point Lisas, Trinidad & Tobago	CDI	25-Apr	Local inspector unavailable. (Covid-19 related)
560	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
561	Point Lisas, Trinidad and Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
562	Point Lisas, Trnindad and Tobago	All Majors	03-Apr	No local inspectors available in Point Lisas and airport closed down till furthe notice.
563	Port Allan, USA	EQUINOR	24-Apr	Covid 19 - travel restrictions
564	Port Allan, USA	ENOC	27-Apr	Covid 19 - travel restrictions
565	Port Dickson, Malaysia	Idemitsu	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic .
566	Port Dickson, Malaysia	CDI	16-Apr	lockdown due to COVID19 - Foreign inspectors not allowed to travel to Malaysia
567	Port Elizabeth, South Africa		16-Apr	no visitor/inspector allowed due to Covid-19
568	Port Elizabeth, South Africa	CDI	04-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
569	Port Esquivel, Jamaica	BHP	30-Mar	
570	Port Esquivel, Jamaica	BHP	30-Mar	Covid 19 - travel restrictions
571	Port Esquivel, Jamaica	Maxcom	01-Apr	Covid 19 - travel restrictions
572	Port Everglades, USA	ENOC	24-Apr	Local inspector unavailable. (Covid-19 related)
573	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)

574	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
575	Port Klang, Malaysia	CDI	01-May	Malaysia lock down till 12th May as per message from agents. Only local inspectors allowed to carry out the inspection subject to terminal permission. CDI does not have any local inspector in Malaysia.
576	Port Louis, Mauritius	CDI	01-Jun	Local inspector unavailable. (Covid-19 related)
577	Port Moresby, Papua New Guinea	Chevron, BHP	27-May	Due to the COVID-19 travel restrictions
578	Port Moresby, Papua New Guinea	Chevron	27-May	Due to the COVID-19 travel restrictions
579	Port Moresby, Papua New Guinea	BHP	25-May	A local inspector is unavailable. (Covid-19 related)
580	Port Moresby, Papua New Guinea	Equinor	02-Jun	Papua New Guinea that no shoreside personell are permitted onboard any vessels
581	Port Reunion	CDI	03-Apr	No local inspectors available.
582	Port Said, Egypt	Gazprom	28-Apr	Complete lockdown No Vetting inspections allowed
583	Port Said, Egypt	CDI	24-May	Local inspector unavailable. (Covid-19 related)
584	Pozos Colorados, Colombia			
585	Priolo, Italy	CDI	28-May	
586	Pt. Lisas, USA	CDI	08-Apr	Due to the current travel restrictions CDI unable to assign inspector at T & T
587	Puerto Bahia, Colombia		10-Apr	No inspectors available
588	Puerto Cortes, Honduras	CDI	14-Apr	Covid 19 - travel restrictions
589	Puerto Cortes, Honduras	Agents	14-Apr	Covid 19 - travel restrictions
590	Puerto Moin, Costa Rica	Lukoil	04-May	Not Inspected. Vetting inspections are not allowed to be performed alongside (only at anchorage)
591	Puerto Santo Tomas, Guatemala			Terminal not allowed or non-availability of any local inspector due COVID – 19
592	Pyeongtaek, South Korea	CDI, SPTT	17-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
593	Qidong, PRC	ENOC	06-Apr	Terminal restrictions
594	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
595	Qingdao, PRC	ENOC	01-May	Terminal restrictions
596	Qingdao, PRC	Petron	05-May	Terminal rejection of the inspector
597	Qingdao, PRC			
598	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
599	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
600	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
601	Qingdao, PRC	BHP	13-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
602	Qingdao, PRC	PHILLIPS66	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
603	Qingdao, PRC	TOTAL, P66	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
604	Qingdao, PRC	SHELL	11-Jun	Pls be advised inspector is not allowed to get on board according to Qingdao terminal's latest regulation. Fyi: No person is allowed to get on board except boarding agent and CIQ officers.

605	Quanzhou, China	Lukoil, Powershell Terminal	11-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
606	Quanzhou, PRC	P66	Mar-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
607	Quanzhou, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
608	Quanzhou, PRC	TOTAL	04-Jun	Due to unavailability of local inspector
609	Quanzhou, PRC	P66	05-Jun	Agents cannot confirm that permit will be granted by local authorities
610	Quintero, Chile	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
611	Quintero, Chile	Marathon	16-Apr	Due to COVID-19, the terminal is no allowing inspections
612	Quintero, Mexico			
613	Ras Al Khair, Saudi Arabia	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
614	Ras Al Khair, Saudi Arabia	ENOC	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
615	Ras Al Khair, Saudi Arabia	Adnoc, Rightship, Koch, Shell	10-Apr	Local inspector unavailable. (Covid-19 related)
616	Ras Al Khair, Saudi Arabia	CDI	14-Mar	Local inspector unavailable. (Covid-19 related)
617	Ras Al Khair, Saudi Arabia	CDI	10-Apr	Local inspector unavailable. (Covid-19 related)
618	Ras Laffan, Qatar		23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
619	Ras Tanura, Saudi Arabia	ENOC	31-Mar	Covid 19 - travel restrictions
620	Ras Tanura, Saudi Arabia	Maxcom	31-Mar	Covid 19 - travel restrictions
621	Ras Tanura, Saudi Arabia	BHP	01-Apr	Covid 19 - travel restrictions
622	Ras Tanura, Saudi Arabia	ENI	01-Apr	Covid 19 - travel restrictions
623	Ras Tanura. Saudi Arabia	ENOC, Maxcom, BHP, ENI	01-Apr	
624	Ras Tanurah, Saudi Arabia	Adnoc, Saudi Aramco, Total, Lukoil, P66	26-Apr	Local inspector unavailable. (Covid-19 related)
625	Rayong, Thailand		27-Apr	Agents - Covid 19 - travel restrictions
626	Reunion	CDI	03-Apr	No local inspectors available.
627	Richard's Bay, South Africa	Rightship, Total, Shell, Neste, Respol, YPF, Conocophilips, Preem	23-Apr	Local inspector unavailable. (Covid-19 related)
628	Richmond, USA	Lukoil	03-Apr	Not possible due to COVID-19 Restrictions. Only critical personnel allowed.
629	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.

630	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.
631	Rijeka, Croatia	LUKOIL	10-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
632	Rio Grande, Brazil			Imposed restrictions
633	Rio Haina, Dominican Republic	CDI	09-May	Local inspector unavailable. (Covid-19 related)
634	Rizhao, PRC	Shell and Maxcom	25-Jan	Inspector's not willing to go due to COVID19
635	Rizhao, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
636	Rizhao, PRC	Chevron	08-May	No available local inspectors; travelling restrictions
637	Rizhao, PRC	P66	05-Jun	Covid 19 - travel restrictions
638	Rizhao, PRC		1-8 Apr	
639	Rotterdam, Netherland	CDI	20-Mar	Inspector refused travelling to Rotterdam due to airport closure at ISLE OF MAN
640	Rotterdam, Netherlands	SHELL	25-May	We regret we are unable to carry out the inspection at this time, as we do not have any local inspectors available. Please request again at a later date.
641	Rotterdam, Netherlands	Equinor	08-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
642	Rovigo, Itali	Shell	05-May	Inspector required to embark by launch
643	Rovigo, Itali	Repsol	05-May	Inspection deemed 'not exceptional' due to Covid-19
644	Rovigo, Itali	BP	05-May	Inspection declined as inspector would have had to remain onboard overnight
645	Rudong, PRC	Phillips66	03-Apr	Terminal restrictions
646	Ruwais, Qatar	Shell	22-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
647	Ruwais, Qatar	Adnoc, Total, Preem, P66	22-Apr	Local inspector unavailable. (Covid-19 related)
648	Ruwais, Qatar	Bieco	22-Apr	No response from OM
649	Ruwais, UAE	ADNOC	12-Apr	Travel restrictions due to COVID - Terminal restrictions due to security sensitivity of the area
650	Sabine Pass, USA	Rightship, Shell	25-May	Cancelled due to unsafe access - adjusted boarding measures (Covid-19 related)
651	Sabine Pass, USA	BP	28-May	
652	Saint Nicolas, France	CDI	20-May	Local inspector unavailable. (Covid-19 related)
653	Saldana Bay, South Africa	BHP, P66	04-Apr	other - complete lockdown due to COVID19
654	Salina Cruz, Mexico	Lukoil	16-Apr	Foreign Inspector travel ban
655	Salina Cruz, Mexico	P66	16-Apr	Foreign Inspector travel ban
656	Salvador, Brazil	ENOC	23-Apr	Planned - Due to COVID-19 I will not be able to attend you in Salvador as I am requiring flight from Rio De Janeiro. I can attend you in Rio De Janeiro or in São Sebastião therefore keep me posted when you have program to attend one of these two ports.
657	Salvador, Brazil	ENOC	01-May	Inspector is unable to attend at this call due to prior commitments.

658	Salvador, Brazil	ENOC	01-May	The inspector is unable to attend at this call due to prior commitments. Please advise us her next convenient port.
659	Salvador, Brazil	KOCH	43977	Terminal Change policy - access through terminal forbidden
660	Santos, Brazil			Imposed restrictions
661	Santos, Brazil	Koch, Petrobras	02-Apr	Local inspector unavailable.
662	Santos, Brazil	Phillips66	13-Apr	
663	Santos, Brazil	Shell, BHP	14-Apr	Shell - Not covering; BHP Not performing inspection.
664	Santos, Brazil	Petrobras	15-Apr	Petrobras - Not performing inspections until further, KOCH - No available local inspectors; travelling restrictions
665	Santos, Brazil	Shell	01-May	Not covering
666	Santos, Brazil	ENOC	02-May	
667	Sao Luis, Brazil	Idemitsu	18-Mar	
668	Sariaya, Philippines	BHP-Rightship, Equinor	24-Apr	Inspection cancelled.
669	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
670	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
671	Shanghai, China	Shell	March	Inspection not allowed by Terminal due to COVID – 19
672	Shiudong, PRC	Lukoil	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
673	Shiudong, PRC		08-May	Inspector who is from abroad is not permitted to come for inspection. Chinese is permitted. If inspector is Chinese , he need to arrive Maoming for quarantine 3 days before on board, and go to hospital for Nucleic acid detection.Launch cost to the terminal will be around 18,000/-USD
674	Shuidong, PRC	BHP	28-May	Covid 19 - travel restrictions
675	Shuidong, PRC	Alma	29-May	Covid 19 - travel restrictions
676	Sierra Leone	Lukoil, Alma	29-Mar	
677	Sierra Leone & Conakry	Lukoil & Alma	29-Mar	Covid 19 - travel restrictions
678	Sikka India	IDEMITSU	12-May	Lockdown in India due to Covid 19 pandemic.
679	Sikka, India	CDI	30-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
680	Sikka, India		1-8 Apr	
681	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
682	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
683	Sines, Portugal			Imposed restrictions
684	Sines, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information.These actions will remain in force from now until Sanitary alert by Covid-19 will cease.

685	Sines, Portugal	Lukoil, POT, Saras, Maxcom, Erg, Neste	20-Apr	No local Inspectors and Covid-19 travel restrictions
686	Sines, Portugal	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC	20-Apr	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC - Local inspector unavailable. (Covid-19 related)
687	Sines, Portugal	Cepsa	01-May	Declined due to COVID-19 travel restrictions
688	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
689	Singapore	Enoc	21-Apr	Due to terminal restriction (Singapore Petrochemical Complex Olefin I)
690	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
691	Singapore	Idemitsu	19-May	Singapore Terminal Restricted for inspection due to COVID 19 pandemic
692	Singapore	Idemitsu	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
693	Singapore, Shell Bukom	Gazprom	17-Apr	Terminal declined inspector's boarding at their terminal due to COVID 19
694	Singapore, Vopak Penjuru	Gazprom	15-Apr	Rejected due to terminal disapproved of any visitors or auditor during current Covid -19 situation
695	Sohar, Oman	CDI, Oiltanking Odfjell	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
696	Sohar, Oman	BHP, Equinor, Gazprom, Repsol, KOCH, ENI, P66,Lukoil, BP, Total, ENOC	30-Apr	Local inspector unavailable. (Covid-19 related)
697	Sohar, Oman	Shell, BP	10-May	Local inspector unavailable. (Covid-19 related)
698	Sohar, Oman	All Majors/CDI	15-May	All routes closed in Oman, foreigners cannot arrive to carry out inspection due to COVID-19
699	Sohar, Oman	Equinor	21-May	Due to travel restrictions imposed by the covid19 outbreak, there are no inspectors available to cover.
700	Sohar, Oman	ENOC, ADNOC, KOCH	21-May	Local inspectors not available; travelling restrictions
701	Sohar, Oman	Idemitsu	22-May	No available local inspectors; travelling restrictions
702	Sohar, Oman	Equinor, ENOC, ADNOC, Idemitsu, KOCH	29-May	Local inspector unavailable. (Covid-19 related)
703	South Africa ports		02-Apr	Heighted level of Security level protocols within the South African Port System during the lockdown period.

704	Southwold, UK	Chevron/Total /Equinor/Shell	25-May	Declined due to unavailability of inspectors
705	Southwold, UK	Lukoil	10-Jun	delay operations
706	Sri Racha, Thailand			Not permitted
707	Sri Racha, Thailand	Lukoil	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
708	St' Charles, Barbados	BHP	02-Apr	Last muute cancellation as terminal change policy - no visitor/inspector allowed due to COVID19
709	St Croix, US Virgin Islands		02-Apr	Not possible due to COVID-19 restrictions
710	St Croix, USA (Virgin Island)	TOTAL	20-Apr	Local inspector unavailable. (Covid-19 related)
711	St. Eustatius		14-Apr	Not possible due to COVID-19
712	St. James, LA USA	Maxcom	01-May	No local inspector available in Louisiana (covid-19 related) normal Texas based inspector to attend but not ready to serve quarantine period when return to Texas
713	Stenungsund, Sweden	CDI	17-Mar	Nominated Inspector declined due to COVID
714	Stignaes, Denmark			Imposed restrictions
715	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April. We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
716	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April. Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
717	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April. Thank you for your email. Please note we not have any local inspectors in Sweden.
718	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April: We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
719	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April: Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
720	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April: Please note we not have any local inspectors in Sweden.
721	Suape, Barzil	IMT/SHELL/CH EVRON	15-May	Due to COVID-19 travel restrictions
722	Suape, Brazil			Imposed restrictions
723	Suape, Brazil	ENOC	17-Apr	Due to COVID 19 travel restrictions we are unable to attend the vessel.
724	Suape, Brazil	IMT/SHELL/CH EVRON	15-May	Due to COVID-19 travel restrictions
725	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
726	Suez, Egypt	Agents	22-May	Covid 19 - travel restrictions
727	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
728	Suez, Egypt	IMT	29-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.

729	Sumed, Egypt	Lukoil	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
730	Sumed, Egypt	Shell	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
731	Taicang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
732	Taicang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
733	Taicang, PRC	Maxcom, ALMA, BHP,Lukoil	14-Apr	Covid 19 - travel restrictions
734	Taicang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
735	Taicang, PRC	BP	09-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
736	Taicang, PRC	Idemitsu	29-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
737	Taicang, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
738	Taicang, Taiwan	Petron, P66	05-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
739	Taichung, Taiwan	Koch, Shell, Total, Rightship, Adnoc	20-Apr	Local inspector unavailable. (Covid-19 related)
740	Taichung, Taiwan	BHP, Gazprom	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
741	Tainjin, PRC			
742	Taipei, Taiwan	CDI	27-Apr	Travel/border restrictions being imposed due to COVID-21
743	Taixing, PRC		10-Apr	Terminal didn't allowed
744	Taixing, PRC	CDI	11-Apr	Terminal rejected additional personnel to enter.
745	Taixing, PRC	Lukoil	01-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
746	Taizhuo, PRC	Lukoil	08-May	Covid 19 - travel restrictions
747	Taizhuo, PRC	Agent	07-May	Covid 19 - travel restrictions
748	Tallinn, Estonia	Lukoil	16-Apr	
749	Tallinn, Portugal	LUKOIL	16-Apr	
750	Tamatave, Madagascar (Toamasina)	Maxcom	16-Apr	Covid 19 - travel restrictions
751	Tamatave, Madagascar (Toamasina)	Lukoil,Total,B HP, ENOC,P66,Aet hon,Koch, agents	14-Apr	Covid 19 - travel restrictions
752	Tangier MED, Morroco	ENOC	02-Apr	Travelling restrictions
753	Tangier, Morocco		07-Apr	Not allowed due to COVID-19 restrictions
754	Tanjung Pelepas, Malaysia	KOCH	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
755	Tanjung Pelepas, Malaysia	P66	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
756	Tanjung Bin, Malaysia	Koch	26-Mar	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
757	Tanjung Priok, FSRU Nusentara, Indonesia	BP	10-May	Travel restriction imposed in th country due to COVID 19.

758	Tarragona, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
759	Tarragona, Spain	Equinor	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
760	Tarragona, Spain	Equinor	05-Jun	no European inspectors are available in Tarragona due to travel restrictions
761	Tarragona, Spain	SHELL	04-Jun	Due to the use of barge / launch boat
762	Tauranga, New Zealand	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
763	Tauranga, New Zealand	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
764	Teesport, UK	Exxon	02-Apr	No available local inspectors; travelling restrictions
765	Tema, Ghana	CDI	19-Mar	Local inspector unavailable. (Covid-19 related)
766	Tema, Ghana	ENOC, KOCH	30-Apr	Local inspector unavailable. (Covid-19 related)
767	Tetney, UK	BP	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
768	Tetney, UK	EQUINOR	13-Apr	Local inspector unavailable.
769	Tetney, UK	BP	20-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
770	Thanh Hoa, Vietnam	PETROVIETNAM KOCH	16-Jun	We have only one local inspector and he will cover few inspections of other vessels from 14 to 20 June. So he will not be available to cover inspection of your vessel. Regret to inform you that we will not be able to arrange the subject vessel inspection, due to the Covid19, Vietnamese Government still not allow International flights up to now.
771	Thessaloniki, Greece	P66	07-May	Local inspector unavailable. (Covid-19 related)
772	Thessaloniki, Greece	Repsol	07-May	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
773	Tianjin, PRC	CDI	10-Apr	No inspection was not allowed by port authority
774	Tianjin, PRC	IMT, Chevron, Shell, Total	Feb	Inspection not allowed by Terminal due to COVID – 19
775	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
776	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
777	Tianjin, PRC	Lukoil	28-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.

778	Tianjin, PRC	Equinor, BHP, Gazprom, Lukoil, KOCH, Idemitsu	09-Feb	Inspector's not willing to go due to safety/health reasons + terminal change policy - no visitor/inspector allowed due to Covid-19.
779	Tianjin, PRC	CDI	11-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
780	Tokuyama, Japan	Equinor, Idemitsu	04-Jun	Regret inform you that we are unable to attend this vessel at Tokuyama. We regret to say we could not find the inspector able to attend your good vessel tomorrow. Sorry for causing your inconvenience.
781	Townsville, Australia	Chevron	March	Inspection not allowed by Terminal due to COVID – 19
782	Tramandai, Brazil	Lukoil	18-Apr	Due to the COVID-19 travel restrictions (Unavailability of Flights)
783	Tramandai, Brazil		24-Apr	Not allowed due to COVID-19 restrictions
784	Tramandai, Brazil	Lukoil	07-May	Covid 19 - travel restrictions
785	Tramandai, Brazil	PMI	04-May	Covid 19 - travel restrictions
786	Tramandai, Brazil	Koch	03-May	Covid 19 - travel restrictions
787	Tramandai, Brazil	Maxcom	02-May	Covid 19 - travel restrictions
788	Tranmere, UK	ENOC	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
789	Tuban, Indonesia	ENOC	05-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
790	Tuban, Indonesia	Rightship	07-Apr	Not possible due to border closures and quarantine requirements due to COVID-19
791	Tuban, Indonesia	Cocophillips	16-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
792	Tuban, Indonesia	Exxon, P66	16-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
793	Tuticorin, India	CDI	19-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
794	Tuxpan, Mexico	VIVO	31-Mar	
795	Tuxpan, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
796	Tuxpan, Mexico			Do not allow inspectors onboard.
797	Ulsan, SK	NESTEOIL	22-May	(Planned) - Neste not performing any inspections due to the COVID 19 situation.
798	Ulsan, SK	IMT, SHELL	10-Apr	Travel restriction
799	Ulsan, SK	All Majors/CDI	15-May	SK Energy terminal in Ulsan do not permit any inspections to be carried out during cargo operations. Option provided is to carry out the inspection at anchorage which will be an idle inspection and not serve the purpose.
800	Ust Lega, Russia	EXXON	07-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels. We will maintain our pragmatic approach in evaluating TC vessels and SIRE inspections reports will be reviewed on a case by case basis accordingly
801	Ust Lega, Russia	EXXON	07-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
802	Vadinar, India			

803	Vadinar, India	Maxcom	09-Apr	Covid 19 - travel restrictions
804	Vadinar, India	BHP	06-Apr	Covid 19 - travel restrictions
805	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
806	Vadinar, India	ENOC	01-May	Covid 19 - travel restrictions
807	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
808	Valencia, Spain	BHP	29-May	OM - Unfortunately do not have available inspectors and will decline inspection due to current health/virus/quarantine /travel problems , no flights etc..
809	Valencia, Spain	P66	29-May	OM - Unable to schedule the inspection due to the conflict that the Suggested date is within 30 days of an already planned SIRE/OVID inspection with another member.
810	Vatso, Italy	CDI	March	Inspection not allowed by Terminal due to COVID – 19
811	VeraCruz, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
812	VeraCruz, Mexico			Do not allow inspectors onboard.
813	Veracruz, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
814	Veracruz/Altamira, Mexici	CDI	14-Apr	Covid 19 - travel restrictions
815	Virgin Islands, USA	All Majors/CDI	10-Apr	All ports in USVI is locked down due to COVID-19 and no inspections can be arranged
816	Vizag, India	Koch	08-Apr	Other (National Lockdown - Travel restriction)
817	Vizag, India	CDI	15-Apr	India lockdown due to COVID
818	Vizag, India	Koch	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
819	Vizag, India	Equinor	20-May	Due to several restrictions imposed by the covid-19 outbreak on this given location, the inspector will not be able to attend.
820	Vizag, India	Koch	06-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
821	Vizag, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
822	Vungtau, Vietnam	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
823	Vungtau, Vietnam	NESTEOIL	02-May	At this moment Neste does not carry out sire inspection
824	Vungtau, Vietnam	P66	02-May	Travel/border restrictions being imposed due to COVID-20
825	Walvis Bay, Namibia		April	Namibian authorities suspended Visa issue for 1 month thus NO inspector available
826	Walvis Bay, Namibia	BHP	06-Apr	Lockdown in that area and restricted movement by air, road or rail Not be possible to inspect the subject vessel.
827	Walvis Bay, Namibia	BHP	06-Apr	Local inspector unavailable.
828	Wenzhou, PRC		10-Apr	Terminal didn't allowed
829	Whiffenhead, Canada	BP	16-Apr	Foreign Inspector travel ban
830	Wilhelmshaven, Germany			Imposed restrictions
831	Wilhelmshaven, Germany	BP	29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
832	Yabucao, Puerto Rico	ENOC/BHP/Lukoil/Equinor	03-Apr	Not possible due to COVID-19 Restrictions
833	Yanbu, Saudi Arabia	ADNOC	28-Apr	Travel restrictions - Lockdown

834	Yanbu, Saudi	Enoc	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
835	Yanbu, Saudi	Shell	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
836	Yanbu, Saudi Arabia	CDI, Koch, Shell	12-Apr	Other (National Lockdown - Travel restriction)
837	Yanbu, Saudi Arabia	CDI	11-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
838	Yanbu, Saudi Arabia	CDI / Gas	26-May	No available local inspectors; travelling restrictions
839	Yanbu, Saudi Arabia	CDI	01-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
840	Yanbu, Saudi Arabia	Koch	29-Apr	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
841	Yangpu, PRC	Idemitsu	12-Apr	No inspection was not allowed at the terminal
842	Yangpu, PRC	Idemitsu	12-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
843	Yangpu, PRC	CDI	17-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
844	Yangshan, PRC	MMS	16-May	Present stage, visitor is not allowed in Yangshan LNG terminal.
845	Yantai, PRC	Chevron, Shell, Koch,	Feb	Inspection not allowed by Terminal due to COVID – 19
846	Yantai, PRC	Lukoil, P66	21-Feb	Local inspector unavailable. (Covid-19 related)
847	Yantai, PRC	CDI	21-Feb	Local inspector unavailable. (Covid-19 related)
848	Yeosu, SK		05-Jan	Terminal policy- no visitor/inspector allowed due to Covid-19
849	Yeosu,SK		25-Mar	Due to COVID-19 not permitted by terminal
850	Yeosu,SK	EXXON	08-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
851	Yingkou, PRC	NA	17-May	The following restrictions applies: 1. Inspector should hold Two times (24 interval) nucleic acid testing before onboard date. (Send agent the test reports and other required documents in advance) a. Test can be done at local hospital, 1st test to be done 7 days prior to attendance. 2. 14 days isolation in Yingkou hotel arranged by local port authorities after departure from vessel 3. Other documents will inform him directly if confirmed. 4. Inspectors will most preferably not from the high risk area. (HUBEI, JILIN, HEILONGJIANG province)
852	Yingkou, PRC	GAZPROM	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
853	Yizheng, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
854	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
855	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
856	Yumurtalik, Turkey	CDI	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
857	Yung An, Taiwan			

858	Yung An, Taiwan	Chevron	02-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
859	Yung An, Taiwan	KOCH	01-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
860	Yung An, Taiwan	GAZPROM	15-Apr	Local inspector unavailable.
861	Yung An, Taiwan	BP	14-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
862	Zeebrugge, Belgium	REPSOL	14-Apr	Other - Due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
863	Zeebrugge, Belgium	PREEM	05-May	Inspector refused to follow precautions stipulated by the Company SMS.
864	Zhangjiagang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
865	Zhangjiagang, PRC	Maxcom ALMA, BHP, Lukoil,	14-Apr	Covid 19 - travel restrictions
866	Zhangjiagang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
867	Zhangjiagang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
868	Zhangjiagang, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
869	Zhangjiang, PRC	BP	18-Feb	As per BP's message they stated due to terminal restrictions but found out inspector did not want to use launch boat as we managed to book inspection with another oil major
870	Zhapu, PRC	BP	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
871	Zhapu, PRC	Lukoil, BHP Rightship	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
872	Zhapu, PRC	Petron/Chevron	09-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
873	Zhoushan, PRC	Shell	02-Apr	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
874	Zhoushan, PRC	ENOC	13-Apr	Terminal restrictions
875	Zhoushan, PRC		21-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
876	Zhoushan, PRC	SHELL	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
877	Zhoushan, PRC	SHELL	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
878	Zhoushan, PRC		08-May	Terminal restriction for sire inspection is in place.
879	Zhoushan, PRC	EQUINOR	14-May	Terminal policy- no visitor/inspector allowed due to Covid-19

880		BASF	Apr	Rejected for business based on CDI more that 12 months old / no pyhsical CDI could be completed prior to last CDI expiring 12mnth.
-----	--	------	-----	--