

Date : 13/07/2020

INSPECTION CANCELLED OR DECLINE				
No	Port	OM	Date	(blue font - new entry since last weekly update) Remark
1	Adelaide, Australia	Koch, Shell	March	Inspection not allowed by Terminal due to COVID – 19
2	A Corunna, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
3	A.D.Reis, Brazil	EQUINOR	05-Jan	Declined due to travel restrictions
4	A.D.Reis, Brazil	TOTAL	05-Apr	Declined due to unavailability of inspectors
5	Abidjan, Ivory Coast	CDI	15-Mar	Local inspector unavailable. (Covid-19 related)
6	Adabiyah, Egypt	Statoil	22-Apr	No flights into Egypt, Statoil cancelled request
7	Adabiyah, Egypt	CDI	25-May	Rejected for business based on SIRE more than 6 months old / no physical SIRE could be completed prior to last SIRE expiring 6mths/12mths.
8	Adelaide, Australia	Shell, BP, Idemitsu, Viva	April	Inspection not allowed as interstate travel is restricted due to Covid 19
9	Ain Sukhna Sonkar Terminal, Egypt	Shell	20-May	Others – Unable to carry out the inspection at this time, do not cover this Country.
10	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
11	Ain Sukhna, Egypt	Lukoil, Adnoc, Maxcom	03-May	Covid 19 - travel restrictions
12	Ain Sukhna, Egypt	ENOC	02-May	Covid 19 - travel restrictions
13	Ain Sukhna, Egypt	P66	04-May	Covid 19 - travel restrictions
14	Ain Sukhna, Egypt	MOH	04-May	Covid 19 - travel restrictions
15	Ain Sukhna, Egypt	IMT	04-May	Covid 19 - travel restrictions
16	Al Jubail, Saudi Arabia	IMT	25-Jun	OM - Due to current COVID-19 pandemic situation worldwide , we regret to inform that we are currently unable to arrange as your request.
17	Alcudia, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
18	Alexandria, Egypt	Enoc	18-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
19	Alexandria, Egypt	Koch	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

20	Alexandria, Egypt	Maxcom	23-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
21	Aliaga, Turkey			Imposed restrictions
22	Aliaga, turkey	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
23	Aliaga, Turkey	All Majors/CDI	15-May	Inspections not permitted to be carried out due to COVID-19. Local inspector was appointed; however he was denied entry to the terminal for the purpose of inspection.
24	Aliaga, Turkey	GAZPROM	09-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
25	Aliaga, Turkey	GAZPROM	09-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
26	AL-Jubail, Saudi Arabia	Idemitsu	15-Jun	All air-flights to or from Saudi Arabia has been suspended due to COVID-19 until further instructions.
27	All ports in India	All Majors	03-Apr	Locked down till 14-Apr, no inspections can be scheduled
28	Altamira, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
29	Altamira, Mexico			Do not allow inspectors onboard.
30	Altamira, Mexico	Maxcom	27-Mar	All arranged, port closed over night for non-locals, even as inspector was Mexican
31	Altamira, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
32	Altamira, Mexico	Maxcom	08-May	Covid 19 - travel restrictions
33	Altamira, Mexico	ALMA	07-May	Covid 19 - travel restrictions
34	Altamira, Mexico	ENOC	07-May	Covid 19 - travel restrictions
35	Amsterdam, Netherland	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
36	Amsterdam, Netherland	P66	Apr	No inspector available
37	Amsterdam, Netherlands	Neste	18-May	At this moment Neste does not carry out any sire inspections.
38	Angra Dos Reis, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
39	Antifer, France	BP	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
40	Antwerp, Belgium	Gazprom	06-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. From agent: We received terminal ATPC instructions from that due COVID nobody is allowed on the terminal anymore till further notice
41	Apia, Samoa	P66	19-Jun	Due to the COVID-19 travel or terminal restrictions
42	Arzew, Algeria		07-Apr	Not allowed due to COVID-19 restrictions
43	Arzew, Algeria	CDI	27-May	Local inspector unavailable. (Covid-19 related)
44	Arzew, Algeria	Total	29-Jun	Not having local inspector
45	Ashklelon, Isreal	Gazprom	04-Mar	Last minute cancellation as inspector's were not allowed to enter Israel if previously travelled to high risk COVID19 countries in Europe

46	Aughinish, Ireland	P66	25-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
47	Aughinish, Ireland	Koch, VIVO	25-Apr	Local inspector unavailable. (Covid-19 related)
48	Augusta, Sicily	BHP	29-May	The Sicily region have still travel limitation until at least the 7th June. Not residents in Sicily cannot travel to Augusta. In view of restriction, we will decline the inspection invitation.
49	Aviero, Portugal	CDI	28-Mar	Terminal requirements not to allow any inspections due to COVID-19
50	Bahia Blanca, Argentina	KOCH, Idemitsu	31-Mar	Local inspector unavailable. KOCH and Idemitsu were not able to find available inspectors due to COVID
51	Banática, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
52	Bangkok & Maptaphut, Thailand	PTT	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
53	Banjul, Gambia	P66, Idemitsu, Maxcom, ENOC, KOCH	06-Jul	Travel restrictions
54	Banjul, SK	Maxcom	16-Apr	Covid 19 - travel restrictions
55	Banjul, SK	Maxcom	15-Apr	Covid 19 - travel restrictions
56	Banjul, SK	Total, ENOC, Maxcom	14-Apr	Covid 19 - travel restrictions
57	Banjul, SK	BHP	14-Apr	Covid 19 - travel restrictions
58	Banjul, SK	Aethon/Koch	14-Apr	Covid 19 - travel restrictions
59	Barcelona, Spain	Cepsa	01-Jun	Declined on 20 May 2020 due to COVID-19 travel restrictions
60	Barranquilla, Colombia	BEICO	10-Apr	Port does not allow till further notice.
61	Basamuk, PNG			
62	Bataan, Philipine	PETRON	18-May	Regret to inform you that visiting inspector is not allowed as of the moment due to COVID-19 and we are still on community quarantine until May 30.
63	Beaumont, USA	Exxon/IMT	05-Apr	
64	Beira, Mozambique	ENOC	20-May	Covid 19 - travel restrictions
65	Beira, Mozambique	P66	27-Apr	Local inspector unavailable. (Covid-19 related)
66	Beira, Mozambique	Lukoil	27-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
67	Belem, Barzil	Petrobras	10-Apr	Petrobras are not carrying out inspections worldwide due to COVID-19
68	Belize	EQUINOR	19-May	Covid 19 - travel restrictions
69	Belize,	Equinor	01-Jun	Covid 19 - travel restrictions
70	Benicia, CA, USA	Phillips66	07-Apr	Terminal not allowed

71	Bethioua, Algeria	Shell	25-Jun	We regret we are unable to carry out the inspection at this time. We do not cover this Country.
72	Bilbao, Brazil			Imposed restrictions
73	Bilbao, Spain	PETRONOR	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
74	Bintulu OPL, Malaysia	Petronas	20-Apr	During Movement Control Order period, all personal enter Sarawak have to be complete compulsory quarantine for 14 days at hotel / hospital arrange by local government. After complete compulsory quarantine 14 days, auditor to need pass Port health screening before permitted to board vessel at anchorage. As per the above and also travel restrictions and safety of the inspector; we regret to inform cannot cover the inspection.
75	Bintulu, Malaysia	MMS	27-May	Due to COVID-19 and movement restriction, inspector need to be quarantine at Sarawak for 14 days before the inspection.
76	Bizerte, Tunisia	BP	09-Jun	short notice
77	Bizerte, Tunisia	Shell	08-Jun	unable to conduct inspection in Tunisia
78	Bonny, Nigeria	NLNG	19-Jun	Local inspector unavailable. (Covid-19 related)
79	Bonny, Nigeria	Petron	16-May	Terminal change policy – visitor/inspector need 14 days quarantine due to Covid-19.
80	Bontang , Indonesia	Idemitsu	17-Apr	No available local inspectors; travelling restrictions
81	Bordeaux, France	EQUINOR	17-May	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available for the given port/date to cover this request at the moment.
82	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
83	Boryeong, SK	PETRONAS	06-Apr	We do not have available inspectors and will decline inspection.
84	Botany Bay,	VIVA	15-Apr	Local inspector unavailable.
85	Botany Bay, Australia	Ampol	02-Apr	Due to situation of Coronavirus outbreak, OM are unable to process the inspection request.
86	Botany Bay, Australia	BP, Total, IMT, Lukoil, Ampol and Shell	10-Apr	Shell eventually took the inspection but finally terminal did not allow.
87	Botany Bay, Australia	BP	02-Apr	Travel restriction imposed in th country due to COVID 19
88	Bourgas, Bulgaria	SHELL	09-Apr	Local inspector unavailable.
89	Bourgas, Bulgaria	BP	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
90	Bourgas, Bulgaria	Chevrom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
91	Brisbane, Australia		03-Apr	Allowed- boarding of inspectors only 3hours after berthing. Check with agents.

92	Brisbane, Australia	ENOC	14-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
93	Brisbane, Australia	P66	17-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
94	Brisbane, Australia	CHEVRON	28-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
95	Brisbane, Australia	Chevron	28-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
96	Brunei	Gazprom, idemitsu, Equinor, Maxcom	04-Apr	other - complete lockdown due to COVID19
97	Brunei	All Majors/CDI	29-May	Information: Inspections not permitted in Brunei due to COVID-19 pandemic. All foreigners arriving Brunei need to serve 14 days quarantine period.
98	Burgas, Bulgaria	All Majors/CDI	01-May	Bulgaria is locked down due to COVID-19
99	Busan, SK		05-May	Not possible due to COVID 19 restrictions
100	Busan, SK		05-May	Not possible due to COVID 19 restrictions
101	Cabo Negro, Chile	CDI	16-May	Other - Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
102	Cabo Negro, Chile	CDI	16-May	Local inspector unavailable. (Covid-19 related)
103	Cabo Negro, Morocco	CDI	16-May	Inspection not permitted due to Terminal Internal Policy, not COVID-19 related
104	Cabo Negro, Morocco	CDI	16-May	Local inspector unavailable. (Covid-19 related)
105	Caldera, Chile	Marathon	22-Apr	Terminal restriction
106	Callao, Peru	ConocoPhillips	23-Apr	ConocoPhillips declined request due to Covid
107	Callao, Peru	CDI	08-May	Local inspector unavailable. (Covid-19 related)
108	Callao, Peru	Any OM	15-Jun	Foreign Inspector travel ban. Airports closed due Emergency declared till June 30th.
109	Canaport, Canada	Chevron	17-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
110	Canaport, Canada	Equinor	15-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
111	Canaport, Canada	EQUINOR	21-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
112	Canaport, Canada			Terminal quarantines vessel if inspector boards prior berthing. Not permitted during discharge. Vessel must be at sea for >14 days prior berthing. Post discharge you are allowed everything at the anchorage.
113	Caoeger Bay, South Africa	ENOC, Equinor	05-May	Local inspector unavailable. (Covid-19 related)
114	Caofeidian, PRC	Enoc, Total, Shell, P66, Bieco, Koch, BHP, IMT, Chevron	Feb	Inspection not allowed by Terminal due to COVID – 19

115	Cartagena, Colombia	Chevron	19-May	Inspector unavailability
116	Cartagena, Spain			Terminal not allowed or non-availability of any local inspector due COVID – 19
117	Cartagena, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
118	Cartagena, Spain	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
119	Castellon, Spain	Enoc	March	Inspection not allowed by Terminal due to COVID – 19
120	Castellon, Spain	Equinor	21-Mar	Terminal change policy - no visitor/inspector allowed due to Covid-19
121	Ceuta, Spain	Lukoil,Cepsa, OMV, Total. Maxcom, POT, Repsol, P66, Enoc	16-Apr	No local Inspectors and Covid-19 travel restrictions
122	Ceyhan, Turkey	ENOC	08-May	ENOC are unable to attend the vessel.
123	Ceyhan, Turkey		22-Apr	Checked with Agents - Complete lockdown No Vetting inspections allowed
124	Chang Xing, PRC	All OM	06-May	Terminal restriction
125	Changzhou Huarun, PRC		13-May	As per agents - not allowed
126	Changzhou, PRC	CDI	09-Jun	Pls kindly note subject vessel fixed calling Jiangyin/Changzhou/Taizhou. After checked with each port, Changzhou and Taizhou tml don't permit inspection nowadays due to COVID-19 even Chinese. For Jiangyin, as our agent reported, jgn port authorities need 14 days quarantine after inspection to government appointed hotel waiting 14 days.
127	Chennai, India	Chevron	04-Apr	other - complete lockdown due to COVID19
128	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
129	Chennai, India	BHP	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
130	Chiba, Japan	Equinor	07-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19.
131	Chiba, Japan		22-Apr	Not allowed due to COVID-19 restrictions

132	Chirique Grande, Panama	-	21-Jun	According to local agent, SIRE inspections are not allowed due to COVID 19.
133	Chiriqui Grande, Panama		16-Apr	Not possible due to COVID-19 restrictions
134	Chiriqui Grande, Panama	P66. Equinor	30-Apr	Not possible due to COVID 19 travel restrictions. No local inspector.
135	Chittagong	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
136	Chittagong, Bangladesh	ENOC	18-Mar	Due to travel restrictions from Bangladesh government, inspector has to be under 14 day quarantine upon arrival.
137	Chittagong, Bangladesh	BP	Apr	Terminal not allowing to board BP vetting inspector due to restriction.
138	Chittagong, Bangladesh	EQUINOR	12-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
139	Chittagong, Bangladesh	MAXCOM	11-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
140	Ciudad Madero, Mexico	Equinor	20-Apr	Due to the COVID-19 travel restrictions (Lock Down)
141	Coassa, Panama	All	10-May-20	Terminal under security level 2 – no visitor/inspector allowed due to Covid-19.
142	Coatzacoalcos, Mexico	EQUINOR	06-Apr	Covid 19 - travel restrictions
143	Coazacoalcos, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
144	Coazacoalcos, Mexico			Do not allow inspectors onboard.
145	Coega Bay, South Africa	Equinor	15-May	Local inspector unavailable. (Covid-19 related)
146	Coega Bay	P66	10-Jun	<ul style="list-style-type: none"> Local inspector unavailable. (Covid-19 related); Vessel has been rated as unacceptable due to no valid SIRE reports available ; Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
147	Conarky, Guinea	Lukoil, Alma	29-Mar	
148	Concepcion Bay, Chile	CHEVRON	10-Apr	Not able to attend due the new restriction during Easter holidays, travel problems due to COVID19. At this time the inspection is now cancelled.
149	Concepcion Bay, Chile	CHEVRON	11-Apr	Regret we will not be able to attend this one due the new restriction during Easter holidays, travel problems due to COVID19. Thank you very much for your help, at this time the inspection is now cancelled.
150	Conchan, Peru	CHEVRON	17-Mar	Peruvian Government has restricted citizens' movement within their homes and closed international travel with effect from 16 March to 1 April.

151	Conchan, Peru	REPSOL	18-Mar	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
152	Conchan, Peru	Any OM	15-Jun	Foreign Inspector travel ban. Airports closed due Emergency declared till June 30th.
153	Corpus Christi, USA	Koch	15-May	Covid 19 - travel restrictions
154	Corpus Christi, USA	Equinor	25-May	Personal issues with the inspector
155	Coruna, Spain	Cepsa	29-Apr	Only at their terminals at Huelva, Tenerife and Algeciras
156	Cotonou, Benin	CDI	17-Mar	Local inspector unavailable. (Covid-19 related)
157	Cotonou, Benin	CDI	21-Mar	Local inspector unavailable. (Covid-19 related)
158	Cotonou, Benin	Lukoil	16-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
159	Cotonou, Republic of Benin	Agent	07-May	Covid 19 - travel restrictions
160	Covenas, Colombia	NA	15-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19. (ADVISED THROUGH AGENT)
161	Covenas, Columbia		16-Apr	Not possible due to COVID-19 restrictions
162	Covenas, Columbia	ENOC	18-Apr	Permission not granted by terminal due to COVID-19 restrictions
163	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice
164	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
165	Cristobal, Panama	Phillips66	04-Apr	There are travel restrictions in the region due to COVID 19.
166	Cristobal, Panama	All Majors	03-Apr	Due to COVID-19 pandemic, Panama is locked down and no inspections are permitted till further notice. Exception is if the inspector is a local, however permission is required.
167	Cristobal, Panama		27-Mar	Travel restriction
168	Daesan, SK	TOTAL	05-Apr	Declined due to unavailability of inspectors
169	Daesan, SK	Total	31-May	Terminal prohibited any job other than cargo operation at berth. The same was explained you earlier and we have arranged his on / off schedule at the anchorage. However, the vessel's ETB delayed several hours again today as the terminal changed our vessel's jetty. And the inspector suddenly informed that he should cancel the inspection.
170	Daesan, SK			Not permitted by terminal
171	Daesan, SK	ENOC	12-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
172	Daesan, SK	IMT & BP	14-Feb	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
173	Dahej, India		01-May	Agents information due to terminal restrictions and lock-down

174	Dakar, Primorsk Oil Terminal, Senegal		10-Jun	Due to COVID restrictions, our inspectors are unable to reach Dakar and carry out the inspection onboard the vessel
175	Dakar, Senegal	P66, Idemitsu, Maxcom, ENOC, KOCH	06-Jul	Traveling restrictions
176	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
177	Dakar, Senegal	Maxcom	14-Apr	Covid 19 - travel restrictions
178	Dakar, Senegal	ENOC, BHP, agents	13-Apr	Covid 19 - travel restrictions
179	Dakar, Senegal	Koch, Aethon, Total	13-Apr	Covid 19 - travel restrictions
180	Dakar, Senegal	All Majors/CDI	10-Apr	Dakar is locked down due to COVID-19 and no inspections can be arranged
181	Dalian, PRC	Idemitsu	25-Jul	Local inspector only, and needs 14 days quarantine.
182	Dalian, PRC		13-May	As per agents - not allowed
183	Dalian, PRC	Shell, Chevron	27-May	Terminal restrictions; local inspectors only
184	Dalian, PRC	KOCH	24-26-Jun	Covid-19 restrictions
185	Dapeng, PRC	MMS	07-May	Visitor enter terminal must stay in this city "Shenzhen" longer than 14 days; Visitor should need Nucleic acid test of COVID-19 3 days before ship arrival, then we can make the application; Terminal will consider to approve or not base on Customs' quarantine pre examination on the vessel about 2-3 days before ship arrival(base on vessel's port calls records, crews conditions etc.
186	Djen Djen	BHP, ENOC, Chevron	03-Jul	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
187	Dominican Republic	P66	13-Apr	Due to the COVID-19 travel restrictions
188	Dominican Republic	Lukoil	13-Apr	Due to Dominican Republic is locked down
189	Donges, France	Enoc	23-May	OM - Regret due to COVID 19 we cannot attend this vessel.
190	Donges, France	P66	23-May	Unfortunately due to COVID 19, there are travel or terminal restrictions in the location you requested this inspection to be conducted in
191	Dongguan, PRC	any OM	03-Apr	Covid 19 - country lock down
192	Dongguan, PRC	BHP	18-Apr	Dongguan Immigration is not allowed the SIRE inspector to visit ship for this calling due to Dongguan got two confirmed COVID-19 cases in last week which from foreign ships.
193	Dongguan, PRC	BHP	22-Apr	We do not have available inspectors at the moment due to various virus restrictions and will decline inspections.
194	Dongguan, PRC	Shell	19-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
195	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Inspection at the moment yet.
196	Dongguan, PRC	Petron	03-May	We have liaised with Dongguan custom and immigration authority, they are not allowed for SIRE Inspection at the moment yet.
197	Dongguan, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19

198	Dongguan, PRC	Agent	25-Jun	
199	Dongguan, PRC	Maxcom	10-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
200	Dongguan, PRC	SIRE	25-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
201	Dongjiakou, {PRC	BHP	25-May	Covid 19 - travel restrictions
202	Dongjiakou, PRC			
203	Dongjiakou, PRC	Maxcom	07-Apr	Terminal is closed as per covid 19 restrictions
204	Dongjiakou, PRC	MAXCOM	07-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
205	Dongjiakou, PRC	Chevron	10-Apr	Plan 17/04/2020 - Chevron do not schedule SIRE inspection at China port at the moment.
206	Dongjiakou, PRC	Shell	10-Apr	Plan 17/04/2020 - Rejected due to COVID-19
207	Dongjiakou, PRC	KOCH	24-26-Jun	Covid-19 restrictions
208	Dongjiakou, PRC	KOCH	01-Jul	no visitor/inspector allowed due to Covid-19.
209	Dongying, PRC	EQUINOR	20-May	Covid 19 - travel restrictions
210	Dongying, PRC	BHP	21-May	Covid 19 - travel restrictions
211	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
212	Dongying, PRC	ENOC	23-May	Covid 19 - travel restrictions
213	Dongying, PRC	Maxcom	21-May	Covid 19 - travel restrictions
214	Dongying, PRC	Alma	22-May	Covid 19 - travel restrictions
215	Douala, Cameroon			Terminal not allowed or non-availability of any local inspector due COVID – 19
216	Douala, Cameroon	Gazprom,Total	01-Jun	Lockdown due to COVID19 - no local inspectors available
217	Dumai, Indonesia	BHP, Neste oil	05-Jun	Due to COVID-19 travel restrictions
218	Durban, South Africa	Shell	26-Mar	
219	Durban, South Africa	Shell	24-Mar	Covid 19 - country lock down
220	Durban, South Africa	Shell	26-Mar	Covid 19 - country lock down
221	El Segundo, California, USA		22-Apr	no visitor/inspector allowed due to Covid-19
222	El Segundo, USWC	Chevron, P66	21-May	Terminal change policy – visitor/inspector allowed due to Covid-19.
223	El Segundo, USWC	Chevron		Terminal does not permit
224	El Segundo, USWC	P66	09-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19. (Terminal belong to Chevron and operator requested them to inspect - tbc)
225	Ennore, India	Shell	04-Jun	Planned: Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections in India until further notice.
226	Ennore, India	ENOC	05-May	Terminal rejection of the inspector
227	Fawley, UK	EXXON	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
228	Fawley, UK			

229	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March: Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
230	Fawley, UK	LUKOIL	18-Mar	E-mail from LUKOIL 16 March: Our inspector has been informed by the local agent that as of this afternoon Fawley have updated their security level to 2, meaning that no vetting inspections can take place on board vessels until otherwise notified.
231	Fawley, UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
232	Fawley,UK	LUKOIL	03-Apr	No inspections possible in Fawley due to COVID-19 pandemic
233	Fortaleza, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
234	Fos, France			Member reported info from agent, now possible to do inspection
235	Fos, France	TOTAL & OMV	23-May	Unfortunately, we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling. We have just received the answer from the last Inspector, unfortunately, he is not available. In view of the above, we are force to postpone the inspection.
236	Freeport , USA	P66	25-Apr	Unfortunately, due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
237	Freeport ,USA	P66	25-Apr	Planned - Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
238	Freeport, Bahamas		10-Apr	Due to Lockdown
239	Freetown, Sierra Leone	P66, Idemitsu, Maxcom	06-Jul	Travelling restrictions
240	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
241	Fujairah, UAE	SHELL	22-Apr	Due to launch required for boarding
242	Fujairah, UAE	IMT	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
243	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
244	Fuzhou, PRC	All Majors/CDI	08-May	Terminal does not permit inspections due to COVID-19
245	Gabes, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions

246	Galveston Offshore lightering area	Chevron	24-Apr	Unavailability of inspector for this inspection
247	Ganyu, PRC	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
248	Gdansk, Poland	ENOC, KOCH	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
249	Geismar, USA	Conocophillips	27-Mar	OM advised they have cancelled due to COVID 19
250	Geismar, USA	Equinor	27-Mar	Equinor did not have inspector due to COVID 19
251	Gemlik, Turkey	CDI	09-Apr	Local inspector unavailable.
252	Geoje, SK		01-Jun	Not allowed by terminal
253	Ghent, Belgium	Neste	14-Apr	Due to corona restrictions within the Company
254	Gijón, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
255	Gizan, Saudi Arabia	Aramco	15-Jun	No third party attendance possible due to the security reasons. Aramco declined due to travel restrictions.
256	Goeje Yard, SK	PETROBRAS	21-May	Planned: Due to the outbreak of the COVID-19, currently we are not performing SIRE inspections in any port of the world
257	Guam, USA	BP,CHEVRON,P66,GAZPROM	10-Apr	Travel restrictions 14 days quarantine resulted to no inspectors available
258	Guam/Saipan, USA			Terminal not allowed or non-availability of any local inspector due COVID – 19
259	Guayanilla, Puerto Rico		16-Apr	Not possible due to COVID-19 restrictions
260	Guaynilla, Puerto Rico		20-May	Not possible as no local inspector and no flights operating to the island
261	Gulei, PRC		22-Mar	Due to COVID-19 not permitted by terminal
262	Gulei, PRC	Maxcom	09-May	Terminal restrictions
263	Gulei, PRC	ENOC	May-20	Terminal change policy – no visitor/inspector allowed due to Covid-19.
264	Hadera, Israel	Repsol	22-May	"Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception"
265	Hadera, Israel	Rightship, Total	22-May	Local inspector unavailable. (Covid-19 related)
266	Haldia, India		Apr	Terminal informed they will not allow vetting inspector to board due to restriction. India under lockdown.
267	Haldia, India	Idemitsu	04-May	India Lock down.
268	Haldia, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
269	Hamriyah, UAE	P66	Apr	Terminal did not allow BP vetting inspector to board due to COVID 19 restriction
270	Hazira, India	Rightship	01-Apr	country under lockdown - travelling prohibited within country

271	Hong Kong, PRC			
272	Honningssvåg, Norway	BP	03-Apr	Due the COVID-19 there is borders restriction to any non-residents (except for transit passengers).
273	Honningssvåg, Norway			
274	Honolulu, USA	SHELL	25-May	Travel restriction imposed in the country due to COVID 19.
275	Houston, USA	Equinor	Mar	Master has raised concerns about safety & health of the crew and has requested for deferring the inspection so as to avoiding/limit contact with visitors to the bare minimum. Tech. Manager agreed and postponed inspection.
276	Houston, USA	REPSOL	05-Apr-20	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
277	Houston, USA	Repsol	13-Apr	
278	Houston, USA	REPSOL	05-Apr	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. 2.- Vessels without a "fresh" SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
279	Houston, USA	Repsol	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
280	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-22
281	Houston, USA	IMT	28-Apr	Travel/border restrictions being imposed due to COVID-24
282	Huangdao, PRC	KOCH	24-26-Jun	Covid-19 restrictions
283	Huangdao, PRC	KOCH	01-Jul	no visitor/inspector allowed due to Covid-19.
284	Huelva, Spain			Imposed restrictions
285	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
286	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected, Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage

287	Huelva, Spain	Repsol	03-Apr	Repsol will only carry out inspections on case by case and vessels requiring essential services till 12-Apr-2020
288	Huelva, Spain	All Majors	03-Apr	Restrictions imposed by terminal as follows: Inspector cannot board the vessel from the terminal side, He can only board using a launch from the sea side at the anchorage or at the berth, Boarding at the berth is only possible with the chocks disconnected. Likewise disembarkation at the berth is also only possible with the chocks disconnected or can disembark at the anchorage
289	Huelva, Spain		18-May	Not possible due to COVID-19 restrictions in port.
290	Huizhou, PRC	Shell	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
291	Huizhou, PRC	P66	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
292	Huizhou, PRC	Petron	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
293	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April. Equinor do not have any available Inspector at Iceland due to COVID-19
294	Iceland	Equinor	16-Apr	E-mail from EQUINOR 14th of April: Equinor do not have any available Inspector at Iceland due to COVID-19
295	Ilo, Peru	Total	09-Jun	Due to the unavailability of an inspector in the port
296	Ilo, Peru	P66	08-Jun	Due to the COVID-19 travel or terminal restrictions
297	Immingham, UK	Ineos, Borealis, Shell	12-Apr	Local inspector unavailable. (Covid-19 related)
298	Incheon, SK			Not permitted by terminal
299	Incheon, SK		06-Jul	According to information from local agent: The terminal regulation for vetting inspection during cargo operation is asf;- i) Not allowed for any vessel of 1st calling at SKIPC terminal. ii) Allowed for vessel from 2nd calling at SKIPC terminal, which vessel have not any problem on her performance at prior calling.
300	Iskendrun, Turkey		29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
301	Itaqui, Brazil	BHP	17-Apr	We regret will not be able to cover vessel's inspection.
302	Itaqui, Brazil	ENOC	17-Apr	Regret due to COVID 19 travel restrictions we are unable to attend the vessel.
303	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.
304	Itaqui, Brazil	Shell	24-May	OM - We regret, due to COVID -19 travel restrictions we are unable to arrange this inspection.

305	Itaqui, Brazil	BP	24-May	OM - our inspectors are unable to cover Itaqui as the city it falls in Sao Luis is in lockdown
306	Itaqui, Brazil	Maxcom	24-May	OM- Much to our regret we can't cover as per Covid restrictions
307	Jasaan, Philippines	P66/BHP/Petron	28-May	No domestic flights available.
308	Jebel-Ali, UAE	Equinor	14-Apr	Inspection rejected - due to Hamriyah Terminal Restriction Not Allowed (COVID-19 pandemic).
309	Jebel-Ali, UAE	BP	11-Apr	Vessel had berth at SOET terminal, where SIRE Inspection are not permitted at COVID 19.
310	Jeddah, Saudi Arabia	BIECO	22-Apr	Terminal restriction
311	Jeddah, Saudi Arabia	Lukoil	26-Apr	Terminal restriction
312	Jeddah, Saudi Arabia	Any OM	09-Jun	Aramco Jeddah restricts to conduct any kind of inspection on their Terminals.
313	Jiangsu, PRC		27-Apr	Terminal restrictions
314	Jiangyin, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
315	Jiangyin, PRC	SIRE	25-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
316	Jiangyin,PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
317	Jiangyin, PRC	P66	03-Jun	COVID 19 travel or terminal restrictions in the location you requested this inspection to be conducted in.
318	Jisan, Saudi Arabia	Total, ENOC, AMPOL	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
319	JNPT India	P66	09-Jul	Unable to conduct inspection due to terminal restrictions
320	JNPT India	Idemitsu	05-Jun	Dy. Conservator JNPT not allowing any inspection at JNPT.
321	Jorf Lasfar, Morocco			Terminal not allowed or non-availability of any local inspector due COVID – 19
322	Jorf Lasfar, Morocco	CDI	Early March	CDI was postponed on the beginning of March intentionally. Planning was to perform CDI under new management after takeover in discharging port. Takeover plans were postponed due to COVID and therefore CDI inspection too.
323	Jorf Lasfar, Morocco	CDI	26-Mar	Local inspector unavailable. No inspector available due to COVID.
324	Jorf Lasfar, Morocco	SIRE	03-Apr	Other (National Lockdown - Travel restriction)
325	Jorf Lasfar, Morocco	Total, Shell, Borealis, Rightship, Equinor, Adnoc	04-May	Local inspector unavailable. (Covid-19 related)
326	Jorf Lasfar, Morocco	Lukoil	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19. (local inspector available and appointed)
327	Jorf Lasfar, Morocco	CDI	06-May	Local inspector unavailable. (Covid-19 related)
328	Jorf Lasfar, Morocco	SIRE	05-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
329	Jorf Lasfar, Morocco	CDI	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

330	Jose Ignacio	BHP, YPF, P66, Lukoil, Repsol, Total, Alma	06-Jul	
331	Jubail, Saudi Arabia	CDI	21-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
332	Kaarsto, Norway	Chevron, IMT	04-Jun	Inspector unavailability
333	Kakinada, India	CDI	24-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
334	Kakinada, India	EQUINOR	06-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
335	Kakinada, India	BP	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
336	Kakinada, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
337	Kalundborg, Denmark	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
338	Kandla, India	Rightship, Adnoc, Total, Shell, Bienco	25-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
339	Kandla, India	Adnoc, Total, Shell, Bienco	28-Apr	Local inspector unavailable. (Covid-19 related)
340	Kaohsiung, Taiwan	Idemitsu	09-Jul	Travelling restrictions
341	Kaohsiung, Taiwan	Equinor, BP	07-Jul	Travelling restrictions
342	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
343	Kaohsiung, Taiwan	Valero	17-Apr	Covid 19 - travel restrictions
344	Kaohsiung, Taiwan	Idemitsu	03-Apr	Inspections are possible only if a local inspector is available
345	Kaohsiung, Taiwan	Gazprom	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
346	Kaohsiung, Taiwan	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
347	Kaohsiung, Taiwan	Petron	18-Apr	Local inspector unavailable. (Covid-19 related)
348	Kaohsiung, Taiwan	Equinor	26-Jun	Due to the COVID-19 travel restrictions and local inspector unavailable.
349	Kaohsiung, Taiwan	CDI	18-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
350	Kaohsiung, Taiwan	BHP	29-Jun	Local inspector unavailable. (Covid-19 related)
351	Kaohsiung, Taiwan	Enoc	29-Jun	Due to the COVID-19 travel restrictions
352	Kaohsiung, Taiwan	Lukoil	27-Jun	Inspector unavailable.
353	Kaohsiung, Taiwan	ENOC	Apr-20	Inspector can not enter Taiwan due to restriction of entry policy for control of Covid 19
354	Kaohsiung, Taiwan	Idemitsu, Shell, BHP	March	Inspection not allowed by Terminal due to COVID – 19
355	Kaoshiung, Taiwan	SHELL, BP, CHEVRON, ENOC	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19 unavailable. (Covid-19 related)
356	Kaoshiung, Taiwan	ENOC	20-Apr	Local inspector unavailable. (Covid-19 related)
357	Kaoshiung, Taiwan	BHP	17-May	Travel restriction imposed in the country due to COVID 19.
358	Kaoshiung, Taiwan	Idemitsu	17-May	Travel restriction imposed in the country due to COVID 19.

359	Karachi, Pakistan	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
360	Karachi, Pakistan.	All Majors/CDI	10-Apr	Terminal does not permit inspections/crew change due to COVID-19
361	Karratha, Australia	BP	01-May	Terminal restrictions
362	Karratha, Australia	BP	01-May	Terminal restrictions
363	Karsto, Norway	CDI	15-Apr	Local inspector unavailable. (Covid-19 related)
364	Karsto, Norway	CDI	15-May	Local inspector unavailable. (Covid-19 related)
365	Kawasaki, Japan	SHELL	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
366	Kawasaki, Japan	P66	30-Apr	Travel/border restrictions being imposed due to COVID-19
367	Khalifa, U.A.E.	ENOC	26-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
368	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
369	Kikuma, Japan	Viva Energy	29-Mar	SIRE inspection is not allowed in terminals due to COVID at Japan.
370	Kingston,Jamaica		25-May	Not possible due to COVID-19 restrictions and country is under lockdown.
371	Klaipeda, Lithuania	BHP / P66 / Chevron	06-Jun	Due to COVID-19 travel restrictions
372	Koper , Slovenia	Q8	Feb-20	Restriction due to Covid 19
373	Kotka, Finland	Preem, Lukoil, Koch	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19; Local inspector unavailable. (Covid-19 related)
374	Kozmino, Russia	Lukoil	20-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
375	Kuantan, Malaysia	Gazprom	02-Apr	All hotels closed therefore inspector who was driving 6 hours refused to attend - only local inspectors allowed as there are travel restrictions
376	Kwinana, Australia	BP	01-Apr	Terminal restrictions
377	Kwinana, Australia	Chevron	15-Apr	Covid 19 - travel restrictions
378	Kwinana, Australia	BHP	26-May	Panned: Until further notice all non-essential and non- cargo operation visits such as SIRE inspections and routine technician visits will not be permitted during STS operations or when vessels are alongside the refinery jetties.
379	Kwinana, Australia	IMT	28-Jun	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
380	Kwinana, Australia	IMT	24-May	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
381	Kwinana, South Africa	IMT	28-Jun	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
382	La Libertad, Ecuador	Lukoil, Equinor, Rightship, BP, Koch	03-Apr	Local inspector unavailable. (Covid-19 related)

383	La Pampilla, Peru	IMT, Repsol, YPF, Sonangol, Maxcom, Gazprom, Phillips66, Shell	31-Mar	
384	La Pampilla, Peru	IMT	31-Mar	Covid 19 - travel restrictions
385	La Pampilla, Peru	Repsol	31-Mar	Covid 19 - travel restrictions
386	La Pampilla, Peru	YPF	31-Mar	Covid 19 - travel restrictions
387	La Pampilla, Peru	Sonangol	31-Mar	Covid 19 - travel restrictions
388	La Pampilla, Peru	Maxcom	31-Mar	Covid 19 - travel restrictions
389	La Pampilla, Peru	PMI	01-Apr	Covid 19 - travel restrictions
390	La Skhira, Tunisia			Terminal not allowed or non-availability of any local inspector due COVID – 19
391	Lagos, Nigeria	SHELL	07-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19.
392	Lagos, Nigeria	IMT	06-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19.
393	Lagos, Nigeria	ENOC	10-Apr	Local inspector unavailable. (Covid-19 related)
394	Lagos, Nigeria	Total	28-Apr	Not inspecting in Africa currently
395	Lagos, Nigeria	Nobody invited as informed by Agents	04-Apr	other - complete lockdown due to COVID19
396	Las Minas, Panama	BHP	27-May	Local inspector unavailable. (Covid-19 related)
397	Las Minas, Panama	BHP	27-May	A local inspector is unavailable. (Covid-19 related)
398	Las Palmas, Spain	ENOC	24-Apr	Covid 19 - travel restrictions
399	Las Palmas, Spain	CEPSA	24-Apr	Covid 19 - travel restrictions
400	Las Palmas, Spain	Repsol	27-Apr	Covid 19 - travel restrictions
401	Las Palmas, Spain	Cepsa	30-May	MOC is not authorized to perform inspections outside Cepsa Terminals at Huelva, Algeciras or Tenerife.
402	Las Palmas, Spain	Repsol	01-Jun	Repsol does not inspect any vessel except special situations due to Covid-19
403	Lavera, France	KOCH	06-Apr	Not be able to plan the attendance due to COVID 19 travel restrictions
404	Lavera, France	BHP	06-Apr	Do not have available inspectors due to present virus situation. Flight and transport restriction beyond our control
405	Lavera, France	CDI	24-Apr	Travel restriction.
406	Lavera, Portugal	POT	10-Apr	Others - Due to COVID-19, POT do not inspect vessels temporarily.
407	Lavera, Portugal	GAZPROM	10-Apr	Local inspector unavailable.
408	Lavera, Portugal	P66	09-Apr	Local inspector unavailable.
409	Lavera, Portugal	ENOC	09-Apr	Local inspector unavailable.
410	Lavera, Portugal	BHP	06-Apr	Local inspector unavailable.
411	Lavera, Portugal	KOCH	06-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period.
412	Lebanon	KMG, Maxcom	06-Jul	
413	Le Havre, France	CDI	25-Mar	Tech. manager decided to do not proceed with inspection in France to do not put crew in

				unnecessary risk – requested for CDI validity extension (successfully).
414	Le port, Reunion			Terminal not allowed or non-availability of any local inspector due COVID – 19
415	Leixioes, Portugal	Maxcom	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
416	Lianyungang , PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
417	Lianyungang , PRC	P66	03-May	No inspector available due to COVID-19 travel/border restrictions
418	Lianyungang, China	CDI, Xinrongtai	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
419	Lianyungang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
420	Lianyungang, PRC	Maxcom, ALMA	14-Apr	Covid 19 - travel restrictions
421	Lianyungang, PRC	BHP, Lukoil	14-Apr	Covid 19 - travel restrictions
422	Lianyungang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
423	Lianyungang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
424	Lianyungang, PRC	IMT	02-May	Travel/border restrictions being imposed due to COVID-19
425	Lianyungang, PRC	SHELL	03-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
426	Lianyungangn, PRC	All Majors/CDI	24-Apr	Terminal does not permit inspections due to COVID-19
427	Libreville, Gabon	CDI	March	Inspection not allowed by Terminal due to COVID – 19
428	Limay, Phillipines	IMT	01-Apr	Due to COVID-19 not permitted by terminal
429	Limbe, Cameroon	Shell, Enoc	05-Feb	Local inspector unavailable.
430	Limbe, Cameroon	BP, Maxcom	25-Mar	Inspection cancelled , due to Lockdown and restricted movement by air, road, etc
431	Limetree Bay, US Virgin Islands	P66	17-Apr	Due to the COVID-19 travel restrictions (Lock Down)
432	Lisbon, Portugal	BP	09-May	Understand from our inspectors in the region that Portugal borders are closed till at least 15th May and likely to be extended to June.
433	Lome OPL, Togo	Agent	14-May	Covid 19 - travel restrictions
434	Lome OPL, Togo	Agent	15-May	Covid 19 - travel restrictions
435	Lome OPL, Togo	Alma	15-May	Covid 19 - travel restrictions
436	Lome, Togo	Shell	22-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
437	Lome, Togo	Lukoil	22-Apr	Lome is locked down
438	Lome, Togo	CDI	16-Mar	Local inspector unavailable. (Covid-19 related)
439	Lome, Togo	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)
440	Lome, Togo	ENOC	27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
441	Lome, Togo	Lukoil, ENOC, KOCH	06-Jul	Local inspector unavailable (Covid-19 related)
442	Lome, Togo	P66	03-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19.
443	Lome, Togo	P66, ENOC	10-Jun	Foreign Inspector travel ban
444	Lome, Togo	P66	19-Jun	Local inspector unavailable. (Covid-19 related)
445	Lome, Togo	P66	30-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

446	Lome, Togo	Lukoil	30-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
447	Lome, Togo	Ampol	30-Jun	Local inspector unavailable. (Covid-19 related)
448	Long Beach, CA, USA	Shell	30-Mar	Cancelled
449	Loop, USA	Lukoil, ENOC, Maxom	24-Mar	
450	Loop, USA	Lukoil	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
451	Loop, USA	ENOC	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
452	Loop, USA	Maxcom	24-Mar	Covid 19 - travel restrictions / 14 days guarantee rule
453	Loop, USA	PHILLIPS 66	12-Apr-20	There are travel restrictions in the region. To submit a new inspection request once next berthing orders are known and OM will try to accommodate inspection request.
454	Loop, USA	PHILLIPS 66	12-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in. Please feel free to submit a new inspection request once next berthing orders are known and we will try to accommodate your inspection request.
455	Loop, USA	Exxon	14-May	Unable to attend
456	Louisiana, USG	Marathon		Cancelled
457	Luanda, Angola	BHP , Maxcom, P66	13-Mar	Complete lockdown due to COVID19
458	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
459	Luanda, Angola	Agent	14-May	Covid 19 - travel restrictions
460	Luanda, Angola	Chevron	03-Jun	Covid 19 - travel restrictions
461	Lubuk Guang, Indonesia	P66	18-Jun	Terminal change policy – visitor/inspector need 14 days quarantine due to Covid-19.
462	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
463	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
464	Lyttelton, New Zeland	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
465	Mailiao, Taiwan			
466	Mailiao, Taiwan	CDI	29-Mar	Local inspector unavailable. (Covid-19 related)
467	Mailiao, Taiwan	CDI	18-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
468	Malta	Lukoil	16-Apr	Due to Malta is locked down
469	Malta	ENOC, Koch, BIECO	27-Apr	Malta is Locked down, local inspector unavailable
470	Malta	IMT/SHELL/TOTAL	15-May	Malta in lockdown due to COVID
471	Malta	NA	05-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19. (ADVISED THROUGH AGENT)
472	Mamonal, Colombia	CHEVRON	15-Apr	Regret to inform that we do not have an inspector available for this inspection

473	Mamonal, Colombia	LUKOIL	15-Apr	Please be informed that due to terminal restrictions inspection cannot be arranged at Mamonal.
474	Mamonal, Colombia	PHILLIPS 66	15-Apr	Unfortunately due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
475	Manaus, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
476	Mangalore, India	Idemitsu	17-May	Others
477	Manzanillo, Mexico	P66, Shell	April	Inspection not allowed as interstate travel is restricted due to Covid 19
478	Manzanillo, Mexico	P66	14-Apr	Inspection declined due to COVID -19
479	Manzanillo, Mexico	ENOC	14-Apr	Inspection declined due to COVID -19
480	Manzanillo, Mexico	P66	14-Apr	due to COVID 19, there are travel restrictions in the region you requested this inspection to be conducted in.
481	Manzanillo, Mexico	Equinor	14-Apr	Due to travel restrictions imposed by the covid-19 outbreak, there are no inspectors available to cover this request at the moment.
482	Manzatlan, Mexico	Shell, Chevron, Maratthon, P66	10-Apr	Due Covid-19 sanction.
483	Map Ta Phut, Thailand	IMT	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
484	Map Ta Phut, Thailand	SHELL	22-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
485	Map ta Phut, Thailand	Lukoil	02-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
486	Map Ta Phut, Thailand	Agent	04-May	Covid 19 - travel restrictions
487	Map Ta Phut, Thailand	MMS	28-May	The current situation due to COVID-19 outbreak, PTTLNG terminal not allow to do site inspection ,Please find attached PTTLNG's guideline for COVID-19 restriction for reference. Noted : The Civil Aviation Authority of Thailand (CAAT) has announced an extension of temporary ban on all international passenger flights to Thailand until 30 June 2020.
488	Map Ta Phut, Thailand	Shell, BP	07-Jun	Local inspector unavailable. (Covid-19 related)
489	Map Ta Phut, Thailand		1-8 Apr	
490	Maptaphut, Thailand	PTT	07-May	According to the "State of Emergency" declaration in Thailand and limitations of Terminal access granted in related to COVID-19 pandemic. PTT Inspection will not be able to assign during this period. Expected the situation will be released by end of this month.
491	Maptaphut, Thailand	Agents	14-Jun	Lockdown due to COVID19 - terminal restrictions also apply not even local inspectors allowed

492	Map-Ta-Phut, Thailand			Terminal not allowed or non-availability of any local inspector due COVID – 19
493	Maptaphut,Thailand	Agents	16-Jun	Lockdown due to COVID19 - terminal restrictions also apply not even local inspectors allowed
494	Maputo, Mozambique	Lukoil	07-Apr	COVID-19 – traveling restrictions. No local inspector available.
495	Maputo, Mozambique	P66	07-Apr	COVID-19 – traveling restrictions. No local inspector available.
496	Maputo, Mozambique	MAXCOM	07-Apr	COVID-19 – traveling restrictions. No local inspector available.
497	Maputo, Mozambique	ENOC	07-Apr	COVID-19 – traveling restrictions. No local inspector available.
498	Maputo, Mozambique	ENOC	14-Apr	COVID-19 – traveling restrictions. No local inspector available.
499	Maputo, Mozambique	Agenta	23-May	Covid 19 - travel restrictions
500	Marcus Hook, USA	CDI	13-Mar	Nominated inspector declined to attend due to COVID
501	Marcus Hook, USA	CDI	31-Mar	No inspector available due to travel restrictions caused by COVID spread. Local inspector unavailable.
502	Marmara, Turkey			Terminal not allowed or non-availability of any local inspector due COVID – 19
503	Marmara, Turkey	IMT, BP,TOTAL,CHEVRON,SHELL.	10-Apr	Terminal lock down
504	Matosinhos, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
505	Mazatlan, Mexico		10-Apr	No local inspectors available
506	Mazatlan, Mexico	Chevron	15-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
507	Mazatlan, Mexico	PMI	17-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
508	Mazatlan, Mexico	Enoc	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
509	Mazatlan, Mexico	IMT	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
510	Mazatlan, Mexico	Shell	08-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
511	Mazatlan, Mexico	BHP	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
512	Mazatlan, Mexico	Total	16-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
513	Mejillones, Mexico	CDI	12-May	Local inspector unavailable. (Covid-19 related)
514	Melbourne, Australia	BHP	March	Inspection not allowed by Terminal due to COVID – 19

515	Merak, Indonesia	PHILLIPS66	13-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
516	Merak, Indonesia	ENOC	02-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
517	Merak, Indonesia	ENOC	07-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
518	Mesaieed, Qatar	Shell	19-May	OM - We regret we are unable to carry out the inspection at this time. We do not have any local inspectors available
519	Mesaieed, Qatar	BP	19-May	OM - our inspectors in the region are unable to make it due to travel restrictions in place for COVID-19 pandemic.
520	Mesaieed, Qatar	IMT	22-May	OM - Due to COVID-19 pandemic worldwide , with travel/border restrictions being imposed in many countries, we regret to inform that we are currently unable to arrange as your request.
521	Mesaieed, Qatar	TOTAL	22-May	OM - Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling.
522	Midia, Romania	All Majors/CDI	01-May	Inspections are not possible in Romania due to travel restrictions due to COVID-19 pandemic
523	Milazzo , Italy	ENI	1-8 Apr	
524	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
525	Mina Al Ahmadi, Kuwait	IMT	12-Apr	country under lockdown - travelling prohibited within country
526	Mina Al Ahmadi, Kuwait	CDI	21-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
527	Mina Al Ahmadi, Kuwait		27-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
528	Mina Al-Ahmadi, Kuwait	KOCH	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
529	Mina Al-Ahmadi, Kuwait	ENOC	10-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
530	Mina Al-Mahadi, Kuwait	BHP	06-May	Unfortunately the UAE /Gulf countries have not yet provided a clear indications as to when flights will resume. In that regards, visas too will not be issued.
531	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
532	Mizushima, Japan	IMT	03-Apr	Local inspector unavailable. (Covid-19 related)
533	Mobile, Alabama	Koch	02-Apr	Declined inspection as no inspector available. Likely due to COVID19
534	Mobile, Alabama	Lukoil	10-Apr	Inspector could not make in time due to delay at travel checkpoints en route
535	Mohammedia, Morrocco	CDI	26-Apr	Local inspector unavailable. (Covid-19 related)
536	Molendo, Peru		09-Jul	According to information from local agent, it is currently NOT possible for people to arrive Arequipa region (therefore Mollendo port) due to this region still facing Covid 19 infection.
537	Mombasa, Kenya	BHP	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

538	Monroe Terminal, Philadelphia, USEC			Not permitted as vetting considered non essential
539	Monrovia, Liberia	P66, Idemitsu, Maxcom	06-Jul	travelling restrictions
540	Monteverde, Portugal	P66, ConocoPhilips	01-Apr	Local inspector unavailable. (Covid-19 related)
541	Montevideo	CDI	13-Jul	Local inspector unavailable. (Covid-19 related)
542	Montoir, France			
543	Morocco	All Majors/CDI	10-Apr	Morocco is locked down due to COVID-19 and no inspections can be arranged
544	Mossel Bay, South Africa	Lukoil	22-Jun	Harbour Master does not allow Inspector boarding due to Covid-19 measures
545	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
546	Muara, Brunei	Equinor	30-Apr	Travelling restrictions
547	Muara, Brunei	ENOC	11-Jun	Covid 19 - travel restrictions
548	Muara, Brunei	BHP	11-Jun	Covid 19 - travel restrictions
549	Mumbai - JNPT, India	ENOC	03-Apr	Not possible due to COVID-19 Restrictions lockdown
550	Mumbai	Ampol	06-Jul	we are unable to conduct the subject inspection due to the current Covid-19 Outbreak situation in the requested port of inspection
551	Mumbai, India	Chevron	07-Apr	Travelling restrictions
552	Mumbai, India	Phillips 66	12-Apr	Complete lockdown in India due to COVID 19. No public or private transportation's are available.
553	Mumbai, India	ENOC	25-Apr	Covid 19 - travel restrictions
554	Mumbai, India	Lukoil	24-Apr	Covid 19 - travel restrictions
555	Mumbai, India	EQUINOR	15-May	Inspector while trying to attempt to go onboard the subject vessel for conducting SIRE inspection, he was unable to embark the vessel due to excessive swell (embarking on Eagle Victoria was aborted after making several attempts to board the vessel).
556	Mundra, India	Chevron	06-Apr	Travelling restrictions
557	Murmansk, Russia	SHELL	29-Apr	Please be advised that, in accordance with COVID-19 travel restrictions, we are currently unable to arrange ship inspections Russia until further notice.
558	Murmansk, Russia	GAZPROM	28-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
559	Murmansk, Russia	LUKOIL	24-Apr	As per agents quarantine isolation for two weeks is imposed at airport for the passengers arriving from Moscow.
560	Murmansk, Russia	LUKOIL	22-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
561	Murmansk, Russia	TOTAL	18-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
562	Naantali, Finland	LUKOIL	25-Mar	E-mail from LUKOIL 23 March: We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.

563	Naantali, Finland	LUKOIL	25/03/2020	E-mail from LUKOIL 23 March: We regret to tell you that we will not be able to arrange the subject vessel inspection during this call at Naantali due to the travel restrictions implemented by the Finnish Government.
564	Nanjing, PRC	Shell, Preem	15-Apr	Local inspector unavailable. (Covid-19 related)
565	Nanjing, PRC	ConocoPhilips	15-Apr	All inspections paused due to Covid-19
566	Nanjing, PRC	CDI	06-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
567	Nansha, PRC	Shell	30-Mar	
568	Nansha, PRC	Shell	30-Mar	Covid 19 - terminal restrictions
569	Nantong, PRC	P66	27-Apr	Port authorities imposed 14 days quarantine for inspectors after inspection
570	Nantong, PRC	Lukoil	06-Jun	Covid 19 - travel restrictions
571	Nantong, PRC	IMT	24-Jun	OM - Due to current COVID-19 pandemic situation worldwide , we regret to inform that we are currently unable to arrange as your request.
572	Nantong, PRC	IMT	24-Jun	OM- Due to current COVID-19 pandemic situation worldwide , we regret to inform that we are currently unable to arrange as your request
573	Napier, France	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
574	Napier, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
575	Napier, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
576	New plymouth, New Zeland	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
577	New plymouth, New Zeland	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
578	New Plymouth, New Zeland	Shell, Idemitsu, BHPB	03-Apr	Local inspector unavailable. (Covid-19 related)
579	New York, USA			
580	New York, USA	Lukoil	25-Apr	Lukoil cancelled the inspection due to COVID-19.
581	Newcastle, Australia	IMT	Apr	Due to current rapidly increasing severity of COVID-19 pandemic worldwide and with travel/border restrictions being imposed in many countries, we regret to inform you that we are unable to arrange as your request for the subject vessel.
582	Newcastle, Australia			Terminal not allowed or non-availability of any local inspector due COVID – 19

583	Newyork / US	Total	14-Apr	Due to the unavailability of an inspector in the port
584	Ningbo, PRC	Total	12-Jul	No inspector available
585	Ningbo, PRC	Koch	02-Apr	Terminal not allowed any visitors due to Covid-19
586	NingBo, PRC	Petron	Apr-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
587	NingBo, PRC	EQUINOR	03-Apr	Due to COVID-19 not permitted by terminal
588	Ningbo, PRC	BP	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
589	Ningbo, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
590	Ningbo, PRC	Lukoil	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
591	Ningbo, PRC		25-May	COVID-19 restrictions
592	Ningbo, PRC	CDI	18-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
593	Ningbo, PRC	SIRE	25-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
594	Ningbo, PRC	CDI	27-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
595	Nipah, Indonesia	IMT, Lukoil, Shell, BP, Maxcom	10-Apr	No inspectors available.
596	Nipah, Indonesia	Idemitsu	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
597	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-23
598	Nipah, Indonesia	P66	28-Apr	Travel/border restrictions being imposed due to COVID-25
599	Ocoa Bay, Dominican Republic	All Majors	03-Apr	No local inspectors available in Dominican Republic
600	Omoa, Honduras	Equinor, KOCH	07-May	No available local inspectors; travelling restrictions
601	Onsan, SK		20-Mar	Due to COVID-19 not permitted by terminal
602	Onsan, SK	Shell	March	Inspection not allowed by Terminal due to COVID – 19
603	Ornskoldsvik, Sweden	Lukoil	29-Apr	Declined due to COVID-19 travel restrictions
604	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
605	Pachi, Greece	Lukoil	11-Apr	Inspection not allowed at the terminal (Pachi Marine Terminal).
606	Pajaritos, Mexico	CDI	14-Apr	Local inspector unavailable. (Covid-19 related)
607	Pajaritos, Mexico	Lukoil	05-May	Not Inspected. Terminal don't allow the permission for Vetting inspector.

608	Panama			Local restriction
609	Panama	BHP		Not permitted as didn't have local presence.
610	Panama	GAZPROM	09-Mar	Not permitted
611	Paradip, India		1-8 Apr	
612	Paradip, India	N/A	09-Apr	Other (National Lockdown - Travel restriction)
613	Paradip, India	SIRE	09-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
614	Paranagua, Brazil			Imposed restrictions
615	Paranagua, Brazil	Equinor, P66, Koch, Shell	01-Apr	Local inspector unavailable.
616	Paranagua, Brazil	Equinor	03-Apr	Local inspector unavailable. (Covid-19 related)
617	Pasir Gudang, Malaysia	Petron	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic
618	Pembroke, UK	Chevron, Shell, Koch,	06-Jul	
619	Pembroke, UK	EQUINOR	22-May	Planned: According to information received from agent, terminal does not allow inspections to be carried out due to restrictions in force.
620	Pengerang, Malaysia		08-Apr	Due to COVID-19 not permitted by terminal
621	Pengerang, Malaysia	Petronas	14-Apr	MMS does not allow inspector to stay overnight on vessel, As per terminal, inspector to board prior berthing and disembark upon departure from terminal
622	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-19
623	Pengerang, Malaysia	Petron	25-Apr	Travel/border restrictions being imposed due to COVID-20
624	Peru	Repsol	24-Apr	Covid 19 - travel restrictions
625	Philippines	All Majors/CDI	29-May	Information: Inspections not permitted in Philippines due to COVID-19 pandemic. All foreigners arriving Philippines need to serve 14 days quarantine period.
626	Pinkenba, Australia			
627	PISCO	KOCH	14-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
628	Pisco, Peru	EXXON	11-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
629	Point Comfort, USA	CDI	23-Mar	Local inspector unavailable. (Covid-19 related)
630	Point Lisas, Trinidad & Tobago	Lukoil, Savonetta, SP#2 South & SP#4	30-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
631	Point Lisas, Trinidad & Tobago	CDI	21-Apr	Local inspector unavailable. (Covid-19 related)
632	Point Lisas, Trinidad & Tobago	Lukoil, Shell, Rightship, Equinor	10-Apr	Local inspector unavailable. (Covid-19 related)
633	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
634	Point Lisas, Trinidad & Tobago	CDI	05-Apr	Local inspector unavailable. (Covid-19 related)
635	Point Lisas, Trinidad & Tobago	CDI	25-Apr	Local inspector unavailable. (Covid-19 related)

636	Point Lisas, Trinidad & Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
637	Point Lisas, Trinidad and Tobago	CDI	07-May	Local inspector unavailable. (Covid-19 related)
638	Point Lisas, Trnindad and Tobago	All Majors	03-Apr	No local inspectors available in Point Lisas and airport closed down till further notice.
639	Pointe-A- Pierre, Trinidad and Tobago		19-Jun	Not allowed due to COVID restrictions
640	Port Allan, USA	EQUINOR	24-Apr	Covid 19 - travel restrictions
641	Port Allan, USA	ENOC	27-Apr	Covid 19 - travel restrictions
642	Port Dickson, Malaysia	Idemitsu	03-Apr	Inspections are not possible till further notice due to COVID-19 pandemic .
643	Port Dickson, Malaysia	CDI	16-Apr	lockdown due to COVID19 - Foreign inspectors not allowed to travel to Malaysia
644	Port Elizabeth, South Africa		16-Apr	no visitor/inspector allowed due to Covid-19
645	Port Elizabeth, South Africa	CDI	04-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
646	Port Esquivel, Jamaica	BHP	30-Mar	
647	Port Esquivel, Jamaica	BHP	30-Mar	Covid 19 - travel restrictions
648	Port Esquivel, Jamaica	Maxcom	01-Apr	Covid 19 - travel restrictions
649	Port Everglades, USA	ENOC	24-Apr	Local inspector unavailable. (Covid-19 related)
650	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
651	Port Kasim, Pakistan	CDI	13-May	Local inspector unavailable. (Covid-19 related)
652	Port Klang, Malaysia	CDI	01-May	Malaysia lock down till 12th May as per message from agents. Only local inspectors allowed to carry out the inspection subject to terminal permission. CDI does not have any local inspector in Malaysia.
653	Port Louis, Mauritius	CDI	01-Jun	Local inspector unavailable. (Covid-19 related)
654	Port Moresby, Papua New Guinea	Chevron, BHP	27-May	Due to the COVID-19 travel restrictions
655	Port Moresby, Papua New Guinea	Chevron	27-May	Due to the COVID-19 travel restrictions
656	Port Moresby, Papua New Guinea	BHP	25-May	A local inspector is unavailable. (Covid-19 related)
657	Port Moresby, Papua New Guinea	Equinor	02-Jun	Papua New Guinea that no shoreside personnel are permitted onboard any vessels
658	Port Qasim	Rightship	06-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19.
659	Port Reunion	CDI	03-Apr	No local inspectors available.
660	Port Said, Egypt	Gazprom	28-Apr	Complete lockdown No Vetting inspections allowed
661	Port Said, Egypt	CDI	24-May	Local inspector unavailable. (Covid-19 related)
662	Port Said, Egypt	Equinor	02-Jul	Not having local inspector
663	Port Said, Egypt	ENOC	01-Jul	Not having local inspector

664	Port Sudan, Sudan	Enoc	28-Jun	Regret due to COVID 19 travel restrictions we are unable to attend the vessel.
665	Port Sudan, Sudan	Enoc	28-Jun	Regret due to COVID 19 travel restrictions we are unable to attend the vessel.
666	Porto Do Acu, Brazil	ENOC	15-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
667	Pozos Colorados, Colombia			
668	Priolo, Italy	CDI	28-May	
669	Pt. Lisas, USA	CDI	08-Apr	Due to the current travel restrictions CDI unable to assign inspector at T & T
670	Puerto Bahia, Colombia		10-Apr	No inspectors available
671	Puerto Cortes, Honduras	CDI	14-Apr	Covid 19 - travel restrictions
672	Puerto Cortes, Honduras	Agents	14-Apr	Covid 19 - travel restrictions
673	Puerto Moin, Costa Rica	SHELL	08-Jul	Local inspector unavailable. (Covid-19 related)
674	Puerto Moin, Costa Rica	Lukoil	04-May	Not Inspected. Vetting inspections are not allowed to be performed alongside (only at anchorage)
675	Puerto Santo Tomas, Guatemala			Terminal not allowed or non-availability of any local inspector due COVID – 19
676	Pyeongtaek, South Korea	CDI, SPTT	17-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
677	Qidong, PRC	ENOC	06-Apr	Terminal restrictions
678	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
679	Qingdao, PRC	ENOC	01-May	Terminal restrictions
680	Qingdao, PRC	Petron	05-May	Terminal rejection of the inspector
681	Qingdao, PRC			
682	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
683	Qingdao, PRC	Shell	16-Apr	Terminal restrictions
684	Qingdao, PRC	Chevron	01-May	Declined as 'requirements in Huangdao Terminal are complicated and it's difficult to enter the terminal'
685	Qingdao, PRC	BHP	13-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
686	Qingdao, PRC	PHILLIPS66	12-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
687	Qingdao, PRC	TOTAL, P66	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
688	Qingdao, PRC	SHELL	11-Jun	Pls be advised inspector is not allowed to get on board according to Qingdao terminal's latest regulation. Fyi: No person is allowed to get on board except boarding agent and CIQ officers.
689	Qingdao, PRC	BP	22-Jun	Terminal policy- no visitor/inspector allowed due to Covid-19
690	Qingdao, PRC	Any OM	01-Jul	no visitor/inspector allowed due to Covid-19.

691	Quanzhou, China	Lukoil, Powershell Terminal	11-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
692	Quanzhou, PRC	P66	Mar-20	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
693	Quanzhou, PRC	CDI	20-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
694	Quanzhou, PRC	TOTAL	04-Jun	Due to unavailability of local inspector
695	Quanzhou, PRC	P66	05-Jun	Agents cannot confirm that permit will be granted by local authorities
696	Quintero, Chile	IMT	16-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
697	Quintero, Chile	Marathon	16-Apr	Due to COVID-19, the terminal is no allowing inspections
698	Quintero, Mexico			
699	Rades, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions
700	Ramallo, Argentina	BHP	22-Jun	But sorry, not yet, the covid situation arrived later & is exploding here in Argentina in this & coming weeks, Measures are being strengthened and house confinement imposed (one of the longest worldwide) goes on, as well as borders remaining closed, internal flights curtailed, even road traffic permits limited, etc, etc, etc. As a result an inspection, even in Ramallo, where I usually travel by car to inspect, is not yet feasible.
701	Ramallo, Argentina	KOCH	22-Jun	But unfortunately, please note that as per the current Sanitary Situation and COVID-19, the country is under a mandatory quarantine, with a full closure of borders. In this way, it is not possible for an inspector to arrive and carry out this inspection.
702	Ras Al Khair, Saudi Arabia	Gazprom	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
703	Ras Al Khair, Saudi Arabia	ENOC	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
704	Ras Al Khair, Saudi Arabia	Adnoc, Rightship, Koch, Shell	10-Apr	Local inspector unavailable. (Covid-19 related)
705	Ras Al Khair, Saudi Arabia	CDI	14-Mar	Local inspector unavailable. (Covid-19 related)
706	Ras Al Khair, Saudi Arabia	CDI	10-Apr	Local inspector unavailable. (Covid-19 related)
707	Ras Laffan, Qatar		23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
708	Ras Tanura, Saudi Arabia	ENOC	31-Mar	Covid 19 - travel restrictions
709	Ras Tanura, Saudi Arabia	Maxcom	31-Mar	Covid 19 - travel restrictions
710	Ras Tanura, Saudi Arabia	BHP	01-Apr	Covid 19 - travel restrictions
711	Ras Tanura, Saudi Arabia	ENI	01-Apr	Covid 19 - travel restrictions

712	Ras Tanura. Saudi Arabia	ENOC, Maxcom, BHP, ENI	01-Apr	
713	Ras Tanurah, Saudi Arabia	Adnoc, Saudi Aramco, Total, Lukoil, P66	26-Apr	Local inspector unavailable. (Covid-19 related)
714	Rayong, Thailand		27-Apr	Agents - Covid 19 - travel restrictions
715	Rayong, Thailand	Equinor	26-Jun	
716	Rayong, Thailand	Alma	29-Jun	
717	Reunion	CDI	03-Apr	No local inspectors available.
718	Richard's Bay, South Africa	Rightship, Total, Shell, Neste, Respol, YPF, Conocophilips,Preem	23-Apr	Local inspector unavailable. (Covid-19 related)
719	Richmond, USA	Lukoil	03-Apr	Not possible due to COVID-19 Restrictions. Only critical personnel allowed.
720	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.
721	Rijeka, Croatia	All Majors/CDI	08-May	Only local inspectors are allowed to carry out the inspection. Restriction placed on foreigners traveling to Rijeka for the purpose of inspection.
722	Rijeka, Croatia	LUKOIL	10-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
723	Rio de Janeiro, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
724	Rio Grande, Brazil			Imposed restrictions
725	Rio Haina, Dominican Republic	CDI	09-May	Local inspector unavailable. (Covid-19 related)
726	Rizhao, PRC	Shell and Maxcom	25-Jan	Inspector's not willing to go due to COVID19
727	Rizhao, PRC	SHELL	05-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
728	Rizhao, PRC	Chevron	08-May	No available local inspectors; travelling restrictions
729	Rizhao, PRC	P66	05-Jun	Covid 19 - travel restrictions
730	Rizhao, PRC		1-8 Apr	
731	Rotterdam, Netherland	CDI	20-Mar	Inspector refused travelling to Rotterdam due to airport closure at ISLE OF MAN
732	Rotterdam, Netherlands	SHELL	25-May	We regret we are unable to carry out the inspection at this time, as we do not have any local inspectors available. Please request again at a later date.
733	Rotterdam, Netherlands	Equinor	08-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
734	Rovigo, Itali	Shell	05-May	Inspector required to embark by launch
735	Rovigo, Itali	Repsol	05-May	Inspection deemed 'not exceptional' due to Covid-19

736	Rovigo, Itali	BP	05-May	Inspection declined as inspector would have had to remain onboard overnight
737	Rudong, PRC	Phillips66	03-Apr	Terminal restrictions
738	Ruwais, Qatar	Shell	22-Apr	Due to pandemic, OM accepted alternative option - ie screening of SIRE inspection; operator self-inspection and reports.
739	Ruwais, Qatar	Adnoc, Total, Preem, P66	22-Apr	Local inspector unavailable. (Covid-19 related)
740	Ruwais, Qatar	Bienco	22-Apr	No response from OM
741	Ruwais, UAE	ADNOC	12-Apr	Travel restrictions due to COVID - Terminal restrictions due to security sensitivity of the area
742	Sabine Pass, USA	Rightship, Shell	25-May	Cancelled due to unsafe access - adjusted boarding measures (Covid-19 related)
743	Sabine Pass, USA	BP	28-May	
744	Saint Nicolas, France	CDI	20-May	Local inspector unavailable. (Covid-19 related)
745	Saldana Bay, South Africa	BHP, P66	04-Apr	other - complete lockdown due to COVID19
746	Salina Cruz, Mexico	Lukoil	16-Apr	Foreign Inspector travel ban
747	Salina Cruz, Mexico	P66	16-Apr	Foreign Inspector travel ban
748	Salvador, Brazil	ENOC	23-Apr	Planned - Due to COVID-19 I will not be able to attend you in Salvador as I am requiring flight from Rio De Janeiro. I can attend you in Rio De Janeiro or in São Sebastião therefore keep me posted when you have program to attend one of these two ports.
749	Salvador, Brazil	ENOC	01-May	Inspector is unable to attend at this call due to prior commitments.
750	Salvador, Brazil	ENOC	01-May	The inspector is unable to attend at this call due to prior commitments. Please advise us her next convenient port.
751	Salvador, Brazil	KOCH	43977	Terminal Change policy - access through terminal forbidden
752	San Lorenzo, Argentina	BHP	22-Jun	But sorry, not yet, the covid situation arrived later & is exploding here in Argentina in this & coming weeks, Measures are being strengthened and house confinement imposed (one of the longest worldwide) goes on, as well as borders remaining closed, internal flights curtailed, even road traffic permits limited, etc, etc, etc. As a result an inspection, even in Ramallo, where I usually travel by car to inspect, is not yet feasible.
753	San Lorenzo, Argentina	KOCH	22-Jun	But unfortunately, please note that as per the current Sanitary Situation and COVID-19, the country is under a mandatory quarantine, with a full closure of borders. In this way, it is not possible for an inspector to arrive and carry out this inspection.
754	Santos, Brazil			Imposed restrictions
755	Santos, Brazil	Koch, Petrobras	02-Apr	Local inspector unavailable.
756	Santos, Brazil	Phillips66	13-Apr	
757	Santos, Brazil	Shell, BHP	14-Apr	Shell - Not covering; BHP Not performing inspection.

758	Santos, Brazil	Petrobras	15-Apr	Petrobras - Not performing inspections until further, KOCH - No available local inspectors; travelling restrictions
759	Santos, Brazil	Shell	01-May	Not covering
760	Santos, Brazil	ENOC	02-May	
761	Santos, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
762	Sao Luis, Brazil	Idemitsu	18-Mar	
763	Sao Luis, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
764	São Sebastião, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
765	Sariaya, Philippines	BHP-Rightship, Equinor	24-Apr	Inspection cancelled.
766	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
767	Sendai, Japan	IMT	26-Apr	Local inspector unavailable. (Covid-19 related)
768	Sfax, Tunisia	ENOC / P66 / BHP	21-Jun	Others – due to COVID-19 travel restrictions
769	Shanghai, China	Shell	March	Inspection not allowed by Terminal due to COVID – 19
770	Shenzhen, PRC	ENI	24-Jun	We'd like inform you that due to the current travel restrictions and 14 days quarantine for anyone entering China, the inspector is not able to attend , therefore for the time being the inspection is postponed at more convenient time.
771	Shiudong, PRC	Lukoil	07-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
772	Shiudong, PRC		08-May	Inspector who is from abroad is not permitted to come for inspection. Chinese is permitted. If inspector is Chinese , he need to arrive Maoming for quarantine 3 days before on board, and go to hospital for Nucleic acid detection.Launch cost to the terminal will be around 18,000/-USD
773	Shuidong, PRC	BHP	28-May	Covid 19 - travel restrictions
774	Shuidong, PRC	Alma	29-May	Covid 19 - travel restrictions
775	Sierra Leone	Lukoil, Alma	29-Mar	
776	Sierra Leone & Conakry	Lukoil & Alma	29-Mar	Covid 19 - travel restrictions
777	Sikka India	IDEMITSU	12-May	Lockdown in India due to Covid 19 pandemic.
778	Sikka, India	CDI	30-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
779	Sikka, India		1-8 Apr	
780	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
781	Sikka, India	ENOC	04-Apr	Due to COVID 19 restrictions
782	Sines, Portugal			Imposed restrictions
783	Sines, Portugal	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be

				determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
784	Sines, Portugal	Lukoil, POT, Saras, Maxcom, Erg, Neste	20-Apr	No local Inspectors and Covid-19 travel restrictions
785	Sines, Portugal	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC	20-Apr	Lukoil, POT, Saras, Erg, Maxcom, Neste, ENOC - Local inspector unavailable. (Covid-19 related)
786	Sines, Portugal	Cepsa	01-May	Declined due to COVID-19 travel restrictions
787	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
788	Singapore	Enoc	21-Apr	Due to terminal restriction (Singapore Petrochemical Complex Olefin I)
789	Singapore	All Majors/CDI	10-Apr	Only essential services is possible and hence inspections cannot be scheduled till 7-May as per MPA regulations due to COVID-19 circuit breaker in place
790	Singapore	Idemitsu	19-May	Singapore Terminal Restricted for inspection due to COVID 19 pandemic
791	Singapore	Idemitsu	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
792	Singapore	Idemitsu	15-Jun	OM - regret to inform you that nominated Terminal (Vopak Penjaru) is not allowing any inspections/visitors due to ongoing COVID-19 restrictions.
793	Singapore	Total	10-Jun	OM - Unfortunately we have to decline on this occasion due to the unavailability of an inspector in the port where this vessel is presently calling.
794	Singapore, Shell Bukom	Gazprom	17-Apr	Terminal declined inspector's boarding at their terminal due to COVID 19
795	Singapore, Vopak Penjuru	Gazprom	15-Apr	Rejected due to terminal disapproved of any visitors or auditor during current Covid -19 situation
796	Sohar, Oman	Aramco	09-Jul	The Oman borders are closed and local inspector unavailable.
797	Sohar, Oman	CDI, Oiltanking Odfjell	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
798	Sohar, Oman	BHP, Equinor, Gazprom, Repsol, KOCH, ENI, P66,Lukoil, BP, Total, ENOC	30-Apr	Local inspector unavailable. (Covid-19 related)
799	Sohar, Oman	Shell, BP	10-May	Local inspector unavailable. (Covid-19 related)
800	Sohar, Oman	All Majors/CDI	15-May	All routes closed in Oman, foreigners cannot arrive to carry out inspection due to COVID-19
801	Sohar, Oman	Equinor	21-May	Due to travel restrictions imposed by the covid19 outbreak, there are no inspectors available to cover.

802	Sohar, Oman	ENOC, ADNOC, KOCH	21-May	Local inspectors not available; travelling restrictions
803	Sohar, Oman	Idemitsu	22-May	No available local inspectors; travelling restrictions
804	Sohar, Oman	Equinor, ENOC, ADNOC, Idemitsu, KOCH	29-May	Local inspector unavailable. (Covid-19 related)
805	South Africa ports		02-Apr	Heightened level of Security level protocols within the South African Port System during the lockdown period.
806	Southwold, UK	Chevron/Total/Equinor/Shell	25-May	Declined due to unavailability of inspectors
807	Southwold, UK	Lukoil	10-Jun	delay operations
808	Sri Racha, Thailand			Not permitted
809	Sri Racha, Thailand	Lukoil	30-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
810	St' Charles, Barbados	BHP	02-Apr	Last muete cancellation as terminal change policy - no visitor/inspector allowed due to COVID19
811	St Croix, US Virgin Islands		02-Apr	Not possible due to COVID-19 restrictions
812	St Croix, USA (Virgin Island)	TOTAL	20-Apr	Local inspector unavailable. (Covid-19 related)
813	St. Croix, US Virgin Island		22-Jun	Not allowed due to COVID restrictions
814	St. Eustatius		09-Jul	According to information received from local agents: commercial flights between St. Maarten and St. Eustatius remains banned. Also vetting inspectors are not allow to visit vessels at St. Eustatius until further notice.
815	St. Eustatius		14-Apr	Not possible due to COVID-19
816	St. James, LA USA	Maxcom	01-May	No local inspector available in Louisiana (covid-19 related) normal Texas based inspector to attend but not ready to serve quarantine period when return to Texas
817	Stenungsund, Sweden	CDI	17-Mar	Nominated Inspector declined due to COVID
818	Stignaes, Denmark			Imposed restrictions
819	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April. We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
820	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April. Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
821	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April. Thank you for your email. Please note we not have any local inspectors in Sweden.

822	Stockholm, Sweden	LUKOIL	06-Apr	E-mail from LUKOIL 4th of April: We regret to advise you that we are unable to arrange the vessel inspection during her forthcoming call at Stockholm.
823	Stockholm, Sweden	Equinor	07-Apr	E-mail from EQINOR 4th of April: Inspection cancelled, Unfortunately we have no inspector available in Sweden at this time.
824	Stockholm, Sweden	Shell	07-Apr	E-mail received from SHELL 06th of April: Please note we not have any local inspectors in Sweden.
825	Suape, Barzil	IMT/SHELL/CHEVRON	15-May	Due to COVID-19 travel restrictions
826	Suape, Brazil			Imposed restrictions
827	Suape, Brazil	ENOC	17-Apr	Due to COVID 19 travel restrictions we are unable to attend the vessel.
828	Suape, Brazil	IMT/SHELL/CHEVRON	15-May	Due to COVID-19 travel restrictions
829	Suape, Brazil	Petrobras	05-Jun	Petrobras will now carry out inspections at the following ports in Brazil subject to local inspector's availability.
830	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
831	Suez, Egypt	Agents	22-May	Covid 19 - travel restrictions
832	Suez, Egypt	Enoc	25-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
833	Suez, Egypt	IMT	29-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
834	Sumed, Egypt	Lukoil	10-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
835	Sumed, Egypt	Shell	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
836	Taicang	Lukoil		
837	Taicang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
838	Taicang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
839	Taicang, PRC	Maxcom, ALMA, BHP,Lukoil	14-Apr	Covid 19 - travel restrictions
840	Taicang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
841	Taicang, PRC	BP	09-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
842	Taicang, PRC	Idemitsu	29-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
843	Taicang, PRC	CDI	24-May	Terminal change policy - no visitor/inspector allowed due to Covid-19
844	Taicang, PRC	Idemitsu	24-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
845	Taicang, Taiwan	Petron, P66	05-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
846	Taichung, Taiwan	Chevron	07-Jul	Agent

847	Taichung, Taiwan	Koch, Shell, Total, Rightship, Adnoc	20-Apr	Local inspector unavailable. (Covid-19 related)
848	Taichung, Taiwan	BHP, Gazprom	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
849	Tainjin, PRC			
850	Taipei, Taiwan	CDI	27-Apr	Travel/border restrictions being imposed due to COVID-21
851	Taipei, Taiwan	CDI	18-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
852	Taixing, PRC		10-Apr	Terminal didn't allow
853	Taixing, PRC	CDI	11-Apr	Terminal rejected additional personnel to enter.
854	Taixing, PRC	Lukoil	01-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
855	Taixing, PRC	IMT,Chevron,Petron	01-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19.
856	Taizhuo, PRC	Lukoil	08-May	Covid 19 - travel restrictions
857	Taizhuo, PRC	Agent	07-May	Covid 19 - travel restrictions
858	Tallinn, Estonia	Lukoil	16-Apr	
859	Tallinn, Portugal	LUKOIL	16-Apr	
860	Tamatave, Madagascar (Toamasina)	Maxcom	16-Apr	Covid 19 - travel restrictions
861	Tamatave, Madagascar (Toamasina)	Lukoil,Total,BHP, ENOC,P66,Aethon,Koch, agents	14-Apr	Covid 19 - travel restrictions
862	Tangier MED, Morroco	ENOC	02-Apr	Travelling restrictions
863	Tangier, Morocco		07-Apr	Not allowed due to COVID-19 restrictions
864	Tangier, Morocco	IPLOM	09-Jun	Due to local restrictions imposed the permission to drive/travel to Port-Tangier
865	Tangshan	Gazprom	09-Jul	nobody allowed on board except customs officer and immigration/surveyor/agent.
866	Tanjung Pelepas, Malaysia	KOCH	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
867	Tanjung Pelepas, Malaysia	P66	04-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
868	Tanjung Bin, Malaysia	Koch	26-Mar	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
869	Tanjung Priok, FSRU Nusentara, Indonesia	BP	10-May	Travel restriction imposed in the country due to COVID 19.
870	Tarragona, Spain	REPSOL	05-Apr	Due to Covid-19 spread, REPSOL actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.

871	Tarragona, Spain	Equinor	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
872	Tarragona, Spain	Equinor	05-Jun	no European inspectors are available in Tarragona due to travel restrictions
873	Tarragona, Spain	SHELL	04-Jun	Due to the use of barge / launch boat
874	Tauranga, New Zealand	Shell, Idemitsu, BHPB	1-10 Apr	two local inspectors are in New Zealand, but domestic travel is restricted due to the lock down
875	Tauranga, New Zealand	Shell, Idemitsu, BHPB	10-Apr	Other (National Lockdown - Travel restriction)
876	Teesport, UK	Exxon	02-Apr	No available local inspectors; travelling restrictions
877	Tema, Ghana	CDI	19-Mar	Local inspector unavailable. (Covid-19 related)
878	Tema, Ghana	ENOC, KOCH	30-Apr	Local inspector unavailable. (Covid-19 related)
879	Tetney, UK	BP	16-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
880	Tetney, UK	EQUINOR	13-Apr	Local inspector unavailable.
881	Tetney, UK	BP	20-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
882	Thailand	All Majors/CDI	03-Jul	Foreign inspectors cannot travel to Thailand and will require to serve quarantine,
883	Thanh Hoa, Vietnam	PETROVIETNAM KOCH	16-Jun	We have only one local inspector and he will cover few inspections of other vessels from 14 to 20 June. So he will not be available to cover inspection of your vessel. Regret to inform you that we will not be able to arrange the subject vessel inspection, due to the Covid19, Vietnamese Government still not allow International flights up to now.
884	Thanh Hoa, Vietnam	PETROVIETNAM KOCH	16-Jun	We have only one local inspector and he will cover few inspections of other vessels from 14 to 20 June. So he will not be available to cover inspection of your vessel. Regret to inform you that we will not be able to arrange the subject vessel inspection, due to the Covid19, Vietnamese Government still not allow International flights up to now.
885	Thessaloniki, Greece	P66	07-May	Local inspector unavailable. (Covid-19 related)
886	Thessaloniki, Greece	Repsol	07-May	Kindly note that due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception. Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.

887	Tianjin, PRC	Repsol	23-Jul	Regret to say that there is no Inspector availability at Tianjin around 23 July
888	Tianjin, PRC	CDI	10-Apr	No inspection was not allowed by port authority
889	Tianjin, PRC	IMT, Chevron, Shell, Total	Feb	Inspection not allowed by Terminal due to COVID – 19
890	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
891	Tianjin, PRC	PETRONAS	07-Apr	Inspector is not allowed on board in Tianjin port due to COVID-19
892	Tianjin, PRC	Lukoil	28-Mar	Terminal change policy – no visitor/inspector allowed due to Covid-19.
893	Tianjin, PRC	Equinor, BHP, Gazprom, Lukoil, KOCH, Idemitsu	09-Feb	Inspector's not willing to go due to safety/health reasons + terminal change policy - no visitor/inspector allowed due to Covid-19.
894	Tianjin, PRC	CDI	11-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
895	Tokuyama, Japan	Equinor, Idemitsu	04-Jun	Regret inform you that we are unable to attend this vessel at Tokuyama. We regret to say we could not find the inspector able to attend your good vessel tomorrow. Sorry for causing your inconvenience.
896	Townsville, Australia	Chevron	March	Inspection not allowed by Terminal due to COVID – 19
897	Tramandai, Brazil	Lukoil	18-Apr	Due to the COVID-19 travel restrictions (Unavailability of Flights)
898	Tramandai, Brazil		24-Apr	Not allowed due to COVID-19 restrictions
899	Tramandai, Brazil	Lukoil	07-May	Covid 19 - travel restrictions
900	Tramandai, Brazil	PMI	04-May	Covid 19 - travel restrictions
901	Tramandai, Brazil	Koch	03-May	Covid 19 - travel restrictions
902	Tramandai, Brazil	Maxcom	02-May	Covid 19 - travel restrictions
903	Tranmere, UK	ENOC	04-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
904	Tuban, Indonesia	ENOC	05-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
905	Tuban, Indonesia	Rightship	07-Apr	Not possible due to border closures and quarantine requirements due to COVID-19
906	Tuban, Indonesia	Cocophillips	16-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
907	Tuban, Indonesia	Exxon, P66	16-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
908	Tuban, Indonesia	ENOC	12-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
909	Tuticorin, India	CDI	19-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
910	Tuxpan, Mexico	VIVO	31-Mar	
911	Tuxpan, Mexico			All ports east of Mexico. Do not allow inspectors onboard.

912	Tuxpan, Mexico			Do not allow inspectors onboard.
913	Tuxpan, Mexico	Shell	25-Jun	OM- We regret we are unable to carry out the inspection at this time. We do not currently cover this Country due to COVID-19 restrictions. Please request again at a later date at a different port.
914	Ulsan, SK	NESTEOIL	22-May	(Planned) - Neste not performing any inspections due to the COVID 19 situation.
915	Ulsan, SK	IMT,SHELL	10-Apr	Travel restriction
916	Ulsan, SK	All Majors/CDI	15-May	SK Energy terminal in Ulsan do not permit any inspections to be carried out during cargo operations. Option provided is to carry out the inspection at anchorage which will be an idle inspection and not serve the purpose.
917	Ust Lega,Russia	EXXON	07-Apr	Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels. We will maintain our pragmatic approach in evaluating TC vessels and SIRE inspections reports will be reviewed on a case by case basis accordingly
918	Ust Lega,Russia	EXXON	07-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
919	Vadinar, India			
920	Vadinar, India	Maxcom	09-Apr	Covid 19 - travel restrictions
921	Vadinar, India	BHP	06-Apr	Covid 19 - travel restrictions
922	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
923	Vadinar, India	ENOC	01-May	Covid 19 - travel restrictions
924	Vadinar, India	BIECO	04-May	Covid 19 - travel restrictions
925	Valencia, Spain	BHP	29-May	OM - Unfortunately do not have available inspectors and will decline inspection due to current health/virus/quarantine /travel problems , no flights etc..
926	Valencia, Spain	P66	29-May	OM - Unable to schedule the inspection due to the conflict that the Suggested date is within 30 days of an already planned SIRE/OVID inspection with another member.
927	Vatso, Italy	CDI	March	Inspection not allowed by Terminal due to COVID – 19
928	VeraCruz, Mexico			All ports east of Mexico. Do not allow inspectors onboard.
929	VeraCruz, Mexico			Do not allow inspectors onboard.
930	Veracruz, Mexico	Agents	14-Apr	Covid 19 - travel restrictions
931	Veracruz/Altamira, Mexici	CDI	14-Apr	Covid 19 - travel restrictions
932	Vietnam OPL	P66 / PTT	14-Jun	Others – due to COVID-19 travel restrictions
933	Virgin Islands, USA	All Majors/CDI	10-Apr	All ports in USVI is locked down due to COVID-19 and no inspections can be arranged
934	Vizag, India	Koch	08-Apr	Other (National Lockdown - Travel restriction)
935	Vizag, India	CDI	15-Apr	India lockdown due to COVID
936	Vizag, India	Koch	10-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
937	Vizag, India	Equinor	20-May	Due to several restrictions imposed by the covid-19 outbreak on this given location, the inspector will not be able to attend.

938	Vizag, India	Koch	06-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
939	Vizag, India	SIRE	23-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
940	Vungtau, Vietnam	All Majors/CDI	17-Apr	Terminal does not permit inspections due to COVID-19
941	Vungtau, Vietnam	NESTEOIL	02-May	At this moment Neste does not carry out sire inspection
942	Vungtau, Vietnam	P66	02-May	Travel/border restrictions being imposed due to COVID-20
943	Walvis Bay, Namibia		April	Namibian authorities suspended Visa issue for 1 month thus NO inspector available
944	Walvis Bay, Namibia	BHP	06-Apr	Lockdown in that area and restricted movement by air, road or rail Not be possible to inspect the subject vessel.
945	Walvis Bay, Namibia	BHP	06-Apr	Local inspector unavailable.
946	Wenzhou, PRC		10-Apr	Terminal didn't allowed
947	Whiffenhead, Canada	BP	16-Apr	Foreign Inspector travel ban
948	Whitegate	Irving Oil	30-Jun	•Rejected for business based on SIRE more that 6 months old / no physical SIRE could be completed prior to last SIRE expiring 6mnts/12mnts.;
949	Wilhelmshaven, Germany			Imposed restrictions
950	Wilhelmshaven, Germany	BP	29-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
951	Yabucaco, Puerto Rico	ENOC/BHP/Lukoil/Equinor	03-Apr	Not possible due to COVID-19 Restrictions
952	Yanbu, Saudi Arabia	ADNOC	28-Apr	Travel restrictions - Lockdown
953	Yanbu, Saudi	Enoc	18-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
954	Yanbu, Saudi	Shell	23-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
955	Yanbu, Saudi Arabia	CDI, Koch, Shell	12-Apr	Other (National Lockdown - Travel restriction)
956	Yanbu, Saudi Arabia	CDI	11-Apr	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
957	Yanbu, Saudi Arabia	CDI / Gas	26-May	No available local inspectors; travelling restrictions
958	Yanbu, Saudi Arabia	CDI	01-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
959	Yanbu, Saudia Arabia	Koch	29-Apr	Foreign Inspector Travel Ban (Covid-19), Local Inspector unavailable
960	Yangpu, PRC	Idemitsu	12-Apr	No inspection was not allowed at the terminal
961	Yangpu, PRC	Idemitsu	12-Apr	Terminal change policy - no visitor/inspector allowed due to Covid-19
962	Yangpu, PRC	CDI	17-May	Terminal change policy - no visitor/inspector allowed due to Covid-19

963	Yangpu, PRC	SIRE	25-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
964	Yangshan, PRC	MMS	16-May	Present stage, visitor is not allowed in Yangshan LNG terminal.
965	Yantai, PRC	Chevron, Shell, Koch,	Feb	Inspection not allowed by Terminal due to COVID – 19
966	Yantai, PRC	Lukoil, P66	21-Feb	Local inspector unavailable. (Covid-19 related)
967	Yantai, PRC	CDI	21-Feb	Local inspector unavailable. (Covid-19 related)
968	Yeosu, S Korea	Equinor	09-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19
969	Yeosu, SK		05-Jan	Terminal policy- no visitor/inspector allowed due to Covid-19
970	Yeosu, SK	Lukoil	29-Jun	Agent and LUKOIL QUOTE: the regulation was changed from today (29th June) Sapo no.1 Terminal, Yeosu prohibited any inspection during berthing due to COVID19. UNQUOTE
971	Yeosu,SK		25-Mar	Due to COVID-19 not permitted by terminal
972	Yeosu,SK	EXXON	08-Apr	Others - Due to the ongoing concerns associated with COVID-19, IMT will not be arranging inspections on TC vessels.
973	Yingkou, PRC	NA	17-May	The following restrictions applies: 1. Inspector should hold Two times (24 interval) nucleic acid testing before onboard date. (Send agent the test reports and other required documents in advance) a. Test can be done at local hospital, 1st test to be done 7 days prior to attendance. 2. 14 days isolation in Yingkou hotel arranged by local port authorities after departure from vessel 3. Other documents will inform him directly if confirmed. 4. Inspectors will most preferably not from the high risk area. (HUBEI, JILIN, HEILONGJIANG province)
974	Yingkou	Total	06-Jul	
975	Yingkou	Lukoil	25-Jun	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
976	Yingkou, PRC	Shell, BIECO, Idemitsui	16-17- Jun	No visitor/inspector allowed due to Covid-19.
977	Yingkou, PRC	GAZPROM	01-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
978	Yizheng, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
979	Yokkaichi, Japan	Shell	15-Jun	Launch service required
980	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
981	Yosu, SK	GS Caltex terminal	08-May	GS Caltex terminal at Yosu does not permit inspections to be carried out when vessel alongside the terminal.
982	Yumurtalik, Turkey	CDI	29-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

983	Yung An, Taiwan			
984	Yung An, Taiwan	Chevron	02-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
985	Yung An, Taiwan	KOCH	01-Apr	Due to COVID 19 there is travel restrictions which makes it impossible for oversea inspectors to travel and no local inspector at Taiwan
986	Yung An, Taiwan	GAZPROM	15-Apr	Local inspector unavailable.
987	Yung An, Taiwan	BP	14-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19
988	Zeebrugge, Belgium	REPSOL	14-Apr	Other - Due to health risks associated to Covid-19 spread all over the world, REPSOL has decided to perform following actions: 1.- Apart from a very few exceptions which will be determined case by case. Repsol will not inspect any vessel. Your vessel is not an exception 2.- Vessels without a “fresh” SIRE or REPSOL required Inspection will be evaluated case by case based on all available information. These actions will remain in force from now until Sanitary alert by Covid-19 will cease.
989	Zeebrugge, Belgium	PREEM	05-May	Inspector refused to follow precautions stipulated by the Company SMS.
990	Zhangjiagang, PRC	Idemitsu	15-Jul	Zhangjiagang port is not allowed for any inspection.
991	Zhangjiagang, PRC	Maxcom	16-Apr	Covid 19 - travel restrictions
992	Zhangjiagang, PRC	Maxcom ALMA, BHP, LukOil,	14-Apr	Covid 19 - travel restrictions
993	Zhangjiagang, PRC	Agents	13-Apr	Covid 19 - travel restrictions
994	Zhangjiagang, PRC	Idemitsu	21-Apr	Covid 19 - travel restrictions
995	Zhangjiagang, PRC	ALMA PETROLI SPA	25-29 May	China Terminal Restricted - no inspection is allowed due to Covid-19.
996	Zhangjiang, PRC	BP	18-Feb	As per BP's message they stated due to terminal restrictions but found out inspector did not want to use launch boat as we managed to book inspection with another oil major
997	Zhapu, PRC	BP	11-May	Terminal change policy – no visitor/inspector allowed due to Covid-19.
998	Zhapu, PRC	Lukoil, BHP Rightship	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
999	Zhapu, PRC	Petron/Chevron	09-Jun	Terminal change policy – no visitor/inspector allowed due to Covid-19.
1000	Zhoushan, PRC	Shell	02-Apr	Terminal's policy – not allow Sire inspector to board the vessel due to Covid -19
1001	Zhoushan, PRC	ENOC	13-Apr	Terminal restrictions
1002	Zhoushan, PRC		21-Apr	Terminal change policy – no visitor/inspector allowed due to Covid-19.
1003	Zhoushan, PRC	SHELL	21-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19

1004	Zhoushan, PRC	SHELL	28-May	Foreign Inspector travel ban / Inspector need to serve quarantine period due to Covid-19
1005	Zhoushan, PRC		26-Jun	Terminal policy- no visitor/inspector allowed due to Covid-19
1006	Zoushan	Lukoil	08-Jul	Terminal change policy – no visitor/inspector allowed due to Covid-19.
1007	Zhoushan, PRC		08-May	Terminal restriction for sire inspection is in place.
1008	Zhoushan,PRC	EQUINOR	14-May	Terminal policy- no visitor/inspector allowed due to Covid-19
1009		BASF	Apr	Rejected for business based on CDI more that 12 months old / no physical CDI could be completed prior to last CDI expiring 12mnths.